

MECCANO

(TRADE MARKS 296321, 12633, 10274, 55/13476, 884/25, 2913)

INSTRUCTIONS

FOR OUTFITS Nos. 00 to 3

2/-


Copyright by MECCANO LIMITED, LIVERPOOL, throughout the world

No. 28A

OVERSEAS EDITION

MECCANO

THE TOY THAT MADE ENGINEERING FAMOUS



The Meccano system consists of accurately made and highly finished engineering parts with which almost every mechanical movement known may be reproduced in model form. More can be accomplished with Meccano than with any other constructional toy, for no other system has such possibilities. The genius is in the parts and the youngest boy can commence to build models as soon as he gets his Outfit home. A screwdriver, provided in the Outfit, is the only tool necessary.

When you have built all the models shown in this book you will want to build others of a more advanced type, and you cannot do better than purchase a copy of the No. 4-7 Manual from your dealer. This Manual contains illustrations of a fine selection of models, a large number of which you will be able to build by adding a few extra parts to your equipment.

There is practically no limit to the number of models that can be built with Meccano. The most wonderful feature about the system is that it is *real engineering*; it is fascinating and delightful and it gives you a satisfaction beyond anything that you have ever previously experienced.

IF IN DOUBT WRITE TO MECCANO LIMITED

The service of Meccano does not end with selling an Outfit and an Instruction Manual. When you want to know something more about engineering than is now shown in our books, or when you strike a rough problem of any kind, write to us. We receive over 200 letters from boys every day all the year round. Some write to us because they are in difficulty, others because they want advice on their work or pleasures, or about their choice of a career. Others, again, write to us just because they like to do so and we are glad to know that they regard us as their friends.

Although all kinds of queries are put to us on all manner of subjects, the main interest is, of course, engineering. No one has such a wonderful knowledge of engineering matters as that possessed by our staff of experts. This vast store of knowledge, gained only by many years of hard-earned experience, is at your service. *We want the Meccano boy of to-day to be the famous engineer of to-morrow.*

HOW TO BUILD WITH MECCANO

Make the simple models first—there is loads of fun in them—and then try to improve them. Every model can be made in a dozen different ways. It is important to screw up all the nuts and bolts tightly to ensure that your models will be strong and firm when they are completed. When you want to add more parts to your Outfit so that you can build bigger models, you can always get them from your dealer.

Each Outfit may be converted into the one next higher by the purchase of an Accessory Outfit. Thus, a No. 2 may be converted into a No. 3 by adding to it a No. 2A. A No. 3A would then convert it into a No. 4 and so on. In this way, no matter with which Outfit you commence you may by degrees build it up until you have the largest Outfit.

■ All models shown in this Manual are numbered and for reference purposes each model number is preceded by the number of the Outfit with which it may be built. Thus, for example, model No. 00.60 may be built with No. 00 Outfit, and model No. 2.20 with No. 2 Outfit.



THE "MECCANO MAGAZINE"

The *Meccano Magazine* is the Meccano boy's newspaper. It tells him of the latest Meccano models; what Meccano Clubs are doing; how to correspond with other Meccano boys; the Competitions that are running, etc. It contains interesting articles on engineering and electrical subjects, and deals with many other topics of interest to boys, including suggestions from Meccano boys for new Meccano parts and correspondence columns in which the Editor replies to his readers' enquiries. Write to the Editor, *Meccano Magazine*, Binns Road, Liverpool, giving the names and addresses of three of your chums who are not Meccano boys and enclosing 6d. in stamps. He will then forward a specimen copy of the "M.M." post free. It is sent regularly to subscribers at the rate of 4/- for six issues, post free, or it may be ordered from any Meccano dealer, newsagent or bookstall, price 6d. per copy.



MECCANO STANDARD MECHANISMS


There are a number of Meccano movements that have to a certain extent become standardised, that is to say they may be applied to more than one model, in most cases without any alteration, but in some few instances with only slight alterations to the original movement. These have been collected and classified, and may be obtained in the form of a Manual entitled "Meccano Standard Mechanisms." It will be observed that many of these Standard Mechanisms are referred to in the instructions for building the more intricate models in this book.

You may obtain a copy of the "Standard Mechanisms" Manual from your dealer, price 1/6, or direct from Meccano Ltd., Binns Road, Liverpool, price 1/7½ post free.



IMPROVED MECCANO PARTS

A number of models included in this Manual show the new style 5½" x 2½" Flanged Plate (with flanges at the ends as well as the sides) and improved Sector Plate (with two additional rows of holes), but it should be noted that, although the new parts are more adaptable, the old-style plates may still be used in their place if desired. When it is required to journal an Axle Rod in a slot in the new Flanged Plates, an ordinary Strip should first be bolted to the Plate so that one of its holes forms an additional bearing for the Rod.




Standard Mechanisms
No. 262

SIMPLE MECCANO PIVOTS

In building Meccano models it is frequently required to attach two parts together so that one or both are quite free to swivel. A very simple way to do this is shown under detail number 262 in the Meccano Standard Mechanisms Manual, and for the benefit of those readers who are unable to consult the special Manual, we have reproduced this detail. As will be seen, it consists of a simple type of pivot or swivel bearing formed by a bolt and two nuts. The bolt is secured rigidly to a Strip or Plate, etc., by means of the nuts, which are secured tightly against opposite sides of the Strip, sufficient space being left beneath the head of the bolt to permit another Strip to turn freely about its shank.

A somewhat similar form of swivel-joint, also widely used, consists of a bolt and lock-nuts (Standard Mechanisms No. 263). The two Strips to be connected pivotally are placed on the bolt and held in position by two nuts locked together on the shank. The Strips must be allowed a certain amount of play so that they can pivot independently about the bolt. These pivoting devices will be found equally valuable in the simplest and the most elaborate models.



Particulars and Prices of Meccano Parts

[illegible]

Meccano Accessory Parts will be supplied in colours unless nickelled parts are specially ordered.

*IMPORTANT—These parts are available with nickel finish only.

No.						s. d.
89.	5½" Curved Strips,	10" radius	...	each	0	3
89a.	3½" Curved Strips,	cranked,	1½" radius, 4 to circle	"	0	3
90.	2½" "	"	2½" radius	"	0	2
90a.	2½" "	"	cranked, 1½" radius, 4 to circle	"	0	2
94.	Sprocket Chain	...	per 40" length	0	8	
*95a.	Sprocket Wheels,	2" diam.	...	each	0	7
*95b.	"	1½" "	...	"	0	6
*96.	"	1" "	...	"	0	5
*96a.	"	¾" "	...	"	0	4
97.	Braced Girders,	3½" long	...	½ doz.	1	3
97a.	"	3" "	...	"	1	0
98.	"	2½" "	...	"	1	0
99.	"	12½" "	...	"	3	9
99a.	"	9½" "	...	"	2	10
99b.	"	7½" "	...	"	2	10
100.	"	4½" "	...	"	1	6
100a.	"	5½" "	...	"	1	3
101.	Heads, for looms	doz.	1	0
102.	Single Bent Strips	each	0	2
103.	Flat Girders, 5½" long	½ doz.	1	2
103a.	"	9½" "	...	"	1	8
103b.	"	12½" "	...	"	1	9
103c.	"	4½" "	...	"	1	0
103d.	"	3½" "	...	"	0	10
103e.	"	3" "	...	"	0	8
103f.	"	2½" "	...	"	0	7
103g.	"	2" "	...	"	0	6
103h.	"	1½" "	...	"	0	6
103k.	"	7½" "	...	"	1	5
*104.	Shuttles, for looms	each	10	9
105.	Reed Hooks, for looms	"	0	6
106.	Wood Rollers	"	2	2
106a.	Sand Rollers	"	2	6
107.	Tables for Designing Machines	"	2	2
108.	Architraves	"	0	3
109.	Face Plates, 2½" diam.	"	0	6
110.	Rack Strips, 3½" "	"	0	3
111.	Bolts, ½" "	each	0	1
111a.	"	3 for	0	2
111c.	"	doz.	0	4
113.	Girder Frames	each	0	5
*114.	Hinges	per pair	0	6
*115.	Threaded Pins	each	0	3
*116.	Fork Pieces, Large	"	0	5
*116a.	" Small	"	0	5
117.	Steel Balls, ½" diam.	doz.	0	9
118.	Hub Discs, 5½" "	each	1	9
119.	Channel Segments (8 to circle, 11½" diam.)	"	0	6
120.	Buffers	"	0	3
120a.	Spring Buffers	per pair	1	0
120b.	Compression Springs	each	0	2
121.	Train Couplings	"	0	3
122.	Miniature Loaded Sacks	"	0	3
*123.	Cone Pulleys	"	0	9
*124.	Reversed Angle Brackets, 1" "	½ doz.	1	6
125.	"	"	0	4
126.	Trunnions	each	0	3

No.		s. d.
126a.	Flat Trunnions	each 0 2
127.	Simple Bell Cranks	0 2
128.	Boss Bell Cranks	0 5
*129.	Rack Segments, 3" diam.	0 7
*130.	Triple Throw Eccentrics	1 5
131.	Dredger Buckets	$\frac{1}{2}$ doz. 2 9
132.	Flywheels, 2 $\frac{1}{2}$ " diam.	each 1 5
*133.	Corner Brackets	0 2
*134.	Crank Shafts, 1" stroke	0 3
135.	Theodolite Protractors	0 3
136.	Handrail Supports	0 5
137.	Wheel Flanges	0 5
138.	Ship's Funnels	0 5
138a.	" Cunard type	1 2
139.	Flanged Brackets (right)	0 3
139a.	" (left)	0 3
140.	Universal Couplings	1 2
141.	Wire Lines (for suspending clock weights)	1 0
142.	Rubber Rings, 3" rim	0 5
142a.	Dunlop Tyre to fit 2" diam. rim... ..	0 6
142b.	" 3"	0 9
143.	Circular Girders, 5 $\frac{1}{2}$ " diam.	1 5
144.	Dog Clutches	0 9
145.	Circular Strips, 7" diam. over all	1 1
146.	" Plates, 6"	1 5
*147.	Pawls, with pivot bolt and nuts	0 5
*147a.	Pawls	0 3
*147b.	Pivot Bolt with 2 nuts	0 3
148.	Ratchet Wheels	0 9
149.	Collecting Shoes, for Electric Locos	2 3
150.	Crane Grabs... ..	0 10
151.	Pulley Blocks, Single Sheave	1 0
152.	" Two	1 2
153.	" Three	1 5
*154.	Corner Angle Brackets, $\frac{1}{2}$ ", right hand	$\frac{1}{2}$ doz. 0 8
*154b.	Corner Angle Brackets, $\frac{1}{2}$ " left hand	0 8
155.	Rubber Rings, $\frac{1}{2}$ "	each 0 2
*156.	Pointers, 2 $\frac{1}{2}$ " over all, with boss... ..	0 6
157.	Fans, 2" diam.	0 6
158a.	Signal Arms, Home	0 8
158b.	" Distant	0 8
*159.	Circular Saws	1 5
160.	Channel Bearings, $1\frac{1}{2}$ " \times 1" \times $\frac{1}{2}$ "	0 3
162.	Boiler, complete with ends	1 5
162a.	Boiler ends	0 5
163.	Sleeve Pieces	pair 0 8
164.	Chimney Adaptors	each 0 3
165.	Swivel Bearings	0 9
166.	End	0 5
167.	Geared Roller Bearings	28 6
167a.	Roller Races, geared, 192 teeth	6 6
167b.	Ring Frames for Rollers	4 3
167c.	Pinions for Roller Bearings, 16 teeth	1 5
168.	Ball Bearings, 4" diam.	4 3
168a.	Ball Races, flanged	0 9
168b.	" geared	1 1
168c.	Ball Casings, complete with balls	2 6
169.	Digger Buckets	3 0
*170.	Eccentrics, $\frac{1}{2}$ " throw	1 1

*IMPORTANT.—These parts are available with nickel finish only.

PLATES


76, 109, 53, 146, 77, 61, 54, 52, 72

RODS, CRANKS AND COUPLINGS

134, 64, 166, 121, 116A, 144, 165, 130, 19S, 17, 170, 63, 63A, 140, 63B, 63C, 136, 128, 62, 80A, 62B, 127, 116

MISCELLANEOUS

151, 152, 153, 138, 162, 138A, 66&67, 142A, 41, 106, 169, 43, 157, 156, 149, 106A, 164, 131, 142, 35, 59, 104, 159, 57A, 101, 120, 120A, 158A, 65, 115, 163, 34B, 150, 34, 50A, 114



WHAT THE GUILD MEANS

THE Meccano Guild is an organisation for boys, started at the request of boys, and conducted as far as possible by boys. In joining the Guild a Meccano boy becomes a member of a great brotherhood of world-wide extent, every member of which has promised to observe its three great objects:—

- (1) *To make every boy's life brighter and happier.*
- (2) *To foster clean-mindedness, truthfulness, ambition, and initiative in boys.*
- (3) *To encourage boys in the pursuit of their studies and hobbies, and especially in the development of their knowledge of mechanical and engineering principles.*

HOW TO BECOME A MEMBER

MEMBERSHIP of the Guild is open to every boy possessing a Meccano Outfit, or Hornby Train Set, who satisfactorily fills in the prescribed application form. The only conditions are that members promise to observe the objects of the Guild and to wear their badges on all possible occasions.

The price of the Guild membership badge is 7d. post free in the United Kingdom, but members abroad will be required to pay 5d. extra for registered postage. A remittance for the necessary amount should be sent along with the form of application. The Guild badge is beautifully enamelled in blue and white and is made for wearing in the lapel of the coat.

MECCANO CLUBS

MECCANO CLUBS are founded and established under the guidance of the Guild Secretary at Headquarters and at the present time there are active Clubs in over one hundred towns and villages in the United Kingdom and in many countries Overseas. Each Club has its Leader, Secretary, Treasurer, and other officials all of whom, with the exception of the Leader, are boys. Write for information how to form a club, if there is no club near you.

Special awards are given to Club members for good work in connection with their Club and medallions are awarded in connection with the Recruiting Campaign, full particulars of which will be sent on request.



BADGE OF
MEMBERSHIP



GUILD
LEADER'S
BADGE



MECCANO GUILD
MEMBER'S CERTIFICATE




RECRUITING MEDALLION



SPECIAL MERIT MEDALLION

These Models can be built with MECCANO Outfit No. 00

Model No. 00.1 Table




Model No. 00.2 Dividers




Model No. 00.3 Bench




Model No. 00.4 Clothes Hanger




Model No. 00.5 Carpenter's Square




Model No. 00.7 Shipyard Bogie



Model No. 00.8 Meat Saw




Model No. 00.6 Desk




Model No. 00.15 Rifle with Bayonet




Model No. 00.9 Hand Cart




Model No. 00.10 Fire-Axe




Model No. 00.11 Velocipede



Model No. 00.12 Ladder




Model No. 00.13 Trowel




Model No. 00.16 Plough





Model No. 00.17 Sled



Model No. 00.18 Barrow




Model No. 00.19 Flat Truck

Model No. 00.20
Collapsible
Table

The $2\frac{1}{2} \times 1$ " Double Angle Strips 1 are attached to the $5\frac{1}{2} \times 2\frac{1}{2}$ " Flanged Plate 2 by lock-nutted bolts, as in Standard Mechanism No. 263. The Bolts 3 are secured to the $5\frac{1}{2}$ " Strip 4 and their shanks engage with the centre holes in the $2\frac{1}{2} \times 1$ " Double Angle Strips 1, thus maintaining the legs 5 in an upright position. When it is desired to fold up the legs 5, it is only necessary to raise the ends of the Strip 4, thus freeing the Double Angle Strips 1. The table is shown in the folded position in Fig. 00.20A.

Model No. 00.21 Trolley

Model No.
00.22
SpadeModel No.
00.23
Cement
Marker

Model No. 00.26 Motor Boat








Model No.
00.27
Plasterer's
HawkModel No. 00.28
ChuteModel No. 00.24
Lewis GunModel No.
00.25
Potato
ChopperModel No. 00.29
Spinning Top

FIG. 00.20A



Model No. 00.31 Switch

Model No. 00.30
Mason's TrowelModel No. 00.32
Baggage Cart

These Models can be built with MECCANO Outfit No. 00

Model No. 00.33
Friction Grip Tongs



Model No. 00.34 Tweezers



Model No. 00.35 Ceiling Fan



Model No. 00.36
Telegraph Pole




Model No. 00.37
Tin Opener




Model No. 00.38
Pen Rack




Model No.
00.39
Dividers



Model No. 00.40
Glider



Model No. 00.41
Crib




Model No. 00.43 Book End




Model No. 00.42
Telegraph Key




Model No. 00.48
Anchor



Model No. 00.45
Refreshment Wagon




Model No. 00.46
Buffers



Model No. 00.47
Piano Stool



Model No.
00.44
Sword




These Models can be built with MECCANO Outfit No. 00


9



Model No.
00.49
Clothes
Horse




Model No.
00.51
Scrap
Reel




Model No. 00.53
Bed

Model No.
00.55
Step
Ladder



Model No. 00.50
Rake



Model No. 00.52 Rake

Model No. 00.54
Track Gauge




Model No. 00.59
Gravel Sifter



Model No.
00.56
Mail Bag
Hanger



Model No. 00.57
Timber Wagon




Model No. 00.58
Cheese Cutter




Model No. 00.61
Umbrella Stand




Model No. 00.62
Cutlery Rest




Model No.
00.63
Birdcage
and
Stand



Model No. 00.64
Hand Car




Model No. 00.60 Trolley



10


These Models can be built with MECCANO Outfit No. 00

Model No. 00.66 Roulette Wheel




Cut out a circular piece of cardboard, and mark as shown to form scoring board. This is clamped between two 1" pulley wheels. The pointer revolves freely on the upright spindle and is held in position by another 1" pulley wheel.


Model No. 00.72 Pulley Shafting



Model No. 00.73 Furrow Roller




Model No. 00.77 Two-Hand Saw




Model No. 00.67

Coat Hanger



Model No. 00.68 Roman Balance




Model No. 00.74 Grill


Model No. 00.75 Hoe



Model No. 00.78 Planing Bench



Model No. 00.65 Axe




Model No. 00.70 Horse




Model No. 00.69 Fork



Model No. 00.71 Timber Truck




Model No. 00.76 Bogie Truck






Model No. 00.79

**Baggage
Truck**




Model No. 00.80 Table

Model No. 00.81 Timber Truck




Model No. 00.82


**Clothes
Drying Frame**

Model No.
00.83

**Pulley
Shafting**

Model No. 00.85
Toy HorseModel No.
00.86


**Mail Bag
Hanger**

Model No.
00.84


**French
Railway
Signal**

These Models can be built with MECCANO Outfit No. 00


Model No. 00.87 Buffing Spindle




Model No. 00.88
Ski-Runner




Model No. 00.89 Cutlery Basket




Model No. 00.92
Band Saw




Model No. 00.90
Trip Hammer




Model No. 00.91 Devil Wall




Model No. 00.93 Sled




Model No. 00.94
Garden Hose Reel






Model No. 00.95
Level Crossing
Barrier





Model No. 00.96
Ladder on
Wheels




Model No. 00.97
Bath Chair

Model No. 00.98
Well Driller




Model No. 00.99
Bed Table


Model No. 00.100
Ore Crusher




Model No. 00.101
Tea Wagon



Model No. 00.102
Blacksmith




Model No. 00.103 Porter's Trolley




Model No. 00.104
Watch Stand



Model No. 00.105 Hand Truck




Model No. 00.106
Meccano Man




Model No. 00.107
Battle Axe




Model No. 00.110
Towel Horse



Model No. 00.108
Print Trimmer



Model No. 00.109
Lever of the
First Order



These Models can be built with MECCANO Outfit No. 00

15

Model No. 00.111
Garden Seat

Model No. 00.112
Elevator Car

Model No. 00.113 Turnstile

Model No.
00.114
Sawing Horse

Model No. 00.116
Windmill


Model No. 00.115
Pen Rack

HOW TO CONTINUE

This completes our examples of models that may be made with MECCANO Outfit No. 00. The next Models are a little more advanced, requiring a number of extra parts to construct them. The necessary parts are all contained in a No. 00A Accessory Outfit, the price of which will be found in the list at the end of this Manual.

These Models can be built with MECCANO Outfit No. 0 (or No. 00 and No. 00A)

Model No. 0.1 Trolley




Parts required:

2 of No. 2	8 of No. 37
2 " " 16	2 " " 48A
4 " " 22	1 " " 52
4 of No. 90A	


Model No. 0.2 Luggage Truck

Parts required:

4 of No. 2
4 " " 5
2 " " 16
4 " " 22
16 " " 37
1 " " 52
4 " " 90A




Model No. 0.3 Swing



Parts required:

4 of No. 2
7 " " 5
2 " " 10
4 " " 12
21 " " 37
1 " " 40
2 " " 48A
1 " " 52
2 " " 90A
2 " " 126

Model No. 0.5 Lathe



Parts required:

1 of No. 2	2 of No. 22
4 " " 5	1 " " 24
2 " " 11	3 " " 35
7 " " 12	16 " " 37
1 " " 17	1 " " 52
1 " " 19s	2 " " 126
2 of No. 126A	

Model No. 0.4 Hat Rack




Parts required:

2 of No. 2
4 " " 5
2 " " 11
5 " " 12
1 " " 17
1 " " 22
22 " " 37
2 " " 48A
4 " " 90A
2 " " 126A

Model No. 0.6 Plough

Parts required:


2 of No. 2	1 of No. 17
1 " " 5	1 " " 22
2 " " 10	15 " " 37
2 " " 11	1 " " 44
3 " " 12	1 " " 48A
4 of No. 90A	



These Models can be built with MECCANO Outfit No. 0 (or No. 00 and No. 00A)

17


Model No. 0.7 Arch



Parts
required :

4 of No.	2
2 " "	11
6 " "	12
19 " "	37
1 " "	52
4 " "	90A


Model No. 0.8 Horizontal Engine



Parts
required :

2 of No.	2	4 of No.	22	1 of No.	52
6 " "	5	1 " "	24	4 " "	90A
2 " "	10	3 " "	35	2 " "	126
1 " "	12	21 " "	37	2 " "	126A
2 " "	16	1 " "	48A		
1 " "	19s				

Model No. 0.9 Notice Board




Parts
required :

10 of No.	37
1 " "	52
3 " "	90A
2 " "	126A


Model No. 0.10 Tea Wagon

Parts required :

8 of No.	5	10 of No.	37
2 " "	16	1 " "	52
4 " "	22	4 " "	90A



Model No. 0.11 Sulkey



Parts required :

2 of No.	2	1 of No.	48A
2 " "	22	4 " "	90A
10 " "	37	2 " "	125


Model No. 0.12 Drafting Table

Parts required :

4 of No.	5	1 of No.	52
12 " "	37	4 " "	90A
1 " "	48A	2 " "	126A



Model No. 0.13 Well Windlass



Parts required:

6 of No.	5
4 " "	12
1 " "	19s
2 " "	22
1 " "	24
12 " "	37
1 " "	40
1 " "	57
4 " "	90A


Model No. 0.14 Pulley Block



Parts required:

4 of No.	2	1 of No.	22	1 of No.	52
2 " "	5	1 " "	23	1 " "	57
2 " "	11	1 " "	24	2 " "	90A
1 " "	17	5 " "	35	2 " "	126
1 " "	19s	20 " "	37	2 " "	126A

Model No. 0.15 Derricking Crane



Parts required:


4 of No.	2	1 of No.	52
5 " "	5	1 " "	57
1 " "	10	2 " "	125
2 " "	11	2 " "	126
1 " "	16		
1 " "	17		
1 " "	19s		
3 " "	22		
1 " "	23		
2 " "	35		
22 " "	37		
2 " "	48A		

The base of the jib is pivoted to the Flanged Plate by means of a bolt and lock-nuts.

Model No. 0.16 See-Saw

Parts required:


4 of No.	2	1 of No.	52
1 " "	16	4 " "	90A
2 " "	22	2 " "	126
12 " "	37		
1 " "	48A		




Model No. 0.17 Rock Drill

Parts required:

1 of No.	11	4 of No.	22	2 of No.	48A
2 " "	16	1 " "	24	1 " "	52
1 " "	17	2 " "	35	2 " "	125
1 " "	19s	5 " "	37		



Model No. 0.18 Drilling Machine


Parts required:

3	of No.	2
4	" "	5
2	" "	11
3	" "	12
1	" "	16
1	" "	17
1	" "	19s
4	" "	22
1	" "	24
6	" "	35
22	" "	37
2	" "	48A
1	" "	52
1	" "	125
2	" "	126A

Model No. 0.19 Scales**Model No. 0.20 Cot**


Parts required:

4	of No.	2	4	of No.	22
7	" "	5	18	" "	37
3	" "	12	2	" "	48A
			1	of No.	52

**Model No. 0.21 Counter Scales**

Parts required:

1	of No.	2	7	of No.	37
2	" "	10	1	" "	44
2	" "	12	1	" "	52
1	" "	17	2	" "	126



Parts required:

2	of No.	2	2	of No.	48A
9	" "	37	1	" "	52
1	" "	37A	4	" "	90A
			1	of No.	126

**Model No. 0.22
Single Sheave
Pulley Block**


Parts required

1	of No.	23
12	" "	37A
1	" "	57
4	" "	111c
2	" "	126A


Model No. 0.23 Couch

Parts required:

1	of No.	2	4	of No.	12	1	of No.	52
3	" "	5	20	" "	37	4	" "	90A
			2	" "	48A			




These Models can be built with MECCANO Outfit No. 0 (or No. 00 and No. 00A)



Model No. 0.24
Punching Bag Stand

Parts required:			
2 of No. 2	12 of No. 37		
1 " " 5	1 " " 52		
1 " " 11	4 " " 90A		
1 " " 22	2 " " 126		


Model No. 0.25
Power Hack Saw




Parts required:		Parts required:		Parts required:	
1 of No. 2	2	1 of No. 24		1 of No. 52	
1 " " 5		1 " " 35		4 " " 90A	
2 " " 11		16 " " 37		2 " " 126	
1 " " 19s		2 " " 48A			

Model No. 0.26
Junction Signal

Parts required:	
3 of No. 2	2
7 " " 5	
2 " " 10	
2 " " 11	
2 " " 12	
2 " " 17	
2 " " 22	
1 " " 23	
4 " " 35	
21 " " 37	
1 " " 40	
1 " " 52	
1 " " 126A	



Model No. 0.28 **Old Siege Gun**




Model No. 0.29 **Anchor**

Parts required:		Parts required:	
2 of No. 2	5	1 of No. 11	
1 " " 5		10 " " 37	
		1 " " 57	
		2 " " 90A	
		2 " " 126A	




Model No. 0.27 **Sled**

Parts required:	
6 of No. 37	1 of No. 52
1 " " 48A	4 " " 90A




Parts required:		Parts required:	
3 of No. 2	2	1 of No. 24	
1 " " 5		18 " " 37	
2 " " 11		2 " " 48A	
4 " " 12		1 " " 52	
2 " " 16		4 " " 90A	
4 " " 22			

Model No. 0.30 Aeroplane



Parts required:					
4 of No.	2	1 of No.	16	1 of No.	35
5 " "	5	1 " "	17	18 " "	37
1 " "	11	2 " "	22	2 " "	126
2 " "	12	1 " "	24	1 " "	126A


Model No. 0.31 Bath Chair



Parts required:


4 of No.	5	17 of No.	37
2 " "	12	2 " "	48A
2 " "	16	1 " "	52
4 " "	22	3 " "	90A
2 of No. 126			

Model No. 0.33 Dump Car



Parts required:					
9 of No.	5	2 of No.	35	2 of No.	90A
6 " "	12	22 " "	37	2 " "	126
1 " "	19s	2 " "	48A	2 " "	126A
4 " "	22	1 " "	52		

Model No. 0.32 Bench Lathe




Parts required:		
3 of No.	2	
5 " "	5	
2 " "	11	
1 " "	16	
1 " "	17	
4 " "	22	
1 " "	24	
15 " "	37	
1 " "	52	
1 " "	125	
2 " "	126	

Model No. 0.34
Punching Machine


Parts required:

3 of No.	2
4 " "	5
2 " "	10
2 " "	11
4 " "	12
1 " "	16
1 " "	17
2 " "	22
2 " "	35
22 " "	37
1 " "	48A
1 " "	52
2 " "	126



These Models can be built with MECCANO Outfit No. 0 (or No. 00 and No. 00A)

Model No. 0.35
The Fencers




Parts required:

8 of No. 5	4 of No. 35
2 " " 10	20 " " 37
6 " " 12	1 " " 52
2 " " 16	2 " " 125
2 " " 22	2 " " 126A


Model No. 0.39 Pen Rack

Parts required:

2 of No. 5
8 " " 37
2 " " 48A
1 " " 52
4 " " 90A



Model No. 0.36 Rattle



Parts required:

2 of No. 2	1 of No. 16
2 " " 5	1 " " 24
1 " " 11	4 " " 35
5 " " 12	9 " " 37


Model No. 0.37
Single Sheave Pulley Block



Parts required:

2 of No. 5	7 of No. 37A
1 " " 23	1 " " 57
3 of No. 111c	


Model No. 0.38 Aerial Ropeway



Parts required:

4 of No. 2	1 of No. 23	2 of No. 48A
4 " " 5	2 " " 35	2 " " 125
2 " " 10	22 " " 37	2 " " 126
1 " " 17	1 " " 40	2 " " 126A

Model No. 0.41
Arm Chair




Parts required:

2 of No. 2
4 " " 5
12 " " 37
1 " " 48A
1 " " 52
3 " " 90A

Model No. 0.40
Music Stand

Parts required:


1 of No. 2
9 " " 5
3 " " 12
12 " " 37
2 " " 48A
1 " " 126




Model No. 0.42 Shearing Machine

Parts required:


4 of No. 2	2 of No. 48A
7 " " 5	1 " " 52
17 " " 37	2 " " 90A



Model No. 0.43 Scooter


Parts
required:

4 of No.	2
2 " "	5
2 " "	11
2 " "	12
2 " "	17
2 " "	22
17 " "	37
1 " "	48A
2 " "	90A

Model No. 0.44 Push Cart


Parts
required:

2 of No.	16	1 of No.	52
4 " "	22	4 " "	90A
16 " "	37	2 " "	126
2 " "	48A	2 " "	126A

**Model No. 0.45
Dog Kennel**

Parts
required:

3 of No.	2
8 " "	5
6 " "	12
20 " "	37
2 " "	48A
1 " "	52
2 " "	90A

Model No. 0.46 Tipping Cart



Parts
required:

7 of No.	5	15 of No.	37	1 of No.	90A
2 " "	16	2 " "	48A	2 " "	125
4 " "	22	1 " "	52	2 " "	126A

**Model No. 0.48
Luggage Truck**

Parts
required:

2 of No.	2
6 " "	5
2 " "	12
1 " "	16
2 " "	22
12 " "	37
1 " "	52
3 " "	90A

**Model No. 0.47
Horse Rake**



Parts
required:

1 of No.	2	3 of No.	22
5 " "	5	2 " "	35
8 " "	12	17 " "	37
1 " "	17	4 " "	90A

**Model No. 0.50
Chaff Cutter**

Parts
required:

2 of No.	2	2 of No.	22
8 " "	5	1 " "	24
1 " "	11	2 " "	35
2 " "	12	19 " "	37
1 " "	16	1 " "	52
1 " "	19s	2 " "	125


**Model No. 0.49
Jib Crane**

Parts
required:

4 of No.	2	1 of No.	19s
9 " "	5	4 " "	22
2 " "	16	1 " "	23
1 " "	17	1 " "	24
		4 " "	35
		17 " "	37
		1 " "	40
		1 " "	48A
		1 " "	52
		1 " "	57

These Models can be built with MECCANO Outfit No. 0 (or No. 00 and No. 00A)

Model No. 0.51 Weather Vane



Parts required :

1 of No. 2	1 of No. 16
2 " " 5	1 " " 22
4 " " 10	
2 " " 11	

Parts required :
(continued)

1 of No. 23
1 " " 24
12 " " 37
1 " " 52
1 " " 126A

Model No. 0.52 Portal




Parts required :

4 of No. 2	22 of No. 37
2 " " 11	2 " " 48A
8 " " 12	1 " " 52
1 " " 22	4 " " 90A

Model No. 0.53 Pump

Parts required :

1 of No. 2	22 of No. 37
6 " " 5	2 " " 48A
2 " " 11	1 " " 52
3 " " 12	2 " " 126
1 " " 16	1 " " 126A
1 " " 17	
1 " " 19s	
3 " " 22	
1 " " 24	
2 " " 35	




The connecting Strip is pivoted by bolts and nuts at one end to the Bush Wheel and at the other end to the cross beam. The latter is pivoted by the same means to the upright.

Model No. 0.56 Go Chair

Parts required :

2 of No. 2
7 " " 5
2 " " 16
4 " " 22
11 " " 37
2 " " 48A



Model No. 0.54 Walking Man




Parts required :

5 of No. 5
3 " " 10
2 " " 12
1 " " 22
7 " " 37
3 " " 90A


Model No. 0.55 Hammock

Parts required :

4 of No. 2	10 of No. 37
8 " " 5	2 " " 126



**Model No. 0.57
Machine Gun**




Parts required :

2 of No. 11	1 of No. 22
4 " " 12	12 " " 37
1 " " 16	1 " " 52
1 " " 19s	4 " " 90A

Model No. 0.58 Swivelling Crane

Parts required :

2 of No. 2	1 of No. 24
4 " " 5	4 " " 35
4 " " 12	18 " " 37
2 " " 16	1 " " 40
2 " " 17	1 " " 44
1 " " 19s	2 " " 48A
4 " " 22	1 " " 52
1 " " 23	1 " " 57
2 of No. 125	



Model No. 0.59 Prancing Horse

Parts required :

6 of No. 5	
4 " " 12	
1 " " 17	
1 " " 19s	
4 " " 22	
1 " " 24	
20 " " 37	
1 " " 44	
1 " " 52	
1 " " 90A	
2 " " 125	
1 " " 126	
1 " " 126A	





FIG. 0.59A

The strip 1 forming part of the body is free to move about the bolt 2, but two nuts on the latter secure the rear legs and tail rigidly together. The arrangement of the various strips about this bolt 2 is shown more clearly in Fig. 0.59A. The strip 3 is free to move at each end about pivots formed from bolts and nuts.

Model No. 0.60 Bench



Parts


required :

2 of No. 2
8 " " 37
1 " " 52
4 " " 90A


Model No. 0.61 Battleship

Parts required :

4 of No. 10	3 of No. 22	2 of No. 43A
1 " " 11	1 " " 24	1 " " 52
4 of No. 2	1 " " 35	2 " " 90A
2 " " 5	22 " " 37	1 " " 125
	2 of No. 126	



Model No. 0.62 Viaduct




Parts required :

8 of No. 5	1 of No. 52
10 " " 37	4 " " 90A

These Models can be built with MECCANO Outfit No. 0 (or No. 00 and No. 00A)

**Model No. 0.63
Parallel Bars**



Parts
required :

2 of No.	2		
6 " "	5		
1 " "	10		
4 " "	12	13 of No.	37
1 " "	16	1 " "	52
3 " "	22	1 " "	111c
2 " "	35	1 " "	126A

Model No. 0.64 Candle Shade

Parts
required

4 of No.	5
8 " "	12
1 " "	24
16 " "	37
4 " "	90A



**Model No. 0.66
Prehistoric Animal**



Model No. 0.65 Revolving Office Chair

Parts required :


3 of No.	5	18 of No.	37
1 " "	12	2 " "	48A
1 " "	17	4 " "	90A
2 " "	22	2 " "	126
1 " "	24	1 " "	126A



Parts
required :


4 of No.	2
2 " "	5
5 " "	10
2 " "	11
4 " "	12
14 " "	37
4 " "	90A

Model No. 0.68 Bridge



Parts required :

2 of No.	2	20 of No.	37
6 " "	5	2 " "	48A
4 " "	12	1 " "	52
		4 of No.	90A



**Model No. 0.67
Billiard Player**

Parts
required :


2 of No.	2
6 " "	5
3 " "	10
5 " "	12
1 " "	16
1 " "	22
1 " "	24
2 " "	35
21 " "	37
2 " "	125

HOW TO CONTINUE


This completes our examples of models that may be made with MECCANO Outfit No. 0. The next models are a little more advanced, requiring a number of extra parts to construct them. The necessary parts are all contained in a No. 0A Accessory Outfit, the price of which will be found in the list at the end of this Manual.



Parts	
required :	
6 of No.	2
8 " "	5
4 " "	12
3 " "	16
4 " "	22
2 " "	35
22 " "	37
4 " "	48A
1 " "	52
2 " "	126A



Parts		
required :		
1 of No.	2	
4 " "	5	
5 " "	12	
3 " "	16	
4 " "	22	
2 " "	35	
14 " "	37	
2 " "	48A	
1 " "	52	
2 " "	54	




Parts required :

2 of No. 2	2 of No. 16	1 of No. 48A
5 " " 5	2 " " 22	1 " " 54
1 " " 11	1 " " 24	2 " " 90A
6 " " 12	21 " " 37	2 " " 100




Parts required :

4 of No. 2	2 of No. 16	8 of No. 37
2 " " 11	4 " " 22	4 " " 48A




Parts required :

4 of No. 2	1 of No. 17
7 " " 5	4 " " 22
2 " " 11	19 " " 37
2 " " 16	1 " " 44
3 of No. 48A	



Parts required :

4 of No. 2	26 of No. 37
8 " " 5	5 " " 48A
2 " " 12	1 " " 54
2 " " 16	2 " " 126A
4 " " 19B	




Parts

2 of No. 2	1 of No. 19s	18 of No. 37
6 " " 5	2 " " 22	1 " " 44
1 " " 11	3 " " 24	3 " " 48A
1 " " 12	4 " " 35	1 " " 52
1 " " 16		

Model No. 1.8

Fire Alarm




Parts required :

4 of No.	1	1 of No.	22
7 " "	2	1 " "	24
1 " "	3	4 " "	35
3 " "	5	27 " "	37
8 " "	12	2 " "	54
1 " "	16		

Model No. 1.9 Swivelling Crane


Parts required :

4 of No.	2	1 of No.	44
7 " "	5	1 " "	48A
2 " "	12	1 " "	52
2 " "	17	1 " "	54
1 " "	19s	1 " "	57
4 " "	22	2 " "	126A
1 " "	23		
2 " "	35		
21 " "	37		
3 " "	38		



The sector plate of the Crane in this model is pivoted to the base with a fast pulley above and below.

Model No. 1.11 Quick-Firing Gun



Parts required :

2 of No.	12
2 " "	16
1 " "	17
4 " "	22
1 " "	24
2 " "	37
1 " "	44
1 " "	54

Model No. 1.10


Submarine

Parts required :

3 of No.	1
2 " "	5
2 " "	11

Parts required (cont.):


2 of No.	12	25 of No.	37
2 " "	16	6 " "	48A
1 " "	19s	1 " "	52
4 " "	22	2 " "	54
1 " "	24	2 " "	125
3 " "	35	2 " "	126A




Model No. 1.12 Racing Motor Car

Parts required :


3 of No.	2	4 of No.	35
4 " "	5	25 " "	37
4 " "	10	3 " "	38
2 " "	11	1 " "	44
8 " "	12	4 " "	48A
2 " "	16	1 " "	126A
1 " "	19s		
4 " "	22		
1 " "	23		
1 " "	24		



The double angle strip 1 carries the front road wheels and is bolted pivotally to the 5½" strip 2, whilst the rear axle is journaled in two angle brackets rigidly secured to the strip 2. A cranked bent strip 3 represents a seat. The steering wheel consists of a ½" pulley 4 bolted to an angle bracket.

Model No. 1.13 AeroplaneParts
required :

4 of No. 1		
2 " " 2		
1 " " 3	1 of No. 16	30 of No. 37
4 " " 5	1 " " 17	2 " " 100
4 " " 10	2 " " 22	2 " " 125
1 " " 11	1 " " 24	1 " " 126
8 " " 12	1 " " 35	2 " " 126A


Model No. 1.14**Man Climbing Pole**

Parts required :

2 of No. 1	26 of No. 37
5 " " 10	4 " " 48A
1 " " 11	1 " " 52
6 " " 12	2 " " 125
1 " " 18A	2 " " 126
3 " " 22	1 " " 126A

Model No. 1.15 Coster's BarrowParts
required :



4 of No. 2	
4 " " 5	
2 " " 10	
2 " " 19B	
16 " " 37	
2 " " 48A	
1 " " 52	
2 " " 126A	

**Model No. 1.17 Centrifugal Governor**

The 3" pulley wheel is bolted to the 5½" x 2½" flanged plate as shown, and the rod 6 is free to rotate in its boss. The bolts 1, 2, 3, are provided with lock-nuts. When the engine to which the governor is attached works at too great a speed, the 1" fast pulley wheels 4 fly outward and lift the two double brackets 5. In actual practice this movement is utilised to close the engine valves and so reduce speed.

Parts
required :

2 of No. 5	
2 " " 10	
2 " " 11	
2 " " 12	
1 " " 16	
1 " " 19B	
1 " " 19s	
4 " " 22	
1 " " 24	
3 " " 35	
18 " " 37	
6 " " 37A	
2 " " 111c	
2 " " 126	


**Model No. 1.16 Bellows**

Parts required :

4 of No. 2	1 of No. 24
1 " " 3	8 " " 35
3 " " 5	25 " " 37
2 " " 10	6 " " 37A
2 " " 11	1 " " 44
4 " " 12	1 " " 52
1 " " 16	2 " " 54
2 " " 17	1 " " 111c
2 of No. 126	

These Models can be built with MECCANO Outfit No. 1 (or No. 0 and No. 0A) and No. 1X


Model No. 1.18 Tower Wagon



Parts required :

4 of No.	2
8 " "	5
2 " "	16
1 " "	17
1 " "	19s
4 " "	22
1 " "	23
4 " "	35
24 " "	37
1 " "	52
1 " "	54
1 " "	57
2 " "	126A


Model No. 1.19 Mountain Transport



Parts required :

2 of No. 1	3 of No. 5	2 of No. 16
2 " " 2	2 " " 11	4 " " 22
18 of No. 37	1 of No. 52	
3 " " 48A	1 " " 54	


Model No. 1.20 Telfer Span



Parts required :

2 of No.	1
2 " "	2
4 " "	5
1 " "	10
1 " "	11
2 " "	12
3 " "	16
1 " "	18A
1 " "	19s
4 " "	22
1 " "	23
8 " "	35
22 " "	37
1 " "	44
2 " "	48A
1 " "	52
2 " "	54
1 " "	57
2 " "	126A

This model will provide many hours of enjoyment. The cords may be made to any length to allow the load to be carried from one side of the room to the other, and, if necessary, a better grip may be obtained by winding the operating cord twice round the pulley on the crank handle. The open sides of the bucket may be closed with cardboard so that it may be loaded with marbles, beads, etc. The bed of the Telfer may be screwed on to a solid base with ordinary wood screws to give better support. The pulley bracket, and that securing the cord on which the bucket travels should be screwed in a suitable position on the opposite side of the room.



These Models can be built with MECCANO Outfit No. 1 (or No. 0 and No. 0A) and No. 1X

Model No. 1.21 Horseman

Parts required:


2	of	No.	2
7	"	"	5
3	"	"	10
2	"	"	12
2	"	"	16
4	"	"	22
1	"	"	24
17	"	"	37
1	"	"	52
1	"	"	54
2	"	"	90A
1	"	"	126A



Model No. 1.22 Helve Hammer

Parts required:

4	of	No.	1	23	of	No.	37
6	"	"	5	1	"	"	44
2	"	"	11	3	"	"	48A
2	"	"	12	1	"	"	52
1	"	"	16	2	"	"	125
1	"	"	17	2	"	"	126A
1	"	"	19s				
4	"	"	22				
1	"	"	24				
4	"	"	35				




Model No. 1.25

Ship's Lamp

Parts required:


2	of	No.	2	4	of	No.	37A
4	"	"	12	1	"	"	48A
1	"	"	17	1	"	"	52
2	"	"	22	1	"	"	54
1	"	"	24	4	"	"	90A
11	"	"	37	2	"	"	111c




Model No. 1.23 Revolving See-Saw

Parts required:

4	of	No.	2	1	of	No.	24
3	"	"	5	2	"	"	35
1	"	"	11	25	"	"	37
6	"	"	12	5	"	"	38
1	"	"	16	1	"	"	44
1	"	"	17	4	"	"	48A
1	"	"	19s	1	"	"	52
2	"	"	22	1	"	"	54
				2	of	No.	125



Model No. 1.24 King Meccano




Parts required:

1	of	No.	3	1	of	No.	35
9	"	"	5	30	"	"	37
5	"	"	10	1	"	"	52
8	"	"	12	2	"	"	111c
1	"	"	17	2	"	"	125
1	"	"	22	2	"	"	126A


These Models can be built with MECCANO Outfit No. 1 (or No. 0 and No. 0A) and No. 1X

Model No. 1.26 Invalid Chair



Parts required:	2 of No. 10
	2 " " 16
4 of No. 2	4 " " 22
6 " " 5	24 " " 37
	4 " " 48A
	1 " " 52
	1 " " 54


Model No. 1.27 Ticca Gharry



Parts required:		
4 of No. 2	6 of No. 12	22 of No. 37
6 " " 5	2 " " 16	1 " " 52
2 " " 10	4 " " 22	1 " " 54

Model No. 1.28 Mechanical Saw

Parts required:			
1 of No. 2	1 of No. 17	4 of No. 38	
8 " " 5	1 " " 19s	1 " " 44	
1 " " 10	3 " " 22	4 " " 48A	
1 " " 11	1 " " 24	1 " " 52	
4 " " 12	3 " " 35	2 " " 125	
1 " " 16	22 " " 37	1 " " 126A	




The strip 9 represents the saw. The crank handle drives through a belt 1 a short rod journalled in a double bracket 2 and carrying a bush wheel 3. The latter imparts a reciprocating motion to the saw frame 4 through a $2\frac{1}{2}$ " strip 5 loosely mounted on bolts secured to the bush wheel and to an angle bracket bolted to the saw frame. This frame slides on a $3\frac{1}{2}$ " rod 6, which acts as a guide, passing through the frame and supported in a reversed angle bracket 7. A washer is placed on the bolt 8 behind the bracket 7. A vice to secure the objects in position for cutting consists of a flat bracket 10 mounted on a bolt 11, a few turns of which causes the flat bracket to grip the object 12. The bolt 11 enters a nut held between the flat trunnion 13 and $5\frac{1}{2}$ " strip 14, which are spaced apart for the purpose by washers placed on the two bolts holding the trunnion in position. The saw frame rests on the stop 15 when not in use. A 1" pulley secured to the top of the frame acts as a weight and helps to steady the saw.

Model No. 1.29 Letter Balance

Parts required:		
6 of No. 2	4 of No. 22	2 of No. 48A
3 " " 5	1 " " 24	1 " " 52
1 " " 10	26 " " 37	2 " " 111c
1 " " 12	4 " " 37A	2 " " 126
2 " " 18A	2 " " 38	2 " " 126A
1 " " 19B	1 " " 44	




Model No. 1.30 Hatchet



Parts required:		
3 of No. 1	15 of No. 37	
6 " " 12	2 " " 54	

Model No. 1.31 Truck with Sides


Parts required:	
4 of No. 2	
4 " " 5	
2 " " 16	
4 " " 22	
12 " " 37	
4 " " 48A	
1 " " 52	



These Models can be built with MECCANO Outfit No. 1 (or No. 0 and No. 0A) and No. 1X

33


Model No. 1.32 Deck Chair



Parts required :


4 of No. 1	4 of No. 35
2 " " 2	26 " " 37
4 " " 5	3 " " 48A
4 " " 10	1 " " 52
2 " " 16	2 " " 126A

Model No. 1.33 Luggage Cart



Parts required :	4 of No. 5	18 of No. 37
	4 " " 12	1 " " 52
	1 " " 16	2 " " 90A
2 of No. 2	2 " " 22	2 " " 100
		2 " " 126A

Model No. 1.34 Mechanical Stamp




Parts required :

5 of No. 2	2
5 " " 5	5
3 " " 16	17
1 " " 17	22
4 " " 22	24
1 " " 35	35
6 " " 37	44
20 " " 44	48A
1 " " 52	52
6 " " 90A	90A
1 " " 100	100
1 " " 126A	126A


Model No. 1.35 Potter's Wheel

Parts required :

3 of No. 2	3 of No. 22
4 " " 5	1 " " 24
1 " " 16	1 " " 35
1 " " 18A	12 " " 37
1 " " 19B	3 " " 48A
1 " " 19s	1 " " 52



Model No. 1.36 Elevator




Parts required :

4 of No. 1	1
2 " " 2	2
6 " " 5	5
6 " " 12	16
1 " " 16	19s
1 " " 19s	22
1 " " 22	35
5 " " 35	37
32 " " 37	48A
6 " " 48A	52
1 " " 52	54
2 " " 54	90A
2 " " 90A	

Model No. 1.37 See-Saw

Parts required :

4 of No. 2	1 of No. 44
4 " " 5	1 " " 52
6 " " 12	2 " " 90A
1 " " 17	
2 " " 35	
19 " " 37	




These Models can be built with MECCANO Outfit No. 1 (or No. 0 and No. 0A) and No. 1X

Model No. 1.38


Try-Your-Strength Machine

Parts required:

4 of No.	1
1 " "	2
6 " "	12
1 " "	17
3 " "	22
1 " "	23
2 " "	35
17 " "	37
1 " "	52
1 " "	111c
2 " "	126
1 " "	126A



Model No. 1.39 Motor Van



Parts required:

3 of No.	5	1 of No.	35
1 " "	11	17 " "	37
1 " "	12	1 " "	48A
2 " "	16	1 " "	52
1 " "	17	1 " "	54
4 " "	22	3 " "	90A
1 " "	23	1 " "	111c
1 " "	24	1 " "	125
1 of No. 126A			

The steering mechanism is shown more clearly in Fig. 1.39A. A length of cord is given two or three turns round the steering column, and is held in position by a spring clip, its ends being tied to a $2\frac{1}{2} \times \frac{1}{2}$ double angle strip. The latter is pivoted to the $5\frac{1}{2} \times 2\frac{1}{2}$ flanged plate of the lorry by means of a bolt and two nuts (see Standard Mechanisms Manual, Detail No. 262).





Fig. 1.39A


Model No. 1.40 Double Cable Key

Parts required:

2 of No.	2
2 " "	22
4 " "	37
1 " "	52
2 " "	111c



Model No. 1.41 Revolving Hammer-Head Crane



Parts required:

2 of No.	1
8 " "	2
4 " "	5
2 " "	12
1 " "	16
1 " "	17
1 " "	18A
2 " "	19B
1 " "	19s
2 " "	22

Parts required (continued):

1 of No.	24
8 " "	35
32 " "	37
3 " "	48A
1 " "	52
1 " "	57
2 " "	126


These Models can be built with MECCANO Outfit No. 1 (or No. 0 and No. 0A) and No. 1X

35

Model No. 1.42 Anti-Aircraft Gun

Parts required :


4 of No. 2	1 of No. 54
4 " " 5	3 " " 111c
8 " " 12	1 " " 125
1 " " 16	2 " " 126
1 " " 17	
2 " " 18A	
2 " " 19B	
3 " " 22	
1 " " 24	
4 " " 35	
18 " " 37	
2 " " 38	
1 " " 48A	



Model No. 1.43 Paddle Steamer

Parts required :


4 of No. 2	1 of No. 52	1 of No. 125
1 " " 3	2 " " 54	2 " " 126
4 " " 5	4 " " 90A	
1 " " 10		
2 " " 12		
2 " " 16		
2 " " 18A		
3 " " 22		
1 " " 24		
3 " " 35		
36 " " 37		
3 " " 48A		



Model No. 1.44 Signal

Parts required :


2 of No. 1	
1 " " 3	
1 " " 5	
2 " " 22	
11 " " 37	
2 " " 37A	
1 " " 52	
2 " " 111c	



Model No. 1.45 Meccanograph

Parts required :

1 of No. 3	
4 " " 5	
2 " " 11	
6 " " 12	
2 " " 16	
2 " " 17	
1 " " 19B	
2 " " 22	
1 " " 24	
5 " " 35	
21 " " 37	
2 " " 37A	
2 " " 38	
2 " " 48A	
1 " " 52	
2 " " 100	
3 " " 111c	
2 " " 126	



Model No. 1.46 Ladder on Wheels

Parts required :

6 of No. 2	
4 " " 5	
2 " " 16	
4 " " 19B	
16 " " 37	
8 " " 38	
4 " " 48A	
1 " " 52	




These Models can be built with MECCANO Outfit No. 1 (or No. 0 and No. 0A) and No. 1X

Model No. 1.47 Scooter


Parts required :

5 of No. 1	2	1 of No. 22
1 " " 10	1	" " 24
1 " " 11	14	" " 37
3 " " 12	2	" " 38
1 " " 17	1	" " 44
1 " " 18A	1	" " 48A
2 of No. 126A		



Model No. 1.49 Ballista


This is a model of an ancient engine of war, resembling the crossbow. The $3\frac{1}{2}$ " strip 1 is bolted firmly to the double angle strip 2, which is prevented from turning by the addition of angle brackets as shown. A double bracket 3 slides on the strip 1 and is secured to a piece of cord. On rotation of the crank handle 4, the strip 1 is pulled backward until the double bracket 3 slips off its end. The strip then flies forward and strikes the missile, which consists of a 2" rod placed ready in the double bracket 5.



4 of No. 1	2 of No. 16	1 of No. 44
4 " " 2	1 " " 18A	4 " " 48A
1 " " 3	3 " " 19B	1 " " 52
2 " " 11	1 " " 19S	1 " " 90A
2 " " 12	4 " " 22	2 " " 126A
	21 " " 37	

Model No. 1.48 Tight-Rope Walker

The cord on which the "Meccanition" runs is endless and passes over the 1" fast pulleys at each end of the model. One of the pulleys is secured to a crank handle, by means of which the model may be operated. The Meccanition runs on the upper half of the endless cord, the lower half being attached to one of his feet.




Parts required :

4 of No. 1	2 of No. 17	
4 " " 2	1 " " 19S	
1 " " 3	4 " " 22	2 of No. 48A
8 " " 5	1 " " 23	1 " " 52
3 " " 10	6 " " 35	2 " " 54
4 " " 12	34 " " 37	1 " " 126A
2 " " 16		

Model No. 1.50 Inclined Plane

Parts required :


4 of No. 1	1 of No. 23
2 " " 2	4 " " 35
6 " " 5	10 " " 37
3 " " 16	1 " " 48
4 " " 22	3 " " 48A
	1 " " 57



These Models can be built with MECCANO Outfit No. 1 (or No. 0 and No. 0A) and No. 1X


Model No. 1.51 Travelling Crane

Parts required :		
2 of No. 1	1 of No. 24	2 of No. 90A
6 " " 2	4 " " 35	5 " " 111c
1 " " 11	20 " " 37	1 " " 125
3 " " 16	4 " " 37A	2 " " 126
1 " " 18A	1 " " 48	2 " " 126A
2 " " 19B	4 " " 48A	
4 " " 19S	1 " " 52	
1 " " 22	1 " " 57	
1 " " 23		



Model No. 1.53 Motor Tractor

Parts required :		
3 of No. 5		
1 " " 10		
2 " " 12		
2 " " 16		
1 " " 18A		
4 " " 19B		
1 " " 22		
1 " " 24		
15 " " 37		
2 " " 37A		
6 " " 38		
4 " " 48A		
1 " " 52		
1 " " 54		
1 " " 111c		
2 " " 126		
1 " " 126A		



The steering gear is shown in Fig. 1.53A. The front wheels are carried in a $2\frac{1}{2}'' \times \frac{1}{2}''$ double angle strip 1, which is mounted pivotally by a bolt and two nuts (S.M. 262) to a $2\frac{1}{2}''$ strip 2 secured to the $5\frac{1}{2}'' \times 2\frac{1}{2}''$ flanged plate.

Model No. 1.52 Motor Cyclist and Pillion Rider

Parts required :		
4 of No. 2	4 of No. 22	
9 " " 5	1 " " 24	
4 " " 10	2 " " 35	
2 " " 11	30 " " 37	
8 " " 12	2 " " 48A	
1 " " 16	2 " " 90A	
2 " " 17	2 " " 125	
2 of No. 126A		






Fig. 1.53A

These Models can be built with MECCANO Outfit No. 1 (or No. 0* and No. 0A) and No. 1X

Model No. 1.54 Hand Loom



Parts required:


4 of No.	2
6 " "	5
7 " "	12
2 " "	16
1 " "	24
21 " "	37
4 " "	48A
1 " "	52

The warp threads are tied at one end to a double angle strip 1, whilst their other ends are secured alternately to the tops of the upright strips 2, and the 2½" strip 3. The "shedding" movement of the warp is obtained by moving the strip 3 up or down each time the shuttle—a 3½" rod 4—is passed between the two layers of warp 5 and 6. Wool or similar material is particularly suited to this apparatus. The strands 6 should be kept very taut, and the weft threads may be closed up with the woven portion by means of an ordinary comb each time the shuttle passes.


Model No. 1.55 Gong

Parts required:

4 of No.	2	1 of No.	22
1 " "	5	9 " "	37
3 " "	12	1 " "	52
1 " "	16	1 " "	54




Model No. 1.56 Punching Machine



Parts required:

4 of No.	2
2 " "	5
1 " "	16
4 " "	22
1 " "	24
16 " "	37
4 " "	48A
1 " "	52

Model No. 1.57 Roundabout




Parts required:

4 of No.	1	1 of No.	17	22 of No.	37
4 " "	2	1 " "	19	4 " "	48A
6 " "	5	3 " "	22	1 " "	52
4 " "	10	1 " "	24	2 " "	54
2 " "	16	6 " "	35		

Begin to build this model by making the platform from a flanged plate and 12½" strips. The drive from the pulley on the crank handle is taken to a 1" pulley fast on a vertical 2" rod, another similar pulley being secured to this rod beneath the plate. The arms are formed of four 5½" strips bolted to a bush wheel fast on the 2" rod.

Model No. 1.58 Gymnast



Parts required:		
4 of No.	1	
3 " "	5	
3 " "	10	
8 " "	12	
1 " "	16	
1 " "	19s	
3 " "	22	
1 " "	24	
3 " "	35	
25 " "	37	
2 " "	37A	
1 " "	38	
1 " "	52	
2 " "	54	
1 " "	126A	

One of the $2\frac{1}{2}$ " strips representing the arms of the gymnast is bolted to a bush wheel secured on a $3\frac{1}{2}$ " rod. When the crank handle is rotated the gymnast turns complete somersaults in a very amusing manner. The gymnast's "arms" must be pivoted to the angle brackets forming his shoulders by means of bolts and lock-nuts


Parts required:		
3 of No.	1	
8 " "	2	
4 " "	12	
20 " "	37	
2 " "	54	
2 " "	100	

Model No. 1.59 Rake



Parts required:		
1 of No.	2	
1 " "	3	
4 " "	10	
1 " "	12	
6 " "	37	

Model No. 1.60 Inverted Truss




Model No. 1.61 Coat Hanger



Parts required:		
1 of No.	1	2 of No. 5
2 " "	2	6 " " 37
1 of No. 57		


Model No. 1.62 Aerial Flight



Parts required:		
4 of No.	1	4 of No. 12
4 " "	2	3 " " 16
8 " "	5	1 " " 18A
1 " "	10	2 " " 19B
1 " " 19s		

Parts required (continued):		
3 of No.	22	33 of No. 37
1 " "	23	2 " " 38
6 " "	35	2 " " 48A
1 of No. 52		
2 " " 54		
2 " " 126		
1 " " 126A		


Model No. 1.63 Butter Churn



Parts required:

2 of No.	2
4 " "	5
1 " "	19s
1 " "	24
2 " "	35
18 " "	37
4 " "	38
1 " "	52
2 " "	54
2 " "	126A

Model No. 1.64 Cable Railway



Parts required:

2 of No.	1	1 of No.	19s	4 of No.	48A
2 " "	2	4 " "	22	1 " "	52
4 " "	12	2 " "	35	2 " "	100
2 " "	16	18 " "	37		

Model No. 1.67 Candle Stick

Parts required:


2 of No.	11
4 " "	12
1 " "	19B
4 " "	37
1 " "	111c
1 " "	125



Model No. 1.66 Inverted Centrifugal Governor

Parts required:


4 of No.	2	1 of No.	19s
5 " "	5	4 " "	22
1 " "	11	1 " "	23
8 " "	12	1 " "	24
1 " "	16	3 " "	35
1 " "	18A	22 " "	37
2 " "	19B	6 " "	37A
		4 " "	38
		1 " "	48A
		1 " "	52
		1 " "	54
		3 " "	111c
		1 " "	125



Model No. 1.68 Machine for Tracing a Locus


Parts required:

1 of No.	2	4 of No.	35
1 " "	5	4 " "	37
1 " "	11	3 " "	37A
1 " "	12	4 " "	38
1 " "	17	1 " "	54
1 " "	18A	2 " "	111c
1 " "	24	1 " "	125



The $5\frac{1}{2}$ " strip is pivoted to the $2\frac{1}{2}$ " strip by means of a bolt and two nuts, and the $2\frac{1}{2}$ " strip is similarly pivoted to the sector plate. By revolving the $2\frac{1}{2}$ " strip about its pivot, the vertical $1\frac{1}{2}$ " rod can be made to trace a locus. If the positions of the $1\frac{1}{2}$ " rod and the $5\frac{1}{2}$ " strip are altered, several different loci may be traced. Machines of this type are of advantage in assisting in the design of engine connecting rods.

Model No. 1.65 Man and Boy



Parts required:


4 of No.	2
1 " "	3
1 " "	5
5 " "	10
1 " "	11
8 " "	12
1 " "	22
1 " "	24
26 " "	37
1 " "	52
2 " "	54
1 " "	90A
2 " "	125
1 " "	126A

These Models can be built with MECCANO Outfit No. 1 (or No. 0 and No. 0A) and No. 1X

Model No. 1.69 Gramophone

Parts required:


2 of No. 10	6 of No. 37	1 of No. 52
1 " " 12	1 " " 38	2 " " 111c
1 " " 19B		
1 " " 23		
1 " " 24		



Model No. 1.70 Lancer

Parts required:


1 of No. 2	4 of No. 22
1 " " 3	1 " " 24
9 " " 5	1 " " 35
2 " " 10	27 " " 37
2 " " 11	1 " " 48A
5 " " 12	1 " " 52
2 " " 16	1 " " 54
1 " " 19s	4 " " 90A
1 of No. 126A	



Model No. 1.71 Stamping Machine

Parts required:


4 of No. 2	
4 " " 5	
2 " " 10	
2 " " 16	
1 " " 19s	
4 " " 22	
1 " " 24	
2 " " 35	
22 " " 37	
4 " " 48A	
1 " " 52	
2 " " 126A	



Model No. 1.72 Lorry Crane

Parts required:


4 of No. 2	2 of No. 16
8 " " 5	1 " " 17
2 " " 10	1 " " 18A
2 " " 12	1 " " 19s
	3 " " 22
	1 " " 23
	1 " " 24
	3 " " 35
	29 " " 37
	1 " " 44
	5 " " 48A
	1 " " 52
	1 " " 54
	1 " " 57
	2 " " 125
	4 " " 126



Model No. 1.73 Lazy Tong


Parts required:

2 of No. 1	1 of No. 23	2 of No. 48A
4 " " 2	12 " " 37	2 " " 111c
4 " " 5	10 " " 37A	



These Models can be built with MECCANO Outfit No. 1 (or No. 0 and No. 0A) and No. 1X


Model No. 1.74 Rowing Boat



Parts required :

4 of No. 2	4 of No. 35
4 " " 5	24 " " 37
4 " " 10	3 " " 48A
7 " " 12	1 " " 52
2 " " 16	2 " " 54
1 " " 22	1 " " 111c

Model No. 1.77 Tower Wagon




Parts required :

6 of No. 2	2
6 " " 5	
3 " " 16	
4 " " 19B	
1 " " 19s	
3 " " 22	
2 " " 35	
33 " " 37	
5 " " 48A	
1 " " 52	
1 " " 57	
1 " " 125	
2 " " 126	
2 " " 126A	


Model No. 1.75 Weather Vane

Parts required :

3 of No. 1	14 of No. 37
2 " " 2	1 " " 52
1 " " 11	1 " " 54
2 " " 12	1 " " 111c
1 " " 24	2 " " 126



Model No. 1.76 Violin and Bow



Parts required :


4 of No. 2	1 of No. 12	5 of No. 37
1 " " 5	1 " " 18A	1 " " 54
1 " " 11	2 " " 35	1 " " 126

Model No. 1.78 Beam Engine

The connecting strip 1 is attached pivotally by a bolt and two nuts (Standard Mechanism No. 262) to one end of the beam 2 and to the bush wheel 3. The strip 4 is similarly connected to the other end of the beam 2 and to the double bracket 5 attached to the piston rod. The short rod carrying the flywheel 6 is journaled in a 2 1/2" strip supported by the trunnion 7 and in a reversed angle bracket bolted to the 2 1/2" strip.

Parts required :


6 of No. 2	2
1 " " 3	
1 " " 5	
2 " " 11	
3 " " 12	
2 " " 16	
1 " " 17	
1 " " 19B	
1 " " 24	
8 " " 35	
20 " " 37	
4 " " 37A	
1 " " 48	
1 " " 52	
2 " " 125	
1 " " 126	
2 " " 126A	



These Models can be built with MECCANO Outfit No. 1 (or No. 0 and No. 0A) and No. 1X

43

Model No. 1.79
Chinese Windlass




Parts
required :

4 of No.	1
1 " "	3
1 " "	18A
3 " "	19B
1 " "	19S
3 " "	22
1 " "	23
1 " "	24
8 " "	37
1 " "	44
2 " "	48A
1 " "	52
1 " "	57

Model No. 1.80 Bellows

Parts
required :


2 of No.	2
1 " "	17
9 " "	37
4 " "	48A
2 " "	54



Model No. 1.82
Sand Yacht

Parts
required :

1 of No.	1
1 " "	2
1 " "	3
2 " "	5
2 " "	12
2 " "	16
1 " "	18A
4 " "	19B
1 " "	22
1 " "	24
4 " "	35
23 " "	37
1 " "	52
1 " "	54
2 " "	90A
1 " "	125
1 " "	126
2 " "	126A



Model No. 1.81 Bed Table




Parts
required :

3 of No.	2
1 " "	3
1 " "	5
1 " "	11
5 " "	12
2 " "	16
1 " "	17
4 " "	22
1 " "	24
31 " "	37
4 " "	48A
1 " "	52
1 " "	126A

Model No. 1.83 Forge Bellows


Parts required :

4 of No.	2	1 of No.	19
1 " "	3	2 " "	22
2 " "	5	1 " "	24
2 " "	10	5 " "	35
1 " "	11	25 " "	37
2 " "	12	3 " "	48A
2 " "	16	1 " "	52
1 " "	17	2 " "	54
2 of No. 126A			



These Models can be built with MECCANO Outfit No. 1 (or No. 0 and No. 0A) and No. 1X

Model No. 1.84 Bow Girder



Parts required :


2 of No. 1	6 of No. 37
4 " " 12	2 " " 54

Model No. 1.87 Coaster

The figure 1 is loosely attached by lock-nutted bolts 2 to the sector plate 3 and is connected to the bush wheel 4 by the pivotally-attached $2\frac{1}{2}$ " strip 5. The $1\frac{1}{2}$ " rod carrying the bush wheel 4 is journaled in the cranked bent strip 6, the 1" fast pulley 7 being connected to the road wheel by a cord as shown.

Parts required :


2 of No. 2	2 of No. 18A
9 " " 5	4 " " 22
5 " " 10	1 " " 23
2 " " 11	1 " " 24
7 " " 12	8 " " 35
1 " " 16	37 " " 37
2 " " 17	6 " " 37A
	1 " " 48
	2 " " 48A
	2 " " 54
	2 " " 111c
	2 " " 125
	2 " " 126A




Model No. 1.85 Hooke's Coupling

Parts required :

2 of No. 11	7 of No. 35
2 " " 12	12 " " 37
3 " " 16	1 " " 48
2 " " 19B	2 " " 48A
1 " " 19s	1 " " 52
	2 of No. 54




Model No. 1.86 Arc Lamp



Parts required :

2 of No. 1	
1 " " 3	
1 " " 22	
1 " " 24	
10 " " 37	
1 " " 52	
1 " " 90A	
2 " " 126	


Model No. 1.88 Quick Return Device



Parts required :

2 of No. 2	1 of No. 24
1 " " 3	6 " " 35
2 " " 5	15 " " 37
2 " " 11	2 " " 37A
2 " " 12	3 " " 48A
1 " " 17	1 " " 52
2 " " 18A	2 " " 125

Model No. 1.89 Motor Lorry



Parts
required :

2 of No.	2
2 "	5
2 "	12
2 "	16
1 "	18A
4 "	19B
1 "	24
25 "	37
2 "	38
3 "	48A
1 "	52
1 "	54
1 "	90A
2 "	100
2 "	125
2 "	126A





FIG. 1.89A

Model No. 1.90 Scales

Parts
required :

2 of No.	2
2 "	12
1 "	18A
2 "	35
8 "	37
1 "	52
2 "	54
2 "	126




Model No. 1.91 Spinning Buttons

The sector plates 1 and 2 are mounted pivotally on the rods 3. Two large buttons 4 are placed on lengths of thread or thin elastic stretched between the arms of the Meccanities 5. Start the model as follows: twist the threads a little with your fingers, pull the Meccanities outward, then release them sharply. As soon as the buttons are spinning a slight downward touch on the feet of each Meccanitian is sufficient to keep them going. The ends of the sector plates 1 and 2 are connected to the flanged plate 6 by means of pieces of elastic 7.

Parts
required :


2 of No.	1
6 "	5
4 "	10
8 "	12
2 "	16
2 "	17
2 "	22
6 "	35
28 "	37
4 "	48A
2 "	111c
2 "	126A



These Models can be built with MECCANO Outfit No. 1 (or No. 0 and No. 0A) and No. 1X

Model No. 1.92 Swivelling Jib Crane, Electric


Parts required :		
4 of No. 1	1 of No. 23	1 of No. 57
6 " " 2	1 " " 24	Electric Motor
1 " " 3	6 " " 35	(included in No. 1x
1 " " 11	30 " " 37	Outfit only)
6 " " 12	1 " " 40	
2 " " 16	2 " " 48A	
2 " " 17	1 " " 52	
1 " " 18A	1 " " 54	
4 " " 19B		
4 " " 22		



Model No. 1.93

Swivelling Jib Crane, Hand Operated

This illustrates an alternative construction of the base of model No. 1.92, and is intended to show how the model may be operated by hand if an electric motor is not available.



Parts required :		
4 of No. 1	4 of No. 12	
6 " " 2	2 " " 17	
1 " " 5	1 " " 18A	
1 " " 11	2 " " 19B	
	1 " " 19s	
	4 " " 22	
	1 " " 23	
	1 " " 24	
	4 " " 35	
	32 " " 37	
	4 " " 38	
	1 " " 48	
	1 " " 48A	
	1 " " 52	
	2 " " 54	
	1 " " 57	
	1 " " 126	
	1 " " 126A	


Model No. 1.94 Overhead Crane

Parts required :		
4 of No. 2		
4 " " 5		
2 " " 10		
4 " " 12		
1 " " 16		
1 " " 18A		
1 " " 19s		
4 " " 22		
1 " " 23		
1 " " 24		
2 " " 35		
25 " " 37		
1 " " 38		
6 " " 48A		
1 " " 57		
4 " " 90A		
2 " " 100		




Model No. 1.95 Band Saw

Parts required :		
2 of No. 1		
2 " " 2		
2 " " 5		
2 " " 16		
1 " " 19B		
1 " " 19s		
2 " " 22		
6 " " 35		
18 " " 37		
3 " " 48A		
1 " " 52		
2 " " 90A		
2 " " 126A		



Model No. 1.96 Timber Drag

Parts required :		
1 of No. 1	2 of No. 11	4 of No. 48A
1 " " 2	2 " " 16	3 " " 111c
1 " " 3	4 " " 19B	2 " " 125
2 " " 5	19 " " 37	2 " " 126A
2 " " 10	3 " " 37A	



Model No. 1.97 Bow and Arrow

Parts required:


1 of No. 1 | 1 of No. 16

**Model No. 1.100 Friction Grip Tongs**

The hoisting cord is attached to the double bracket 1. The joints 2, 3 are lock-nutted, so that when the grip is raised the $\frac{1}{2}$ " loose pulley wheel 4 slides upward between the $2\frac{1}{2}$ " strips 5, and the grip closes upon the block of wood or other material placed between its jaws.


Parts required:

3 of No. 2	1 of No. 11
8 " " 5	1 " " 23
4 " " 10	2 " " 35
12 of No. 37	

**Model No. 1.98****Cum Bak**

Parts required:

1 of No. 18A
2 " " 19B
2 " " 22
1 " " 23
1 " " 35
8 " " 37
4 " " 48A




A short length of elastic is doubled and stretched between the centres of the 3" pulley wheels. A weight, consisting of two 1" fast pulley wheels and a $1\frac{1}{2}$ " rod, is suspended from it in the middle of the drum. When the Cum Bak is rolled along any smooth level surface, the elastic becomes twisted and stores up sufficient energy to return the drum to its starting point. If the mechanism is concealed by a thin cardboard covering, the model will cause much amusement by its mystifying behaviour.

Model No. 1.99 Aeroplane

Parts required:

4 of No. 2
6 " " 5
4 " " 10
2 " " 11




2 of No. 12	23 of No. 37
2 " " 16	2 " " 48A
2 " " 22	4 " " 90A
1 " " 24	2 " " 100
1 " " 35	2 " " 126A

Model No. 1.101 Gangway


Parts required:

4 of No. 2	1 of No. 16	22 of No. 37	2 of No. 100
2 " " 5	1 " " 22	4 " " 48A	1 " " 111c
3 " " 10	1 " " 23	1 " " 52	2 " " 126A
1 " " 12	4 " " 35	1 " " 54	



These Models can be built with MECCANO Outfit No. 1 (or No. 0 and No. 0A) and No. 1X

Model No. 1.102 Windlass



Parts required :


6 of No.	5
3 "	12
1 "	19B
1 "	19s
3 "	22
15 "	37
4 "	37A
2 "	48A
1 "	52
1 "	57
3 "	111c
1 "	126A

The figure at the right of the model is arranged to work to and fro when the crank handle is rotated. The bolts 1 and 2 are both secured by two nuts as in Standard Mechanism No. 262.

Model No. 1.104 Top

Parts required :

1 of No.	2	1 of No.	19B
1 "	16	1 "	37
1 of No.	125		




To spin the top wind a length of cord round the rod, as shown, place on a smooth surface and give the cord a sharp pull. When the cord is clear of the rod remove the $5\frac{1}{2}$ " strip and the top will continue to spin for a considerable period

Model No. 1.103 Cart

Parts required :

2 of No.	2	4 of No.	48A
1 "	16	1 "	52
2 "	19B	2 "	100
14 "	37	2 "	126A




Model No. 1.105 The Invalid

When wheeled along the table the "invalid" appears to push himself energetically along. His neck is a flat bracket; his right (or propelling) arm consists of one angle bracket and one $\frac{1}{2}$ " reversed angle bracket, and his left arm—the hand of which is bolted loosely to the chair—is formed by three angle brackets. The chair is composed principally of two sector plates and four $5\frac{1}{2}$ " strips, and it runs on three 1" pulley wheels—one in front and two at the back.

One of these (not visible in the illustration) drives by cord another 1" pulley wheel, the shaft of which also carries a bush wheel 1. As will be seen, a $2\frac{1}{2}$ " strip is pivoted at one end to this bush wheel and at the other end to a second $2\frac{1}{2}$ " strip 2, which, rocking about an axle journaled through its centre hole, is again pivoted to the invalid's hands.

Parts required :


4 of No.	2
6 "	5
1 "	10
4 "	12
3 "	16
1 "	17
4 "	22
1 "	23
1 "	24
4 "	35
24 "	37
4 "	37A
3 "	38
2 "	48A
2 "	54
1 "	125
1 "	126A



These Models can be built with MECCANO Outfit No. 1 (or No. 0 and No. 0A) and No. 1X

49

Model No. 1.106 Giant Foundry Ladle



Parts required :

2 of No.	1	1 of No.	23
6 "	2	1 "	24
7 "	5	36 "	37
2 "	10	6 "	37A
1 "	16	7 "	48A
1 "	17	1 "	52
3 "	19B	2 "	54
1 "	19s	6 "	111c
3 "	22	2 "	126A





FIG. 1.106A

Double-Action Pump

The $5\frac{1}{2}$ " strip 1 is attached to the 1" pulley wheel 2 by means of two angle brackets, through the lower of which passes the set-screw that secures the pulley to its 2" rod. Two washers are placed beneath the head of the bolt joining the angle brackets in order to prevent its shank from binding on the boss of the pulley 2. The joints 3, 4, 5, 6, 7, are all lock-nutted, the remainder of the joints being quite rigid. When the strip 1 descends, together with the first pump, the incidental distortion of the parallelogram 3, 4, 7, 4 causes the second pump to rise. Similarly, when the first pump rises, the second descends.

Model No. 1.108 Double-Action Pump




Parts required :

5 of No.	2
1 "	3
4 "	5
2 "	11
6 "	12
2 "	17
2 "	22
1 "	24
21 "	37
6 "	37A
4 "	38
3 "	48A
1 "	52
6 "	111c
2 "	125

Model No. 1.107 Elevated Jib Crane

A 1" fast pulley wheel secured to the armature spindle of the electric motor is connected by an endless cord to the 3" pulley wheel 1. A 1" fast pulley 2 on the same rod as the latter is similarly connected with a second 3" pulley wheel 3. A cord wound on the rod to which the latter is secured carries the load hook. The jib is supported by two cords 4, and the whole superstructure, which is secured to the 3" pulley wheel 6, is capable of revolving with the rod 5. The latter is journaled in two $2\frac{1}{2}$ " x $\frac{1}{2}$ " double angle strips secured between the sector plates in the base of the model.




Parts required :

2 of No.	1
4 "	2
4 "	5
1 "	11
2 "	12
3 "	16
1 "	17
3 "	19B
4 "	22
1 "	23
1 "	24
5 "	35
26 "	37
2 "	38
5 "	48A
1 "	52
2 "	54
1 "	57
4 "	90A

4-volt Electric Motor
(included in 1x Outfit only)

These Models can be built with MECCANO Outfit No. 1 (or No. 0 and No. 0A) and No. 1X



Model No. 1.109 Shepherd's Crook

Parts required:

2 of No. 1 | 7 of No. 37 | 4 of No. 90A

Model No. 1.110 Meccano Dancer

Two $\frac{3}{4}$ " bolts, secured in opposite slots of the 3" pulley wheel, alternately press down the end of the $5\frac{1}{2}$ " strip 1 and cause the figure to dance in a surprisingly lifelike manner.

Parts required:


2 of No. 1	4 of No. 35
4 " " 2	18 " " 37
1 " " 3	1 " " 52
7 " " 5	1 " " 90A
1 " " 16	3 " " 111c
1 " " 18A	2 " " 126A
1 " " 19B	
1 " " 19S	
3 " " 22	
1 " " 24	

Model No. 1.111 Large Rake

Parts required:

1 of No. 1 | 2 of No. 12
2 " " 2 | 8 " " 37
1 of No. 126A


Model No. 1.112 Gate



Model No. 1.113 Blacksmith


Parts required:

1 of No. 3	1 of No. 35
8 " " 5	26 " " 37
2 " " 10	4 " " 37A
2 " " 11	1 " " 44
5 " " 12	1 " " 52
1 " " 19S	1 " " 54
1 " " 22	1 " " 111c
1 " " 24	2 " " 125
2 of No. 126A	



Parts required:


6 of No. 2
3 " " 5
5 " " 12
13 " " 37
4 " " 37A
1 " " 52
2 " " 111c
1 " " 126A



These Models can be built with MECCANO Outfit No. 1 (or No. 0 and No. 0A) and No. 1X

51

Model No. 1.114 Revolving Tricyclist



Parts required :

3 of No. 2	1 of No. 24
3 " " 5	5 " " 35
3 " " 10	25 " " 37
1 " " 11	1 " " 44
5 " " 12	2 " " 48A
1 " " 16	1 " " 52
2 " " 17	2 " " 125
1 " " 19s	2 " " 126
4 " " 22	1 " " 126A





FIG. 1.114A

Model No. 1.116 Truck




Parts required :

2 of No. 16
4 " " 19B
8 " " 37
2 " " 48A
1 " " 52
2 " " 100

Model No. 1.115 Steam Shovel

Parts required :


5 of No. 2	1 of No. 52
1 " " 11	1 " " 54
1 " " 12	1 " " 111c
2 " " 16	1 " " 126
2 " " 18A	2 " " 126A
1 " " 19s	
4 " " 22	
1 " " 23	
6 " " 35	
12 " " 37	
2 " " 37A	
2 " " 38	



Model No. 1.117 Cot on Wheels

Parts required :


2 of No. 2
5 " " 5
4 " " 12
2 " " 16
4 " " 22
19 " " 37
2 " " 48A
1 " " 52
4 " " 90A
2 " " 100




Model No. 1.118 Chair

Parts required :

2 of No. 2
8 " " 5
2 " " 10
22 " " 37
6 " " 48A
1 " " 52
3 " " 90A



Model No. 1.119 A Sudden Appearance




The sector plate 1, forming the lid, is carried pivotally on an axle rod that passes through its sides three holes from the end, and the rear sector plate 2 is pivoted in a similar manner, excepting that the rod in this case passes through the fourth hole from the end. Pieces of thin elastic are tied to the end holes in each side of the front sector plate at its widest end, and are connected to the ends of screws at the bottom of the box. The "Meccanitian" 3 is placed face downward inside the box with its feet towards the far end of the model. The tension of the elastic holding the lid 1 should be sufficient to keep him in this position. On tilting the plate 1 slightly, however, he will suddenly shoot out of the box, drawn by the elastic bands 4 connected to the $3\frac{1}{2}$ " axle rod 5.

Model No. 1.121 Bath Chair

Parts required :


4 of No. 2	6 of No. 48A
7 " " 5	1 " " 52
2 " " 16	1 " " 126
1 " " 18A	2 " " 126A
2 " " 19B	
3 " " 22	
24 " " 37	
1 " " 37A	
1 " " 44	



Parts required :

4 of No. 1	14 of No. 35
4 " " 2	29 " " 37
9 " " 5	6 " " 48A
5 " " 10	1 " " 52
4 " " 12	2 " " 54
4 " " 16	1 " " 111c
1 " " 22	1 " " 126A

Model No. 1.120 Rat Trap



Parts required :


8 of No. 2			
1 " " 3			
8 " " 5			
5 " " 10			
2 " " 11			
6 " " 12	1 of No. 23	1 of No. 38	1 of No. 54
2 " " 16	1 " " 24	1 " " 48	1 " " 57
1 " " 17	8 " " 35	6 " " 48A	2 " " 90A
3 " " 22	31 " " 37	1 " " 52	3 " " 111c

The " bait " consists of a 1" fast pulley and a $\frac{1}{2}$ " loose pulley suspended by means of a hook from a double bracket. The latter is bolted to a $1\frac{1}{2} \times \frac{1}{2}$ " double angle strip that is free to turn on a 2" rod journaled in a pair of angle brackets. A flat bracket bolted to the double bracket engages a second double bracket on the end of a $5\frac{1}{2}$ " strip that is bolted to the door of the cage. If the " bait " is touched, the heavily-weighted door falls into place, and is prevented from re-opening by catches formed from flat brackets secured to $5\frac{1}{2}$ " strips that are bolted to the trap by their extreme ends and act as springs.


Model No. 1.122 Manual Fire Engine

Parts required :

2 of No. 2	
2 " " 5	
2 " " 11	
2 " " 16	
2 " " 17	
1 " " 18A	
4 " " 19B	
6 " " 35	
12 " " 37	
2 " " 38	
1 " " 52	
2 " " 126	



Model No. 1.123 Field Roller



Parts required :

2 of No. 1	1 of No. 16	6 of No. 48A
3 " " 5	2 " " 19B	2 " " 90A
6 " " 12	30 " " 37	2 " " 126

Model No. 1.126
Dignity and Impudence


Parts required :

5 of No. 2	4 of No. 35
4 " " 5	27 " " 37
5 " " 10	4 " " 48A
2 " " 11	1 " " 52
8 " " 12	2 " " 54
1 " " 16	2 " " 111c
1 " " 17	2 " " 125
2 " " 22	1 " " 126A

Model No. 1.124
Disappearing Meccanitian

Parts required :

6 of No. 2	23 of No. 37
6 " " 5	1 " " 44
1 " " 10	6 " " 48A
4 " " 12	1 " " 52
2 " " 16	2 " " 54
1 " " 22	1 " " 111c
6 " " 35	1 " " 126A




The bottom of the box-like portion of the model consists of a $5\frac{1}{2}'' \times 2\frac{1}{2}''$ flanged plate; three $5\frac{1}{2}''$ strips bolted to upright $2\frac{1}{2}''$ strips form each side and each end consists of three $2\frac{1}{2}'' \times \frac{1}{2}''$ double angle strips. The lid 1, which is mounted pivotally on an axle rod 2, consists of two sector plates bolted together. Elastic bands are tied to the sides of these plates and connected to rod 3 passed through the bottom of the box. The Meccanitian 4 also is connected to this rod by pieces of elastic. On pressing the end of the rear sector plate the lid opens sufficiently to allow the figure to be drawn inside and then snaps back into place. A cranked bent strip 5 is bolted at the back of the figure and rests against the edge of the sector plate.

Model No. 1.125 Elevator

Parts required :


4 of No. 1
7 " " 2
1 " " 3
4 " " 5
1 " " 12
1 " " 16
2 " " 19B
1 " " 19s
4 " " 22
33 " " 37
3 " " 38
6 " " 48A
1 " " 52
2 " " 54
2 " " 100
2 " " 126
2 " " 126A



Model No. 1.127 Elevated Crane

Parts required :

2 of No.	1	1 of No.	52
8 "	2	2 "	54
8 "	5	1 "	57
1 "	11	4 "	90A
2 "	16	2 "	126
1 "	18A	2 "	126A
3 "	19B		
1 "	19s		
4 "	22		
1 "	23		
1 "	24		
3 "	35		
36 "	37		
3 "	38		
4 "	48A		




The base of the swivelling portion of the crane consists of a 3" pulley wheel 1, which has a 3/4" axle rod nipped in its boss. The rod is journalled in two 2 1/2" double angle strips 2 and 3 secured round the sector plates 4. The brake cord 5 passes round the 3" pulley as shown, and is tied to one of the holes in the bush wheel 6. The cords 7 serve merely to support the weight of the jib.

Model No. 1.128 Acrobat on See-Saw

Parts required :

3 of No.	1	3 of No.	22
6 "	2	1 "	24
4 "	5	5 "	35
3 "	10	32 "	37
2 "	11	2 "	48A
4 "	12	1 "	52
2 "	16	1 "	111c
1 "	18A	1 "	126A
1 "	19B		




The 1" rod 1 is journalled in the end holes of two 5 1/2" strips 2 and in the flat trunnion 3 which joins them. It is held in position by two spring clips, placed on either side of the 5 1/2" strips 2.

Model No. 1.129 Acrobats

Parts required :


4 of No.	2
6 "	5
4 "	10
4 "	12
1 "	16
1 "	19s
4 "	22
1 "	24
3 "	35
24 "	37
5 "	38
6 "	48A
1 "	52
2 "	126A

Model No. 1.130
Umpire's Seat

Parts required :


6 of No.	2
7 "	5
2 "	10
4 "	12
24 "	37
3 "	48A
2 "	90A
2 "	126




Model No. 1.131 Gyroscope

Parts
required:
4 of No. 12
1 " " 16
4 " " 19B
1 " " 24
10 " " 37
4 " " 48A


The 7/32" bolt 1 is gripped by the set-screw of the bush wheel. The lower end of the rod 2 of the Gyroscope enters the boss of the bush wheel and rests on the shank of the bolt 1.

Model No. 1.132 Bicycle

Parts
required:
1 of No. 3
7 " " 5
2 " " 10
2 " " 11
4 " " 12
2 " " 17
1 " " 18A
2 " " 19B
2 " " 22
1 " " 24
4 " " 35
13 " " 37
4 " " 37A
3 " " 38
2 " " 90A
4 " " 111c
2 " " 125
1 " " 126A

**Model No. 1.133
Fire Alarm**


Parts required:
4 of No. 1 | 1 of No. 24
1 " " 3 | 2 " " 35
4 " " 5 | 13 " " 37
1 " " 16 | 2 " " 48A
1 " " 22 | 1 " " 52
1 of No. 54

**Model No. 1.134
Band Brake**

Parts required:
1 of No. 2 | 1 of No. 19s | 1 of No. 52
2 " " 5 | 2 " " 22 | 2 " " 54
1 " " 12 | 1 " " 35 | 1 " " 111c
10 " " 37

Model No. 1.135 Luggage Truck


Parts required:
2 of No. 2 | 18 of No. 37
8 " " 5 | 2 " " 48A
1 " " 16 | 1 " " 52
2 " " 19B | 4 " " 90A




Model No. 1.136 Boy on Swing

Parts required :

4 of No.	1	8 of No.	12	1 of No.	24
6 "	"	2 "	"	7 "	"
2 "	"	5 "	"	35 "	"
5 "	"	10 "	"	1 "	"
				1 "	"
				1 "	"
				2 "	"
				2 "	"



Model No. 1.137 Mechanical Shovel




Parts required :


4 of No.	1	1 of No.	24
6 "	"	6 "	"
5 "	"	35 "	"
2 "	"	1 "	"
3 "	"	1 "	"
1 "	"	6 "	"
1 "	"	1 "	"
1 "	"	2 "	"
4 "	"	1 "	"
1 "	"		

Model No. 1.138 Jib Crane

Parts required :

4 of No.	1	1 of No.	24
6 "	"	23 "	"
1 "	"	1 "	"
1 "	"	2 "	"
2 "	"	1 "	"
3 "	"		
1 "	"		
2 "	"		
1 "	"		
1 "	"		
4 "	"		



Model No. 1.139 Toast Rack



Parts required :

6 of No.	5
6 " "	12
21 " "	37
1 " "	52
4 " "	90A


Model No. 1.142 Eccentric Dancers

Parts required :

6 of No.	5	4 of No.	22	2 of No.	111c
4 " "	10	1 " "	23	1 " "	125
6 " "	12	20 " "	37	2 " "	126A
		4 " "	48A		

**Model No. 1.140 Crosshead Demonstration Model**

This is an apparatus for determining the forces that act at the crosshead of a reciprocating engine. The upper inclined length of cord represents the connecting rod and the lower, or vertical portion, the piston rod. The pull on the third cord indicates the pressure exerted on the slide bars of the engine due to the angularity of the connecting rod.

Model No. 1.141 Drop Stamp


Parts required :


4 of No.	2
6 " "	5
3 " "	10
2 " "	16
1 " "	19
4 " "	22
1 " "	34
2 " "	35
2 " "	37
3 " "	48A
1 " "	52
1 " "	54
2 " "	126A

Model No. 1.143 Boat Steering Gear

Parts required :

4 of No.	2	1 of No.	24
1 " "	3	14 " "	37
2 " "	11	4 " "	37A
1 " "	12	1 " "	40
1 " "	16	1 " "	48A
1 " "	18A	1 " "	52
1 " "	19B	6 " "	111c
3 " "	22	1 " "	126



Model No. 1.144 Electric Elevator

Two pairs of cords 1 are stretched tightly on each side of the lift shaft to guide the cage 2 and two other cords 3 are secured at the top and bottom of the shaft and passed behind $2\frac{1}{2}$ " strips 4 bolted to the cage. The drive from the motor is transmitted to the 3" pulley wheel 5 by means of a cord passed round a $\frac{1}{2}$ " pulley on the motor armature.

Parts required :



4 of No. 1	3 of No. 35
6 " " 2	34 " " 37
4 " " 5	1 " " 38
2 " " 12	1 " " 48
3 " " 16	6 " " 48A
3 " " 19B	1 " " 52
4 " " 22	2 " " 54
1 " " 24	2 " " 100

2 of No. 125


Electric Motor
(included in No. 1x
Outfit only)

Model No. 1.147
Safety Catch for Winding Gear
Parts required :

2 of No. 5
1 " " 19s
1 " " 24
1 " " 35
8 " " 37
1 " " 37A
1 " " 52
2 " " 54
1 " " 111c

**Model No. 1.145 Mounted Cowboy****Parts required :**


1 of No. 3
6 " " 5
2 " " 10
2 " " 11
8 " " 12
1 " " 22
24 " " 37
1 " " 52
4 " " 90A
1 " " 111c
1 " " 125

Model No. 1.146 Howitzer**Parts required :**


2 of No. 2	2 of No. 19B
6 " " 5	2 " " 22
4 " " 10	2 " " 35
2 " " 11	14 " " 37
4 " " 12	2 " " 38
1 " " 16	2 " " 111c
2 of No. 125	

Model No. 1.148
Master and Student
Parts required :

9 of No. 5
1 " " 10
2 " " 11
8 " " 12
2 " " 22
20 " " 37
3 " " 37A
1 " " 52
1 " " 90A
4 " " 111c
1 " " 125




Model No. 1.149 Windmill Pump



Parts required :

2 of No. 1	1 of No. 24
9 " " 5	4 " " 35
2 " " 10	24 " " 37
3 " " 12	4 " " 37A
3 " " 16	2 " " 48A
1 " " 19B	1 " " 52
1 " " 19S	2 " " 111c
4 " " 22	2 " " 126A

Model No. 1.150 Coaster




Parts required :

2 of No. 2	
2 " " 5	
4 " " 10	
2 " " 16	
1 " " 18A	
4 " " 19B	
1 " " 22	6 of No. 38
1 " " 24	4 " " 48A
22 " " 37	1 " " 52
2 " " 37A	2 " " 126A

Model No. 1.152 Racing Motor Car


The steering column 1 is journalled in an angle bracket 2 bolted to the $5\frac{1}{2}'' \times 2\frac{1}{2}''$ flanged plate 3, and in the second hole of the $2\frac{1}{2}'' \times \frac{1}{2}''$ double angle strip 4. A bush wheel 5, secured to the lower end of the steering column, is connected by two short lengths of cord to a second $2\frac{1}{2}'' \times \frac{1}{2}''$ double angle strip carrying the front axle. The strip is pivoted to a similar double angle strip 6 by means of a bolt and nuts (Standard Mechanism No. 262).



Parts required :

4 of No. 2	3 of No. 16	25 of No. 37	1 of No. 52
7 " " 5	4 " " 19B	2 " " 37A	2 " " 54
1 " " 10	1 " " 22	4 " " 38	1 " " 111c
1 " " 11	1 " " 24	4 " " 48A	1 " " 125
		1 of No. 126	

Model No. 1.151 Swivelling Crane




Parts required :

2 of No. 1	
6 " " 2	
6 " " 5	
2 " " 11	
1 " " 12	
1 " " 16	
1 " " 17	
3 " " 19B	
1 " " 19S	
4 " " 22	
1 " " 24	
2 " " 35	
25 " " 37	
1 " " 37A	
2 " " 48A	
1 " " 52	
2 " " 54	
1 " " 57	
2 " " 90A	
1 " " 111c	

Model No. 1.153 Automatic Signal


Parts
required :

2 of No.	1
1 " "	2
1 " "	5
1 " "	11
1 " "	12
1 " "	17
1 " "	18A
4 " "	22
1 " "	24
22 " "	37
2 " "	37A
1 " "	38
1 " "	48A
1 " "	52
1 " "	90A
3 " "	111c
2 " "	126
2 " "	126A



The weighted curved strip normally holds the end of the $5\frac{1}{2}$ " strip against an angle bracket, allowing the signal arm to fall to the "all clear" position. Any train passing the signal however, strikes the opposite end of the $5\frac{1}{2}$ " strip, and by means of the cord shown, raises the arm to indicate "danger." The curved strip moves to allow the end of the $5\frac{1}{2}$ " strip to pass over it, and is returned to its original position by reason of its weighted end. The signal then remains at "danger" until the mechanism is re-set.


Model No. 1.154 Horse and Cart



Parts required :

4 of No.	2	2 of No.	16	2 of No.	35	3 of No.	90A
3 " "	5	2 " "	18A	26 " "	37	1 " "	111c
3 " "	10	2 " "	19B	1 " "	48A	2 " "	125
2 " "	11	4 " "	22	1 " "	52	2 " "	126
2 " "	12	1 " "	24	1 " "	54	2 " "	126A

Model No. 1.156 Drill




Parts
required :

1 of No.	3
2 " "	11
6 " "	12
1 " "	16
1 " "	18A
1 " "	19B
1 " "	19S
4 " "	22
1 " "	24
2 " "	35
27 " "	37
1 " "	52
1 " "	54
4 " "	90A
1 " "	125
2 " "	126

Model No. 1.155 Patent Luffing Crane


The hoisting cord 1 is operated by the crank handle 2. It passes over the 1" pulley 3, round the 1" pulley 4 at the jib head, back and round a third 1" pulley 5, and then over the $\frac{1}{2}$ " loose pulley 6 at the jib head and down to the hook. With this arrangement it will be found that the load remains at a constant height when the jib is luffed. The luffing cords 7 are attached to the jib head, passed over the 2" rod carrying the pulleys 3 and 5, and wound on to the luffing winch 8.



Parts
required :

2 of No.	1
3 " "	2
4 " "	5



1 of No.	12
2 " "	16
1 " "	17
1 " "	18A
1 " "	19B
1 " "	19S
4 " "	22
1 " "	23
1 " "	24
6 " "	35
16 " "	37
5 " "	38
1 " "	44
1 " "	52
2 " "	54
1 " "	57
2 " "	111

Model No. 1.157 Sawing Machine**Parts required :**


4 of No. 2	2 of No. 22
3 " " 5	1 " " 24
1 " " 10	2 " " 35
2 " " 11	22 " " 37
4 " " 12	1 " " 44
1 " " 17	2 " " 48A
1 " " 19A	1 " " 52
2 of No. 126A	

Parts required


4 of No. 2	2
6 " " 5	5
1 " " 10	10
6 " " 12	12
2 " " 16	16
4 " " 22	22
1 " " 23	23
20 " " 37	37
2 " " 48A	48A
1 " " 52	52
1 " " 54	54
1 " " 111c	111c

Model No. 1.160 Sailing Boat**Model No. 1.158 Rotating Crane****Parts required :**

4 of No. 2	1 of No. 24
9 " " 5	5 " " 35
2 " " 10	25 " " 37
1 " " 11	4 " " 48A
2 " " 16	1 " " 52
1 " " 17	1 " " 54
1 " " 19s	1 " " 57
4 " " 22	1 " " 125

Model No. 1.159 Motor Lorry**Parts required :**

2 of No. 5	1 of No. 17	1 of No. 52
4 " " 10	4 " " 22	1 " " 54
1 " " 11	1 " " 24	2 " " 100
2 " " 12	1 " " 35	1 " " 125
2 " " 16	23 " " 37	2 " " 126A
	4 " " 48A	


Model No. 1.161 Pen Rack**Parts required :**

4 of No. 2	2
4 " " 5	5
4 " " 10	10
19 " " 37	37
4 " " 48A	48A
1 " " 52	52
1 " " 57	57

The running wheels of this crane are journaled in double angle strips bolted to the base plate and secured at an angle by means of flat brackets. The rear of the base plate is supported on a double bracket. The jib is bolted loosely to the supporting $5\frac{1}{2}$ " strips and is connected by $2\frac{1}{2}$ " strips to the sector plate which pivots about its supporting bolts. By moving this sector plate the elevation of the jib may be altered as desired. The movement is controlled by a double angle strip mounted on the crank handle and connected pivotally to the plate by means of a $2\frac{1}{2}$ " strip. A reversed angle bracket bolted to an upright double angle strip in the rear of the model serves to restrict the movement of the sector plate.

These Models can be built with MECCANO Outfit No. 1 (or No. 0 and No. 0A) and No. 1X


Model No. 1.162 Revolving Gymnasts



Parts required :

2 of No.	1
1 " "	2
8 " "	5
2 " "	10
2 " "	11
10 " "	12
1 " "	16
2 " "	17
4 " "	22
1 " "	24
4 " "	35
29 " "	37
5 " "	38
4 " "	48A
1 " "	52
2 " "	126A

Model No. 1.163 Pantograph



Parts required :


4 of No.	1	1 of No.	22
1 " "	11	1 " "	35
2 " "	12	9 " "	37
1 " "	17	3 " "	37A
		2 of No.	125

The pantograph enables plans, drawings, etc., to be reproduced on a larger or smaller scale than the original. If a pencil, suitably whittled down, is fixed in the reversed angle bracket at the top of the illustration, and the $1\frac{1}{2}$ " rod is made to follow the outlines of the drawing, the pencil will draw an accurately enlarged sketch. If the positions of the rod and the pencil be reversed, the latter can be made to trace a reduced sketch of the original drawing.

Model No. 1.164 Double-Action Piston Connection

Parts required :

2 of No.	1	1 of No.	23
6 " "	2	1 " "	35
1 " "	3	36 " "	37
5 " "	5	5 " "	37A
4 " "	10	4 " "	48A
2 " "	11	1 " "	52
3 " "	12	1 " "	90A
2 " "	19B	3 " "	111C
1 " "	19S	2 " "	126A




HOW TO CONTINUE

This completes our examples of models that may be made with Outfit No. 1 and Outfit No. 1x. The next models are a little more advanced, requiring a number of extra parts to construct them. The necessary parts are all contained in a No. 1A Accessory Outfit, the price of which will be found in the List at the end of this Manual.

These Models can be built with MECCANO Outfit No. 2 (or No. 1 and No. 1A) and No. 2X

Model No. 2.1 Steam Lorry




The boiler of the engine is built up of $2\frac{1}{2}'' \times \frac{1}{2}''$ double angle strips bolted to the bush wheel 1, and to two $2\frac{1}{2}''$ strips 2, which are joined together by flat brackets 3. A $2\frac{1}{2}''$ curved strip (small radius) is bolted to the upper strip 2. A cord is passed completely round two $\frac{3}{4}''$ flanged wheels 4 secured to the steering column, and its ends are tied to the $2\frac{1}{2}'' \times \frac{1}{2}''$ double angle strip 5. The double bent strip bolted to the strip 5 is pivoted by a bolt and two nuts to the sector plate.

Parts required :

2 of No.	3	3 of No.	12
10 "	5	3 "	16
2 "	10	1 "	17
1 "	11	1 "	18A
		2 "	19B
		4 "	20
		3 "	22
		1 "	22A
		1 "	24
		5 "	35
		60 "	37
		5 "	37A
		1 "	45
		8 "	48A
		1 "	52
		2 "	54
		1 "	62
		3 "	90A
		2 "	100
		4 "	111c
		1 "	125
		2 "	126A


Model No. 2.3 Turnstile



Parts required :

12 of No.	2
5 "	5
1 "	15A
1 "	22
1 "	24
1 "	35
44 "	37
1 "	38
1 "	48
8 "	48A
1 "	52
4 "	90A
2 "	99
2 "	126

Model No. 2.2 Mechanical Hammer



Parts required :

2 of No.	2
1 "	3
6 "	5
4 "	8
1 "	11
1 "	12
3 "	16
4 "	22
1 "	22A
1 "	24
8 "	35
32 "	37
1 "	45
3 "	48A
1 "	52
2 "	54
2 "	126A

Clockwork Motor
(included in No. 2x
Outfit only)




FIG. 2.2A

Model No. 2.4 Try-Your-Strength Machine




FIG. 2.4A

Parts required :

6 of No. 1	1	60 of No. 37
6 " " 2	2	6 " " 37A
1 " " 3	4	4 " " 38
2 " " 5	1	1 " " 45
2 " " 6A	1	1 " " 48
4 " " 8	1	1 " " 48A
2 " " 10	1	1 " " 52
10 " " 12	2	2 " " 54
2 " " 18A	3	3 " " 90A
1 " " 23	2	2 " " 100
1 " " 24	2	2 " " 126
3 " " 35		





FIG. 2.4B


The bush wheel 1 is secured to a short axle rod 2, the lower end of which rests on a pair of angle brackets 3 bolted to the ends of four $5\frac{1}{2}$ " strips 4. The strips 4 are pivoted as shown (Fig. 2.4A) on a $1\frac{1}{2}$ " rod 5, and on their opposite ends rests a $\frac{1}{2}$ " loose pulley wheel 6. When the bush wheel 1 is struck, the $5\frac{1}{2}$ " strips fling the pulley wheel 6 upward, but the wheel is guided by the vertical $12\frac{1}{2}$ " strips 7. The weight of the strips 4 then causes the bush wheel to resume its original position.



Model No. 2.5 Tipping Motor Wagon

Parts required :


2 of No. 1	1	4 of No. 19B	1 of No. 52
4 " " 2	4	4 " " 22	2 " " 54
11 " " 5	1	1 " " 24	4 " " 90A
2 " " 6A	6	6 " " 35	2 " " 100
6 " " 12	59	59 " " 37	3 " " 111c
4 " " 16	4	4 " " 37A	1 " " 115
1 " " 17	1	1 " " 45	2 " " 126
1 " " 18A	1	1 " " 48	1 " " 126A
	7	7 " " 48A	



The front axle rod is journaled in a $2\frac{1}{2}$ " \times $\frac{1}{4}$ " double angle strip 1 which in turn is bolted to a double bent strip 2. The double bent strip is pivoted to the sector plate by a bolt and two nuts. Cord passing over a 1" pulley wheel attached to the rod 3 is fastened to the ends of the double angle strip 1, and by rotating another pulley, which represents the steering wheel, the road wheels are deflected.

Model No. 2.6 Electric Truck

An underneath view of the truck is shown in Fig. 2.6A. The front axle is journalled in a $1\frac{1}{2} \times \frac{1}{2}$ " double angle strip 1 that is free to turn on a double bent strip 2, from which it is spaced by a $\frac{1}{4}$ " loose pulley. A length of cord is wrapped round the 1" pulley 3, which is secured to the end of the steering column, and then passed through a cranked bent strip 4 and secured to the double angle strip 1 as shown. The brake cord 5 is attached to the double bent strip 2, wrapped several times round the $\frac{3}{4}$ " flanged wheels 6, passed through the angle bracket 7, and is finally attached to the crank 8. The operating pedal consists of double brackets bolted to another crank that is secured to the same rod as the crank 8.



Parts required:

3 of No. 5	1 of No. 22A	7 of No. 48A
1 " " 6A	1 " " 23	1 " " 52
2 " " 11	4 " " 35	2 " " 62
1 " " 12	35 " " 37	3 " " 90A
1 " " 12A	2 " " 37A	1 " " 111c
3 " " 16	5 " " 38	1 " " 115
1 " " 17	1 " " 44	1 " " 126
3 " " 20	1 " " 45	2 " " 126A
4 " " 22	1 " " 48	





FIG. 2.6A

Parts required:

9 of No. 2	2 of No. 35
2 " " 3	54 " " 37
8 " " 5	6 " " 37A
2 " " 6A	8 " " 38
4 " " 8	1 " " 45
1 " " 12	6 " " 48A
1 " " 16	1 " " 52
1 " " 17	2 " " 54
2 " " 19B	2 " " 99
2 " " 22	6 " " 111c
1 " " 24	1 " " 115


Model No. 2.7 Coal Sifter

The $5\frac{1}{2}$ " strip 1 is pivoted to the angle bracket 2 by a bolt and two nuts. The angle bracket in turn is bolted to the flanged plate, which is suspended in such a way that it is free to swing to and fro. The other end of the $5\frac{1}{2}$ " strip is pivoted to the bush wheel 3.



These Models can be built with MECCANO Outfit No. 2 (or No. 1 and No. 1A) and No. 2X

Model No. 2.8 Treadle Lathe



Parts
required :


7 of No.	2
1 " "	3
1 " "	5
2 " "	6A
4 " "	11
6 " "	12
2 " "	12A
1 " "	16
1 " "	17
3 " "	19B
4 " "	22
1 " "	24
1 " "	35
34 " "	37
2 " "	37A
4 " "	38
1 " "	45
1 " "	52
4 " "	90A
1 " "	115
1 " "	125

The $2\frac{1}{2}$ " strip 2, forming the treadle, is attached pivotally by means of a bolt and two nuts to the angle bracket 1. One end of a further $2\frac{1}{2}$ " strip is connected by the same means to the $2\frac{1}{2}$ " strip 2, and the other end is mounted on a threaded pin secured to the 3" pulley wheel.

Model No. 2.9 Smoothing Iron


Parts required :

4 of No.	2	20 of No.	37
2 " "	3	2 " "	38
6 " "	10	1 " "	48A
4 " "	11	2 " "	54
2 " "	12	1 " "	126A



Model No. 2.10

Gong




Parts required :

6 of No.	1	2 of No.	11
4 " "	2	1 " "	15
2 " "	5	1 " "	22
2 " "	8	27 " "	37
1 of No. 54			

Model No. 2.11 Mat Frame

Parts required :


10 of No.	1	3 of No.	11	1 of No.	18A
4 " "	8	6 " "	12	54 " "	37
4 " "	10	2 " "	12A	2 " "	37A
				2 " "	38
				1 " "	45
				2 " "	62
				4 " "	90A
				2 " "	111C
				1 " "	115
				4 " "	125
				2 " "	126
				2 " "	126A



The strips 1 are hinged to the frame in the following manner. Two cranks 2 with their bosses facing inward are bolted to the strips 1 and two angle brackets are secured to the frame. A rod is then pushed through the holes in the angle brackets and secured in the bosses of the cranks. A double bracket fastened to the ends of the strips 1 carries a threaded pin, which fits in the holes in the trunnions 3. By removing this pin, the frame may be folded flat.

These Models can be built with MECCANO Outfit No. 2 (or No. 1 and No. 1A) and No. 2X

Model No. 2.12 Spinning Top




Parts
required :

1 of No.	2
1 " "	16
2 " "	19B
2 " "	20
2 " "	37
1 " "	40
1 " "	62

The drum on which the cord is wound consists of two $\frac{3}{4}$ " flanged wheels butted together. While the cord is being pulled, the top is held steadily on some smooth surface by means of the handle shown above. The handle is then lifted off, allowing the top to spin freely.


Model No. 2.14 High Level Bridge



Parts
required :

8 of No.	2
4 " "	5
32 " "	37
8 " "	48A
1 " "	52
2 " "	100

Model No. 2.13 Sand Yacht




Parts required :

8 of No.	1	1 of No.	24
2 " "	2	12 " "	35
1 " "	5	60 " "	37
4 " "	8	9 " "	38
4 " "	10	8 " "	48A
4 " "	11	1 " "	52
12 " "	12	1 " "	54
2 " "	12A	1 " "	62
3 " "	16	1 " "	90A
1 " "	17	1 " "	115
2 " "	18A	4 " "	125
4 " "	19B	1 " "	126
1 " "	23	2 " "	126A

Model No. 2.15 Polishing Spindle

Parts required :


4 of No.	12	20 of No.	37
1 " "	16	3 " "	48A
2 " "	22	1 " "	52
1 " "	24	2 " "	54
2 " "	35	2 " "	126



These Models can be built with MECCANO Outfit No. 2 (or No. 1 and No. 1A) and No. 2X


Model No. 2.16 Windmill

The operating cord 1 is given a complete turn round the pair of $\frac{3}{4}$ " flanged wheels 2. It is then led round the 1" loose pulley 3, over the 3" pulley 4, then down and round the $\frac{3}{4}$ " flanged wheels secured to the crank handle 5. The vane 6 is rotated by a cord which passes round a 1" fixed pulley 7 secured to the shaft of the flanged wheels 2.




Parts required	
8 of No.	1
13 " "	2
2 " "	3
10 " "	5
4 " "	8
4 " "	12
1 " "	15
1 " "	15A
1 " "	16
1 " "	18A
2 " "	19B
1 " "	19S
4 " "	20
2 " "	22
1 " "	22A
1 " "	24
6 " "	35
60 " "	37
4 " "	37A
7 " "	38
2 " "	48A
1 " "	52
2 " "	54
4 " "	90A
2 " "	100
4 " "	111c
2 " "	126

Model No. 2.17 Coaster



Model No. 2.18 Towel Horse



Parts required :	
4 of No.	12
2 " "	22A
28 " "	37
2 " "	37A
4 " "	8
2 " "	8
2 " "	8
4 " "	10

Parts required :

2 of No.	1	1 of No.	23
8 " "	2	1 " "	24
4 " "	5	44 " "	37
4 " "	8	4 " "	38
1 " "	15	1 " "	48
1 " "	15A	4 " "	48A
1 " "	17	1 " "	52
4 " "	19B	1 " "	54
3 " "	22	2 " "	62
2 of No. 126			




FIG. 2.17A


These Models can be built with MECCANO Outfit No. 2 (or No. 1 and No. 1A) and No. 2X

69

Model No. 2.19 Motor Van

Parts required :

6 of No. 2	1 of No. 24	6 of No. 48A
10 " " 5	5 " " 35	1 " " 52
1 " " 10	35 " " 37	2 " " 54
2 " " 12	2 " " 37A	3 " " 111c
1 " " 15	1 " " 38	2 " " 125
1 " " 15A	1 " " 45	2 " " 126A
1 " " 16	1 " " 48	
4 " " 19B		
3 " " 22		



The axle rod 1 is journalled in a $2\frac{1}{2}'' \times \frac{1}{2}''$ double angle strip 2. The latter is bolted to a double bent strip that is pivoted to the flanged plate 3 by a bolt and two nuts. Steering is effected by a cord attached to the ends of the double angle strip 2 and passed round a 1" pulley wheel fastened to the lower end of the steering rod.

Model No. 2.20


Easel

Parts required :

5 of No. 1
3 " " 2
2 " " 3
3 " " 5
4 " " 12
2 " " 12A
1 " " 15A
2 " " 22
19 " " 37
4 " " 38



Model No. 2.21 Stamping Mill




Parts required :

2 of No. 3	30 of No. 37
2 " " 6A	2 " " 37A
10 " " 12	11 " " 38
2 " " 15	1 " " 48
1 " " 15A	1 " " 52
1 " " 17	2 " " 54
2 " " 19B	2 " " 62
1 " " 20	4 " " 90A
4 " " 22	2 " " 111c
1 " " 24	1 " " 115
1 " " 35	1 " " 126

These Models can be built with MECCANO Outfit No. 2 (or No. 1 and No. 1A) and No. 2X

Model No. 2.22


Candy Puller



Parts required:

6 of No. 2	3 of No. 35
2 " " 8	36 " " 37
6 " " 12	4 " " 38
2 " " 15	4 " " 48A
2 " " 17	1 " " 52
2 " " 19B	2 " " 54
4 " " 22	2 " " 62
1 " " 24	4 " " 90A
1 of No. 115	

Model No. 2.23 Revolving Truck



Parts required:


1 of No. 16
2 " " 17
2 " " 22
2 " " 22A
4 " " 35
6 " " 37
1 " " 52
4 " " 125

Model No. 2.24 Sifter


The $5\frac{1}{2}$ " strip 1 is pivoted by a bolt and two nuts (S.M.262) to the bush wheel and also to a trunnion bolted to the under-surface of the flanged plate 2. The rod carrying the bush wheel is journaled in one of the side girders and through a double bent strip.

Parts required:

4 of No. 1	2 of No. 54
5 " " 2	2 " " 99
4 " " 5	2 " " 111c
2 " " 6A	1 " " 115
4 " " 8	1 " " 126
4 " " 10	
2 " " 15	
1 " " 15A	
1 " " 17	
2 " " 19B	
4 " " 20	
3 " " 22	
1 " " 24	
4 " " 35	
36 " " 37	
4 " " 37A	
1 " " 38	
1 " " 44	
4 " " 48A	
1 " " 52	



Model No. 2.25 Ladder on Wheels



Parts required:

6 of No. 1
7 " " 5
4 " " 12
2 " " 16
4 " " 20
40 " " 37
4 " " 38
8 " " 48A
1 " " 52
2 " " 90A


These Models can be built with MECCANO Outfit No. 2 (or No. 1 and No. 1A) and No. 2X

71


Model No. 2.26 Tricycle

Parts required :

4 of No. 2	15 of No. 37
6 " " 5	2 " " 37A
2 " " 10	1 " " 111c
3 " " 11	1 " " 126A
2 " " 12	
1 " " 16	
1 " " 18A	
3 " " 19B	
2 " " 35	



Model No. 2.27 Turntable



Parts required :


4 of No. 1	1 of No. 19B	
2 " " 3	3 " " 22	
8 " " 5	1 " " 24	1 of No. 48
4 " " 8	45 " " 37	7 " " 48A
1 " " 17	4 " " 37A	1 " " 52
1 " " 18A	4 " " 38	2 " " 54
		4 of No. 90A
		2 " " 99
		4 " " 111c

The two sides of the revolving portion are joined in the middle by two pairs of $2\frac{1}{2}$ " strips, each pair being overlapped three holes and bolted to the 3" pulley wheel 1. An axle rod secured in the latter is journaled in the bottom plate 2 and retained in position by a 1" fast pulley wheel beneath the plate.

Model No. 2.29 Motor Truck

Parts required :

2 of No. 2	1 of No. 22	2 of No. 54
2 " " 5	1 " " 24	2 " " 100
2 " " 6A	1 " " 35	1 " " 111c
2 " " 10	23 " " 37	2 " " 126A
1 " " 11	2 " " 37A	
3 " " 16	3 " " 48A	
4 " " 19B	1 " " 52	




A cord passed twice round a 1" fast pulley wheel on the lower end of the steering column is tied to the ends of a $2\frac{1}{2}$ " x $1\frac{1}{2}$ " double angle strip, which is pivoted by means of a bolt and lock-nuts to a double bracket bolted to the lower sector plate. The front axle is journaled in the end holes of the double angle strip.

Model No. 2.28 Baby Chair

Parts required :


8 of No. 2	4 of No. 35
2 " " 3	35 " " 37
2 " " 5	2 " " 37A
6 " " 12	4 " " 38
2 " " 16	8 " " 48A
2 " " 17	4 " " 90A
4 " " 22	1 " " 115



The bolts 1 are all secured pivotally (see S.M. Nos. 262 and 263), and the height of the chair may be adjusted by fitting any hole in the strip 2 over the shank of a bolt that is secured in an angle bracket bolted to the double angle strip 3.

These Models can be built with MECCANO Outfit No. 2 (or No. 1 and No. 1A) and No. 2X

Model No. 2.30 Roundabout



When the crank handle is turned, the drum 2 (formed by butting together two $\frac{3}{4}$ " flanged wheels) turns the 3" pulley wheel 3 by means of an endless cord. The 1" fast pulley wheel 4 similarly turns a second 3" pulley wheel 5 resting on another 3" pulley wheel 6 (see Fig. 2.30A). The end of the axle rod 7 is quite free to revolve in the boss of the lower 3" pulley wheel 6.

Parts required :

13 of No.	2
6 "	5
2 "	8
12 "	12
2 "	12A
2 "	15
1 "	19
4 "	19B
2 "	20
4 "	22
1 "	24
48 "	37
7 "	48A
1 "	52
2 "	54
4 "	90A
2 "	126
2 "	126A





FIG. 2.30A

Model No. 2.31 Scales




Parts required :		
2 of No.	1	2 of No. 18A
1 "	6A	2 "
2 "	8	31 "
2 "	10	4 "
1 "	11	1 "
2 "	12	1 "
2 "	12A	4 "
1 of No.	52	2 "
2 "	54	2 "
2 "	62	2 "
2 "	90A	1 "
1 "	115	2 "
2 "	126A	

Model No. 2.32 Pit Head Gear (Electrically Operated)

Parts
required :


8 of No.	1
8 " "	2
4 " "	5
4 " "	8
2 " "	12
3 " "	16
2 " "	19B
3 " "	22
1 " "	24
2 " "	35
60 " "	37
6 " "	37A
6 " "	38
8 " "	48A
1 " "	52
2 " "	54
2 " "	100
6 " "	111c
2 " "	126

Electric Motor
(included in No. 2x
Outfit only)



Model No. 2.33 Pit Head Gear (Hand Operated)

This is an alternative construction of the base of Model No. 2.32, and shows how the electric motor may be dispensed with if necessary. Two 3" pulley wheels 1 are bolted together by four double brackets to form a drum on which the hoisting cord is wound. The cage is raised or lowered on operation of the handle 2, which is connected to the winding drum by an ordinary belt drive. The cage is prevented from overhauling by a band brake that acts on the groove of a third 3" pulley wheel 3. The brake normally is applied by the weight of the $\frac{1}{2}$ " loose pulley wheel 4, which is secured to the end of a $5\frac{1}{2}$ " strip that is bolted to the crank 5.




Parts required :

6 of No.	1	4 of No.	22	2 of No.	54
7 " "	2	1 " "	23	2 " "	62
3 " "	5	1 " "	24	2 " "	99
4 " "	8	3 " "	35	2 " "	100
4 " "	11	60 " "	37	6 " "	111c
6 " "	12	6 " "	37A	1 " "	115
4 " "	16	8 " "	48A	2 " "	126A
4 " "	19B	1 " "	52		


Model No. 2.34 Acrobat

Parts required :

4 of No.	1	28 of No.	37
2 " "	3	6 " "	37A
5 " "	5	5 " "	38
2 " "	8	1 " "	45
2 " "	10	1 " "	52
1 " "	15	1 " "	54
2 " "	19B	2 " "	62
2 " "	20B	1 " "	115
3 " "	22	2 " "	126



Model No. 2.35 Carrier Tricycle



Each pedal of the tricycle consists of an angle bracket pivotally attached to a crank 1 by means of a bolt and two nuts (see S.M. No. 262). The cranks are secured to a $1\frac{1}{2}$ " axle rod carrying a 1" fast pulley wheel 2. A cord passes round this pulley and around the 3" pulley wheel 3, which is spaced away from the $2\frac{1}{2}$ " strips 4 by a 1" fast pulley wheel 5. The double bracket 6 (Fig. 2.35A) is attached pivotally to the lower framework by a bolt and lock-nuts (S.M. 263).

Parts required:	
12 of No.	2
12 " "	5
2 " "	11
6 " "	12
1 " "	16
1 " "	17
2 " "	18A
3 " "	19B
2 " "	22
45 " "	37
5 " "	37A
8 " "	48A
1 " "	52
2 " "	62
3 " "	111c
2 " "	126A





Fig. 2.35A

Model No. 2.36 Roundabout See-Saw




Parts required:

2 of No.	6A	2 of No.	19B
4 " "	8	1 " "	24
4 " "	10	2 " "	35
4 " "	12	34 " "	37
1 " "	16	4 " "	37A
1 " "	18A	6 " "	38
		1 " "	48
		6 " "	48A
		2 " "	54
		2 " "	90A
		4 " "	111c
		2 " "	126
		2 " "	126A


Model No. 2.37 Gondola

Parts required:

6 of No.	1	5 of No.	12	2 of No.	48A
10 " "	2	1 " "	12A	1 " "	52
1 " "	3	2 " "	16	2 " "	54
12 " "	5	4 " "	20B	4 " "	90A
2 " "	6A	1 " "	24	1 " "	126
4 " "	10	57 " "	37	2 " "	126A
1 " "	11	1 " "	44		




Model No. 2.38 Double Drop Hammer

Parts
required :

4 of No.	2
8 " "	5
2 " "	11
1 " "	16
1 " "	19s
2 " "	22
1 " "	24
6 " "	35
23 " "	37
2 " "	48A
1 " "	52
1 " "	54
4 " "	125

Model No. 2.40 Hay Tedder

Parts
required :

4 of No.	1		
2 " "	3		
9 " "	5		
2 " "	6A		
2 " "	10		
6 " "	12		
1 " "	15A	2 of No.	22
1 " "	16	1 " "	24
2 " "	19	2 " "	35
2 " "	20B	34 " "	37
		6 of No.	37A
		4 " "	38
		2 " "	48A
		1 " "	54
		3 of No.	90A
		6 " "	111c
		2 " "	126
		2 " "	126A




Fig. 2.39A

Model No. 2.39 Derrick


Parts
required :

8 of No.	1
4 " "	2
2 " "	3
8 " "	5
1 " "	6A
3 " "	8
2 " "	10
4 " "	11
6 " "	12
2 " "	12A
3 " "	16
2 " "	17
4 " "	18A

4 of No.	19B	1 of No.	52
4 " "	20	2 " "	54
4 " "	22	1 " "	57
1 " "	23	1 " "	111c
1 " "	24	1 " "	115
11 " "	35	2 " "	125
58 " "	37		
3 " "	37A		
5 " "	38		


The 3" pulley wheel 2, which supports the jib, is free to turn on a short axle rod secured in the boss of the lower 3" pulley wheel 2a. The vertical 12½" strips 13 are bolted at their tops to a double bracket, to the centre hole of which is secured a bolt 14 that is free to turn in the flat trunnion 15.

The swivelling movement of the crane is carried out by turning the handle 1, which simultaneously winds and unwinds the ends of a cord passing round the 3" pulley wheel 2 (see Fig. 2.39A). The cord 12, which is tied to the flat bracket 3 at the head of the jib passes over the 2" rod 4, under a similar rod 5, and between two vertical 2" rods 6, which act as guides, and is finally wound on to the crank handle 7. Hence on operation of the latter the jib is raised or lowered. The cord 8 also passes round the rods 4, 5 and 6, and is wound on to the rod 9. Operation of the handle 10 raises and lowers the hook 11. The cords 8 and 12 are prevented from unwinding by band-and-pulley brakes 16.



These Models can be built with MECCANO Outfit No. 2 (or No. 1 and No. 1A) and No. 2X


Model No. 2.41 Elevator



The construction of this model is fairly clear in the illustration, but it might be pointed out that one side of the framework consists of four 12½" angle girders 1 while the opposite side is composed of four 12½" strips 2.

Parts required :

4 of No.	1
8 "	2
2 "	3
8 "	5
4 "	8
4 "	10
1 "	11
12 "	12
1 "	16
1 "	18A
2 "	19B
1 "	19S
4 "	22
1 "	35
60 "	37
6 "	37A
2 "	38
7 "	48A
1 "	52
2 "	54
1 "	62
2 "	90A
2 "	99
2 "	100
6 "	111c



Model No. 2.42 Fire Escape

Parts required :

2 of No.	1
12 "	2
1 "	3
10 "	5
4 "	8
2 "	10
7 "	12
2 "	12A
4 "	16
4 "	19B
1 "	19S
3 "	22
1 "	23
1 "	24
5 "	35
60 "	37
6 "	37A
9 "	38
1 "	44
6 "	111c
1 "	115
2 "	125




FIG. 2.42A

The ladder is elevated on operation of the crank handle 1, which winds in a cord tied to the double angle strip 2. Angle brackets bolted to the 12½" angle girders 12 are attached pivotally to the 5½" strips 13 by means of bolts and nuts (S.M. 262), and the action of winding in the cord thus causes the ladder to swing upward. It is prevented from falling by the friction of the 1" pulley wheels 10 (Fig. 2.42A), which press against the two sector plates. When the ladder is fully elevated, its lower ends act as brakes to prevent the road wheels from revolving.

A second cord is wound upon the rod 3. One end is then carried over the ½" loose pulley wheel 4 and tied to the 2½" strip 5, the opposite end being carried directly to the same strip and secured to it. When the handle 6 is turned, the two ends of the cord are wound and unwound simultaneously, and the ladder is extended or shortened as required. A permanent brake is provided by a cord passing over the 1" pulley wheel 7 and having both its ends secured to the 2½" strip 8. The strip 8 is bolted firmly to the angle bracket 9 (Fig. 2.42A) and keeps the brake continuously in action.


These Models can be built with MECCANO Outfit No. 2 (or No. 1 and No. 1A) and No. 2X

77

Model No. 2.43 Aeroplane

Parts
required :

7 of No.	1	
2 " "	2	
2 " "	3	
7 " "	5	
2 " "	6A	
8 " "	10	
2 " "	11	
8 " "	12	6 of No. 38
1 " "	16	1 " " 48
2 " "	17	6 " " 48A
2 " "	20	2 " " 54
4 " "	22	1 " " 90A
2 " "	22A	2 " " 99
8 " "	35	2 " " 100
58 " "	37	2 " " 126A



Each engine is represented by a $\frac{3}{4}$ " flanged wheel 1 and a 1" fast pulley wheel secured to a 2" rod journalled in a double bracket 2, which is bolted to the $2\frac{1}{2}$ " \times $\frac{1}{2}$ " vertical double angle strip 3. The $12\frac{1}{2}$ " strips 4 of the fuselage proper are bolted to the two sector plates 5, and also by means of angle brackets to the wings. The tail plane consists of two $5\frac{1}{2}$ " strips to which a similar strip, representing the movable portion of the plane, is attached by means of flat brackets.

Model No. 2.44 Anti-Aircraft Gun

The general construction of the model will be made clear by reference to Figures 2.44A and 2.44B. Rotation of the handle 1 causes the gun to revolve on the 3" pulley wheel 2. The barrel of the gun is so balanced on the axle rod 3 that it tends to fall by its own weight, but is prevented from doing so by a cord 4 tied to the gun close to the breech and wound on the $3\frac{1}{2}$ " rod 5. By turning the pulley wheels 6 the muzzle is raised or allowed to fall.




FIG. 2.44B





FIG. 2.44A

Parts required :

9 of No.	2	1 of No.	19B	4 of No.	48A
1 " "	6A	4 " "	20B	1 " "	52
4 " "	8	4 " "	22	2 " "	54
4 " "	10	1 " "	24	4 " "	90A
3 " "	11	8 " "	35	1 " "	115
5 " "	12	57 " "	37	2 " "	126
4 " "	16	6 " "	38	2 " "	126A
2 " "	17	1 " "	44		




These Models can be built with MECCANO Outfit No. 2 (or No. 1 and No. 1A) and No. 2X

Model No. 2.45 Travelling Jib Crane (Electrically Operated)

Parts required :

10 of No. 1	14 of No. 35	4 of No. 90A
9 " " 2	60 " " 37	5 " " 111c
2 " " 3	6 " " 37A	2 " " 126A
2 " " 5	14 " " 38	
2 " " 6A	1 " " 48	Electric Motor
4 " " 8	7 " " 48A	(included in No. 2x
1 " " 10	1 " " 52	Outfit only)
1 " " 11	1 " " 57	
2 " " 12		
2 " " 15		
1 " " 15A		
2 " " 16		
1 " " 17		
2 " " 18A		
1 " " 19		
4 " " 19B		
4 " " 20		
4 " " 22		
1 " " 23		
1 " " 24		




The swivelling structure is bolted to the 3" pulley wheel 1, which rests on a second 3" pulley bolted to the travelling base. A short rod secured to the boss of the upper pulley is free to rotate in the boss of the lower one. The electric motor 2 controls the hoisting gear and the arrangement of the drive will be clear from the photograph. The jib is luffed on operation of the crank handle 3, the cord of which passes round the axle rod 4 in the jib, then round the rod 5 in the base, back round the rod 4 and is finally secured to a flat bracket on the rod 5.

Model No. 2.46 Travelling Jib Crane (Hand Operated)

This shows a section of Model No. 2.45 fitted for hand operation, thus dispensing with the necessity of the electric motor. In this case the hoisting cord is operated by the hand wheel 6, the rod of which is controlled by a band brake 7. The end hole of the lever of the latter is pivotally mounted on the rod 8. The luffing movement of the jib is effected by the crank handle 9. The operating cord passes round the rod 10 attached to the jib, then round rod 11 in the base of the model, again round rod 10, back round rod 11, and once more round rod 10. The end of the cord is then tied to a flat bracket on the rod 1-1.


Parts required :

10 of No. 1	1 of No. 11	4 of No. 20	7 of No. 48A
11 " " 2	1 " " 15	4 " " 22	1 " " 52
2 " " 3	1 " " 15A	1 " " 23	2 " " 54
6 " " 5	5 " " 16	1 " " 24	1 " " 57
2 " " 6A	2 " " 18A	12 " " 35	1 " " 62
4 " " 3	1 " " 19	57 " " 37	4 " " 90A
3 " " 10	4 " " 19B	1 " " 48	1 " " 111c
	1 of No. 115		



These Models can be built with MECCANO Outfit No. 2 (or No. 1 and No. 1A) and No. 2X


Model No. 2.47 Embossing Machine



Parts
required :

4 of No.	1
8 "	2
2 "	3
2 "	5
4 "	8
3 "	11
2 "	12
1 "	15
3 "	16
1 "	18A
4 "	20B
3 "	22
1 "	24
10 "	35
34 "	37
8 "	38
1 "	45
5 "	48A
1 "	52

Model No. 2.48 Railway Bridge with Signals



Parts
required :

2 of No.	1
10 "	2
2 "	3
8 "	5
4 "	8
2 "	10
3 "	11
2 "	12A
1 "	15A

1 of No.	16
1 "	18A
2 "	20B
2 "	22
1 "	24
3 "	35
60 "	37
3 "	37A
6 "	38
7 "	48A
2 "	62
4 "	90A
2 "	99
2 "	100
3 "	111c
1 "	115
2 "	126





FIG. 2.48A

HOW TO CONTINUE

This completes our examples of models that may be made with Outfits No. 2 and No. 2x. The next models are a little more advanced, requiring a number of extra parts to construct them. The necessary parts are all contained in a No. 2A Accessory Outfit, the price of which will be found in the List at the end of this Manual.

Model No. 3.1 Drilling Machine



Parts required :


2 of No. 4	1 of No. 19B	2 of No. 48A
2 " " 5	2 " " 20B	5 " " 59
2 " " 10	1 " " 21	2 " " 62
2 " " 11	4 " " 22	1 " " 63
1 " " 12	2 " " 22A	1 " " 111
1 " " 15	1 " " 24	1 " " 115
2 " " 15A	2 " " 35	3 " " 125
2 " " 17	21 " " 37	2 " " 126A
	1 " " 46	

Model No. 3.2 Strip-Bending Machine

This model represents a device for bending bars or rods of metal to circular form, and may be put to practical purpose in shaping strips of tin or similar material. A loose pulley 1 is spaced by a collar and washers in the centre of the short rod 2 journalled in a $1\frac{1}{2}$ " strip 3. The latter is secured to the end of a $\frac{3}{4}$ " bolt 4 and spaced away from the 3" pulley 5 by means of a number of washers. The opposite end of the rod is supported by a $5\frac{1}{2}$ " strip 6. The handle 7 is secured to a $3\frac{1}{2}$ " rod carrying a $\frac{1}{2}$ " pinion 8. This engages with a 57-teeth gear wheel 9 mounted on another $3\frac{1}{2}$ " rod which is free to revolve in the boss of the wheel 5. The gear wheel 9 carries a 3" strip 10 forming one of the bearings for a short rod carrying a second 1" loose pulley 11. The latter is also spaced by means of a collar and washers so that it lies immediately above the groove of the pulley wheel 5. The material to be shaped is passed between the two loose pulleys at the top of the wheel 5, and on rotation of the handle 7 the arm 10 is caused to move downward, so forcing the object to the same curvature as the circumference of the wheel.

Parts required :


1 of No. 2	
2 " " 3	
1 " " 4	
1 " " 5	
1 " " 6A	
2 " " 16	
1 " " 17	
2 " " 18B	
1 " " 19B	
2 " " 22A	
1 " " 26	
1 " " 27A	



Parts required : (continued)

6 of No. 35	
10 " " 37	
10 " " 38	
1 " " 52	
4 " " 59	
1 " " 62	
1 " " 111	
1 " " 115	
2 " " 126A	

Model No. 3.3 Boring Machine




Parts required :

3 of No. 2	4 of No. 20B	2 of No. 48B
6 " " 3	1 " " 22	1 " " 52
5 " " 5	2 " " 22A	1 " " 53
2 " " 8	3 " " 35	4 " " 59
2 " " 11	38 " " 37	1 " " 62
2 " " 15	1 " " 46	1 " " 63
2 " " 16	2 " " 48A	

Model No. 3.4 Fire Escape

The main frame 1 is pivotally connected to the running truck 2 about the rod 3. Ordinarily the frame 1 rests on the running truck 2 when the escape is being transported. In order to raise the main frame about the pivot rod 3 the handle 4 winds up the cord 5 the outer end of which is connected to the running truck axle. To raise or lower the ladder 6 the handle 7 is turned in one or other direction, the cord 8 passing over the pulleys 9 and being connected to the sliding ladder.




Parts required:

2 of No.	1
4 " "	2
1 " "	3
6 " "	5
4 " "	8
3 " "	11
10 " "	12
2 " "	12A
1 " "	15A
4 " "	16
1 " "	18A
2 " "	19
4 " "	20B
4 " "	22
1 " "	22A
7 " "	35
45 " "	37
1 " "	44
3 " "	48A
2 " "	54
3 " "	59
1 " "	115
4 " "	125
1 " "	147
1 " "	148

Model No. 3.5 Crossbow

Parts required:


5 of No.	1	1 of No.	17
2 " "	2	1 " "	18A
1 " "	3	2 " "	36
4 " "	5	25 " "	37
2 " "	8	1 " "	38
2 " "	11	1 " "	48A
1 " "	12	1 " "	63




Model No. 3.6 Coffee Grinder

Parts required:

2 of No.	2
6 " "	3
2 " "	4
2 " "	16
1 " "	19B
1 " "	26
1 " "	27A
16 " "	37
2 " "	54
3 " "	59
1 " "	115
4 " "	125



Model No. 3.7 Swing




Parts required :

7 of No. 1	56 of No. 37
10 " " 2	4 " " 37A
8 " " 5	6 " " 48A
8 " " 8	1 " " 48B
1 " " 10	2 " " 59
2 " " 15	2 " " 62
1 " " 19B	4 " " 90A
1 " " 24	2 " " 99
2 " " 35	2 " " 111c
1 of No. 115	

Model No. 3.8 Newton's Disc

This model demonstrates that the colours of the spectrum, which are most simply produced by directing a ray of white light through a prism, can be re-combined to form white light. The cardboard disc is divided into equal sectors, and the seven colours of the spectrum—red, orange, yellow, green, blue, indigo, and violet—are painted on separate sectors. If the disc is rotated at a high speed by means of the hand wheel and the gears shown, the disc appears to be of a greyish-white colour.




Parts required :

2 of No. 15	
1 " " 19B	
1 " " 24	
1 " " 26	
1 " " 27A	
10 " " 37	
1 " " 38	
2 " " 52	
2 " " 53	
2 " " 59	
1 " " 115	

Model No. 3.9 Lawn Mower

The grass box 1 is retained in position by two flat brackets bolted to the $2\frac{1}{2} \times \frac{1}{2}$ " double angle strip 2 but spaced from it by a washer on each bolt. The edge of the double angle strip 3 may be slipped in the space between the double angle strip 2 and the flat brackets, one of which is shown at 4.



Parts required :

2 of No. 2	2 of No. 35
2 " " 5	26 " " 37
4 " " 10	6 " " 38
2 " " 11	6 " " 48A
2 " " 16	2 " " 90
4 " " 22	4 " " 90A

These Models can be built with MECCANO Outfit No. 3 (or No. 2 and No. 2A) and No. 3X

Model No. 3.10 Horse Sleigh




Parts required:

3 of No. 2	13 of No. 37	1 of No. 57
4 " " 5	1 " " 48A	2 " " 90
1 " " 23	1 " " 52	1 " " 126A

Model No. 3.12 Drafting Machine

Parts required:


4 of No. 1	1 of No. 24
3 " " 2	15 " " 37
1 " " 4	1 " " 52
2 " " 5	



Model No. 3.11 Demonstration Scales


Parts required:

3 of No. 1
4 " " 2
6 " " 3
1 " " 4
2 " " 5
8 " " 8
4 " " 11
6 " " 12
2 " " 12A
2 " " 17
1 " " 18A
1 " " 22
2 " " 35
58 " " 37
1 " " 44
2 " " 52
2 " " 53
2 " " 59
2 " " 62
4 " " 90
1 " " 125
3 " " 126A



The only feature of this model which needs description is the standard, which is built up of two angle girders 1 bolted to the base 2 by angle brackets and spaced apart at the top by a $2\frac{1}{2}$ " strip obliquely disposed. The balance lever 3 is pivotally carried in curved strips 4 bolted to the top of two angle girders 5 sliding between the girders 1. The girders 5 are themselves bolted together and in order to guide them as they slide vertically flat trunnions 6 are bolted at the front and rear. The balance is raised by depressing the lever 8 pivoted at 9 and pivotally connected at 11 to the vertically sliding girders 5. The indicator 10 is bolted to a crank at the rear, the boss of which is fitted on the pivot rod 11. The connections at 12 are lock-nutted to allow free action.

Model No. 3.13 Pile Driver




On moving the hand lever 6 to the right a $\frac{1}{2}$ " pinion on the hoisting shaft is brought into engagement with the 57-teeth gear wheel 1 on the driving shaft and the ram 4 is raised. The hoisting cord 2 is tied to an angle bracket 3, which lodges under another angle bracket 4 bolted to the ram. The latter may be dropped whenever required by jerking the cord 5, thereby releasing the brackets 3. The strips 7 are duplicated, and the girders 8 slide between their ends.

Parts required :

6 of No.	1	3 of No.	16
3 " "	2	1 " "	19B
2 " "	3	3 " "	20B
6 " "	5	1 " "	21
2 " "	6A	2 " "	22
7 " "	8	1 " "	26
8 " "	12	1 " "	27A
1 " "	15A	1 " "	32
		2 " "	35
		60 " "	37
		2 " "	37A
		1 " "	38
		1 " "	45
		1 " "	46
		1 " "	48A
		2 " "	48B
		2 " "	52
		2 " "	53
		4 " "	59
		1 " "	90A
		1 " "	111C
		1 " "	115
		2 " "	126
		2 " "	126A

Model No. 3.14 Hand Trolley




Parts required :

4 of No.	2	1 of No.	24
3 " "	3	1 " "	26
2 " "	5	1 " "	27A
4 " "	8	6 " "	35
8 " "	10	40 " "	37
4 " "	11	1 " "	45
2 " "	15A	1 " "	48B
4 " "	16	2 " "	52
1 " "	18A	3 " "	59
4 " "	19B	4 " "	90A
2 " "	22	2 " "	125
2 of No. 126A			

The connecting arm is pivoted at its lower end to the bush wheel and at its upper end to the hand lever a bolt and two nuts being used to pivot the arm in each case. The drive is transmitted from the 1" pulley wheel on the shaft of the bush wheel to a similar pulley on the axle of the road wheels by means of a crossed belt. The $1\frac{1}{2}$ " rod carrying the bush wheel is journaled in a $3\frac{1}{2}$ " strip fastened to the side angle girder, and also in a double bent strip secured to the inside of the girder.

Model No. 3.15 Tank Wagon



Parts required :


1 of No.	2
1 " "	6A
1 " "	12
2 " "	16
4 " "	19B
9 " "	37

1 of No.	52
2 " "	126
1 " "	126A
1 " "	162

These Models can be built with MECCANO Outfit No. 3 (or No. 2 and No. 2A) and No. 3X

85

Model No. 3.16 Actuated See-Saw



Parts required :


1 of No. 3	4 of No. 22	2 of No. 52
6 " " 5	1 " " 24	2 " " 53
8 " " 8	1 " " 26	3 " " 59
4 " " 12	1 " " 27A	2 " " 62
2 " " 15	2 " " 35	2 " " 90A
3 " " 15A	43 " " 37	1 " " 111c
4 " " 19B	2 " " 37A	1 " " 115
	2 " " 48B	

The model is actuated by the motion of one pair of travelling wheels. The axle to which these wheels are secured carries two 1" fast pulley wheels, which are connected by endless cords to similar pulleys on the same rod as a $\frac{1}{2}$ " pinion wheel. This $\frac{1}{2}$ " pinion meshes with a 57-teeth gear wheel secured to the rod of a bush wheel, and the latter is connected by means of a $5\frac{1}{2}$ " strip to an extended crank (a $2\frac{1}{2}$ " strip and a crank bolted together) secured to the pivotal rod of the see-saw.

Model No. 3.17 Toboggan

Parts required :


6 of No. 5	
22 " " 37	
5 " " 48A	
1 " " 52	
2 " " 90	
1 " " 90A	



Model No. 3.18 The Meccangaroo

When placed upon an incline the "Meccangaroo" will "walk" with a quaint action. The positions of the various strips in relation to the body should be reproduced as accurately as possible, for the successful working of the model depends upon them.

The animal rocks about a short rod secured between the rocker-frame which does duty as "legs." This frame consists of two $3\frac{1}{2}$ " strips 3 bolted at their upper ends to cranks in which the short rod is secured, and at their lower ends to two $2\frac{1}{2}$ " large radius curved strips 4, which are connected together at their ends by $1\frac{1}{2}$ " strips 5 and braced to the strips 3 by $2\frac{1}{2}$ " strips.



Parts required :


8 of No. 2	
2 " " 3	
8 " " 5	
2 " " 6A	
6 " " 10	

Parts required :
(continued)

2 of No. 11	
4 " " 12	
48 " " 37	
2 " " 52	
2 " " 62	
2 " " 90	

These Models can be built with MECCANO Outfit No. 3 (or No. 2 and No. 2A) and No. 3X

Model No. 3.19 Ice Boat




Parts required :

3 of No.	1	1 of No.	22
2 "	2	1 "	24
2 "	3	36 "	37
3 "	5	1 "	52
2 "	8	1 "	54
2 "	12	1 "	59
3 "	12A	1 "	62
1 "	17	1 "	63
1 "	19s	2 "	126A

Parts
required :

2 of No.	2
3 "	5
3 "	11
1 "	17
1 "	22A
1 "	27A
9 "	37
2 "	59

Model No. 3.20 Pastry Designer




Model No. 3.21 Steam Road Roller

Parts required :

2 of No.	2	3 of No.	22
7 "	5	1 "	23
2 "	11	1 "	24
1 "	12	57 "	37
2 "	12A	11 "	38
3 "	16	1 "	45
1 "	17	8 "	48A
4 "	19B	1 "	48B
1 "	21	3 "	53


Parts
required :
(continued)

4 of No.	59
1 "	62
4 "	90A
1 "	126
1 "	126A
1 "	162
1 "	164



Model No. 3.22 Paddle Boat

Parts required :		
6 of No. 1	4 of No. 35	1 of No. 59
4 " " 2	94 " " 37	2 " " 62
6 " " 3	3 " " 37A	1 " " 63
2 " " 4	6 " " 38	2 " " 99
10 " " 5	2 " " 45	2 " " 100
2 " " 6A	1 " " 46	1 " " 111
14 " " 12	2 " " 48	1 " " 116A
2 " " 15	10 " " 48A	1 " " 126A
2 " " 15A	2 " " 52	1 " " 138A
4 " " 16	2 " " 53	1 " " 166
2 " " 18A		
4 " " 19B		
4 " " 20B		
4 " " 22		
1 " " 24		



The paddle-wheels are secured to a crankshaft (see Fig. 3.22A) consisting of two $3\frac{1}{2}$ " axle rods 1, two cranks 2, and a $\frac{3}{4}$ " bolt 3 secured to the central holes of the cranks. The two oscillating cylinders 4 are built up from two $\frac{3}{4}$ " flanged wheels and a pair of sleeve pieces, the latter being bolted to the $2\frac{1}{2} \times \frac{1}{2}$ " double angle strips 5, which are free to turn on rods 6. The ends of the 5" piston rods are secured in the bosses of two small fork pieces 7, which pivot about the $\frac{3}{4}$ " bolt 3 of the crankshaft. As the model runs along the ground, the 3" pulley wheels 8 secured to the rods 1 are rotated by endless cords from the 1" fast pulley wheels 9, while the cylinders 4 oscillate and appear to be actually operating the paddle-wheels.





FIG. 3.22A

Model No. 3.23
Auto Dial Press

Parts required :		
4 of No. 2	22 of No. 37	
5 " " 5	5 " " 48A	
2 " " 15	1 " " 52	
1 " " 16	3 " " 59	
1 " " 17	1 " " 63	
1 " " 18A	4 " " 90A	
1 " " 19B	1 " " 115	
4 " " 20B		
1 " " 21		
1 " " 22		
1 " " 24		
1 " " 26		
1 " " 32		



These Models can be built with MECCANO Outfit No. 3 (or No. 2 and No. 2A) and No. 3X

Model No. 3.24 Scarifier

Parts required:


7 of No.	2	1 of No.	18A
1 " "	3	2 " "	22
4 " "	5	29 " "	37
1 " "	10	2 " "	38
1 " "	11	2 " "	90
11 " "	12	1 " "	126A



Model No. 3.26 Electric Tramcar

Parts required:


3 of No.	1	1 of No.	18A	2 of No.	53
14 " "	2	4 " "	20	2 " "	54
12 " "	5	3 " "	22	1 " "	59
4 " "	10	1 " "	24	2 " "	62
4 " "	12	1 " "	26	1 " "	63
4 " "	12A	2 " "	35	2 " "	100
1 " "	15	87 " "	37	1 " "	111c
2 " "	16	1 " "	43	1 " "	115
2 " "	17	2 " "	48	4 " "	125
		4 " "	48A	1 " "	116A
		2 " "	52	1 " "	147B



Model No. 3.25 Pit Head Gear

Parts required:

10 of No.	1	6 of No.	35
9 " "	2	74 " "	37
4 " "	3	1 " "	48B
2 " "	4	2 " "	52
8 " "	8	3 " "	53
10 " "	12	2 " "	54
2 " "	15	4 " "	59
3 " "	15A	2 " "	100
1 " "	16		
1 " "	17		
1 " "	19		
1 " "	19B		
1 " "	26		
1 " "	27A		




This model will be improved by the addition of a lever and strap friction brake, or other controlling device, which may be fitted to the further end of the driven shaft (see S.M. No. 81).

Model No. 3.27 Tower Wagon

When operated the handle 1 winds in the cord 2, which passes over a 1" fast pulley wheel 3 and is tied to the rod 4. The upper part of the tower is thus raised or lowered as required, being guided by the $\frac{3}{4}$ " flanged wheels 5 and two pairs of reversed angle brackets 6. The steering cords 7 are tied to the 57-teeth gear wheel 8 and to the end of a $2\frac{1}{2}$ " \times $\frac{1}{2}$ " double angle strip bolted to a double bent strip, which is pivoted to the sector plate 9. The front axle is journaled through the ends of the double angle strip.

Parts required:

4 of No. 1	2 of No. 54
2 " " 4	3 " " 59
6 " " 5	4 " " 90A
2 " " 6A	1 " " 98
8 " " 8	2 " " 100
8 " " 12	1 " " 111c
1 " " 15	1 " " 115
3 " " 15A	4 " " 125
4 " " 16	
1 " " 17	
4 " " 19B	
4 " " 20	
1 " " 21	
2 " " 22	
1 " " 24	
1 " " 26	
1 " " 27A	
1 " " 32	
3 " " 35	
84 " " 37	
2 " " 37A	
1 " " 45	
8 " " 48A	
2 " " 52	
1 " " 53	




Model No. 3.28

Two-Cylinder Vertical Steam Engine

Parts required:

2 of No. 3
2 " " 8
2 " " 11
3 " " 12
4 " " 16
2 " " 19B
4 " " 20
1 " " 22
1 " " 27A
40 " " 37
7 " " 38
2 " " 48B
2 " " 52
3 " " 53
3 " " 59
2 " " 115
2 " " 125
1 " " 162
2 " " 163
1 " " 164
2 " " 165

Electric Motor
(included in No. 3x
Outfit only)



These Models can be built with MECCANO Outfit No. 3 (or No. 2 and No. 2A) and No. 3X


Model No. 3.29 Swinging Cot



Parts required :

2 of No. 1	6 of No. 37A
18 " " 2	8 " " 38
6 " " 3	1 " " 45
2 " " 5	3 " " 48A
8 " " 8	1 " " 52
3 " " 12	4 " " 59
1 " " 15	2 " " 62
1 " " 15A	1 " " 63
3 " " 16	1 " " 98
1 " " 22	2 " " 99c
10 " " 35	2 " " 100
68 " " 37	4 " " 111


Model No. 3.30 Swing Boat



Model No. 3.31 Lace Jennier

Parts required :


6 of No. 2	28 of No. 37
2 " " 8	1 " " 37A
4 " " 11	4 " " 38
2 " " 15	2 " " 48B
1 " " 19E	2 " " 52
1 " " 24	2 " " 53
1 " " 26	2 " " 59
1 " " 27A	1 " " 115



Parts required :

2 of No. 1	2 of No. 22A
17 " " 2	64 " " 37
4 " " 5	2 " " 37A
6 " " 8	2 " " 45
8 " " 12	4 " " 90A
2 " " 17	2 " " 99
2 " " 19B	2 " " 100
2 " " 22	2 " " 111c

Model No. 3.32 Railway Gauge



Parts
required :

2 of No.	2
1 " "	6A
2 " "	8
2 " "	11
2 " "	12
25 " "	37
1 " "	53
2 " "	90A
2 " "	126
2 " "	126A


Model No. 3.33 Auto Swing Boat

The connecting strip 1 is attached pivotally at one end to a threaded pin secured to the bush wheel 2 on the driving spindle of the motor, and at the other end by means of bolt and lock-nuts to a crank 3 mounted on the shaft 4, which operates the swing boat.


Parts required :

3 of No.	1	1 of No.	10	86 of No.	37	2 of No.	90A
16 " "	2	12 " "	12	2 " "	37A	2 " "	99
6 " "	3	2 " "	15	1 " "	59	2 " "	100
8 " "	5	1 " "	24	2 " "	62	1 " "	111c
8 " "	8	2 " "	35	1 " "	63	1 " "	115
2 of No. 126A							

Clockwork Motor (not included in Outfit)




Model No. 3.34 Scales



Parts required :

10 of No.	2	2 of No.	48A
1 " "	3	1 " "	48B
2 " "	5	2 " "	52
5 " "	8	1 " "	53
7 " "	10	2 " "	54
5 " "	12	4 " "	59
2 " "	15A	2 " "	62
4 " "	19B	2 " "	100
67 " "	37	2 " "	126
2 " "	38	2 " "	126A



Model No. 3.35 Lathe

The arrangement of the treadle is shown in detail in Fig. 3.35A. The crank 1 is provided with a flat bracket, the round hole of which coincides with the elongated hole of the crank, and receives the short rod 2. The crank 1 is free to turn about a threaded pin 3, secured to the 3" pulley wheel 4, and once the latter is set in motion it can be kept in rotation by working the treadle 5. The strips 6 of the saddle (Fig. 3.35) are duplicated and their ends form slots to receive the flanges of the angle girders 7. The hand wheel 8 is a dummy one, but if desired it may be arranged to operate the saddle by an endless rope device.

Parts required:

3 of No. 3	2 of No. 16	3 of No. 35	4 of No. 59
10 " " 5	1 " " 17	44 " " 37	1 " " 62
2 " " 8	1 " " 18A	2 " " 37A	4 " " 90A
2 " " 11	2 " " 19B	4 " " 38	1 " " 111c
4 " " 12	1 " " 21	1 " " 46	1 " " 115
2 " " 12A	2 " " 22	2 " " 48B	
2 " " 15A	1 " " 24	3 " " 53	

Model No. 3.36 Vertical Steam Engine

Parts required:

2 of No. 12	1 of No. 45
1 " " 16	1 " " 52
1 " " 17	1 " " 59
1 " " 19B	1 " " 115
2 " " 20B	1 " " 162
3 " " 22	1 " " 163
1 " " 24	1 " " 164
9 " " 37	1 " " 166
2 " " 38	







FIG. 3.35A

Model No. 3.37 Horizontal Engine

This model forms an interesting example of the use of the Meccano boiler, sleeve piece and other new parts. The $2\frac{1}{2}$ " strip 1, forming the connecting rod, is attached to the $1\frac{1}{2}$ " pulley wheel by means of a threaded pin. The latter is fastened in one hole of the $1\frac{1}{2}$ " pulley wheel, and two washers are placed upon it between the strip 1 and the wheel. The connecting rod is held in place by a collar locked to the end of the threaded pin. The boiler is attached to the framework by means of two $2\frac{1}{2}$ " \times $\frac{1}{2}$ " double angle strips attached by their centre holes to the side of the boiler opposite the chimney. When the boiler is placed in the position shown, the whole is secured by bolting the double angle strips to the side flanged plates.



Parts required:		
1 of No. 5	3 of No. 22	1 of No. 115
2 " " 12A	1 " " 35	1 " " 116
2 " " 15A	25 " " 37	2 " " 126
1 " " 16	7 " " 38	1 " " 126A
1 " " 19B	1 " " 45	1 " " 162
1 " " 19S	1 " " 48	1 " " 163
4 " " 20B	4 " " 48A	1 " " 164
1 " " 21	2 " " 52	1 " " 166
	4 " " 59	



Model No. 3.38 Rattle

Parts required:

4 of No. 2	6 of No. 37
2 " " 12	1 " " 48B
2 " " 15	4 " " 59
2 " " 26	1 " " 63

Model No. 3.39 Oil Cake Chopper

Parts required:

4 of No. 3	1 of No. 52
6 " " 10	2 " " 53
1 " " 15	2 " " 54
1 " " 19B	1 " " 59
4 " " 22	2 " " 90A
24 " " 37	1 " " 115
2 " " 48B	2 " " 125

Fig. 3.39A, shows the hand wheel and shaft removed from the model. It will be seen that the chopping mechanism is represented by flat brackets clamped between two pairs of 1" fixed pulley wheels.




FIG. 3.39A



Model No. 3.40 Railway Wagon Swivel Crane




FIG. 3.40A


The flanges of the sector plates 1 are bolted to the 3" pulley wheel 2 upon which the crane swivels, and the spindle of the pulley wheel is rotated by the worm 3 engaging the gear wheel 4 (Fig. 3.40A). In order to bring the worm centrally over the teeth of the gear wheel 4, washers are placed beneath the angle brackets 5 in which the spindle of the worm is journalled.

Parts required :

4 of No. 1	4 of No. 20B	2 of No. 54
6 " " 2	4 " " 22	1 " " 57
1 " " 3	1 " " 22A	3 " " 59
2 " " 5	1 " " 24	1 " " 63
4 " " 8	1 " " 27A	1 " " 115
1 " " 11	1 " " 32	4 " " 125
14 " " 12	3 " " 35	4 " " 126A
2 " " 15	70 " " 37	
1 " " 15A	2 " " 38	
2 " " 17	2 " " 48A	
1 " " 19	2 " " 52	
1 " " 19B	2 " " 53	


Model No. 3.41 Wire Rope Maker

The strands are twisted from both ends by the handles 1 and 2 of the fixed parts. The handle 1 rotates through a large gear wheel 3 two pinions 4 on the rods 5 carrying cranks to which the strands are attached. The other ends of the strands are connected to a double bracket 6 on a bush wheel which is rotated in the opposite direction by a crank handle 2. The carriage 7 runs on rails and the vertical rod 8 is kept just at the formation of the twisted rope and so controls the tightness of the twist.



Parts required for Wire Rope Maker :


6 of No. 2	2 of No. 15	1 of No. 27A	2 of No. 52
1 " " 3	3 " " 15A	3 " " 35	3 " " 53
2 " " 5	2 " " 19S	50 " " 37	4 " " 59
2 " " 8	4 " " 20B	1 " " 45	2 " " 62A
3 " " 11	1 " " 24	2 " " 48A	4 " " 126
12 " " 12	2 " " 26		



Model No. 3.42 Letter Balance

Parts required:

4 of No. 2	2 of No. 18A	1 of No. 53
2 " " 3	2 " " 20B	4 " " 59
5 " " 5	2 " " 22A	1 " " 62
2 " " 10	4 " " 35	1 " " 63
1 " " 11	37 " " 37	2 " " 90A
4 " " 12	6 " " 37A	2 " " 111
2 " " 12A	2 " " 48A	4 " " 111c
1 " " 15	1 " " 48B	2 " " 125
2 " " 17	1 " " 52	2 " " 126A




Parts

required:

2 of No. 1	8 " " 2
1 " " 3	6 " " 5
1 " " 6A	1 " " 8
2 " " 11	2 " " 12
16 " " 12	2 " " 12A
2 " " 15	1 " " 15A
4 " " 19B	2 " " 20B
1 " " 22	1 " " 24
1 " " 35	4 " " 37
60 " " 37	1 " " 37A
1 " " 38	1 " " 48
1 " " 48A	2 " " 48B
1 " " 52	2 " " 53
2 " " 54	2 " " 59
4 " " 90A	3 " " 98
1 " " 111c	2 " " 125
4 " " 126	2 " " 162

Model No. 3.43 Tank Lorry



It should be noted that the steering cord is given a complete turn around the two $\frac{3}{4}$ " flanged wheels 1 to prevent slipping. The steering column 2 is journalled in the end of a $1\frac{1}{2}$ " strip, the other end of which is bolted to a $2\frac{1}{2}$ " \times $\frac{1}{2}$ " double angle strip secured between the two sector plates 3. The front road wheels are secured to a 5" rod that is journalled in the end holes of a $3\frac{1}{2}$ " \times $\frac{1}{2}$ " double angle strip. The ends of the steering cord are tied to this strip, which is pivoted by means of a bolt and lock-nuts (S.M. 263) to the central hole of a $1\frac{1}{2}$ " \times $\frac{1}{2}$ " double angle strip. The latter is bolted between a pair of Trunnions attached to the underside of the $5\frac{1}{2}$ " \times $2\frac{1}{2}$ " flanged plate. The tank 4 merely rests on the $5\frac{1}{2}$ " strips 5.





FIG. 3.43A


Model No. 3.44 Horizontal Engine

Parts required :

5 of No. 5	30 of No. 37
2 " " 8	3 " " 48A
2 " " 12	2 " " 48B
3 " " 15A	2 " " 52
1 " " 19S	3 " " 53
2 " " 19B	3 " " 59
4 " " 20B	1 " " 116
1 " " 21	2 " " 126
1 " " 22	1 " " 162
2 " " 35	1 " " 163
1 of No. 165	



Model No. 3.46 Flax Cleaner



The six $3\frac{1}{2}$ " strips forming the rotating frame are fastened to a bush wheel that in turn is attached to the rod 1. The $3\frac{1}{2}$ " strips are braced by six $2\frac{1}{2}$ " strips. The drive is transmitted from rod 2 to rod 1 by means of endless cords. Two separate cords are used in order to secure a more positive drive.

Parts required :


4 of No. 2	1 of No. 26
6 " " 3	1 " " 27A
6 " " 5	1 " " 35
2 " " 8	34 " " 37
2 " " 12	3 " " 38
3 " " 15A	2 " " 52
1 " " 19B	3 " " 53
4 " " 22	4 " " 59
1 " " 24	1 " " 115

Model No. 3.45 Lawn Marker

The small roller, which consists of two $\frac{3}{4}$ " flanged wheels secured to a short rod, rest on the edges of the two 3" pulley wheels. In actual practice the container is filled with whitewash, in which the inner wheel is partially immersed, and the mixture is transferred via the roller to the outer wheel, which does the actual marking.

Parts required :


2 of No. 1	4
2 " " 4	5
2 " " 5	12
2 " " 12	12A
2 " " 16	16
2 " " 17	19B
2 " " 20	20
2 " " 22	22
21 " " 37	37
1 " " 38	38
2 " " 48A	48A
2 " " 53	53
4 " " 59	59
2 " " 90A	90A



These Models can be built with MECCANO Outfit No. 3 (or No. 2 and No. 2A) and No. 3X

97

Model No. 3.47 Roundabout




Parts required :	2 of No. 8	1 of No. 16	1 of No. 32
			2 " " 35
4 of No. 1	1 " " 12	2 " " 19B	36 " " 37
			8 " " 48A
12 " " 2	3 " " 15A	1 " " 24	2 " " 52
			3 " " 53
		2 " " 26	2 " " 59
		1 " " 27A	1 " " 115
			2 " " 126A

Model No. 3.48 Drop the Nigger


The sector plate 1 is a target, which, when hit, allows the nigger to be dropped. The plate 1 is carried on the strip 2 pivoted at 5, and the weight of the nigger supported on another sector plate 4 pivoted at 5 by means of the cord 6 keeps the lower end of the strip 2 hard against a short rod 7 pivoted at 8. When the target is hit and knocked back the rod 7 is released and falls about its pivot, allowing the sector plate 4 with the nigger to drop.

Parts
required :

1 of No. 1	3
6 " " "	8
8 " " "	12
1 " " "	15A
3 " " "	17
2 " " "	22
1 " " "	35
6 " " "	37
33 " " "	44
1 " " "	48A
4 " " "	53
2 " " "	54
2 " " "	59
3 " " "	63
1 " " "	



Model No. 3.49 Kinetograph



Most Meccano boys probably are aware of the principles of the Kinetograph, but for the benefit of those who have not seen one in action, we may mention that it is a device which imparts an appearance of animation to a series of pictures, each differing slightly from the other and passed in rapid succession before the eyes. In this respect it resembles the remarkable principle upon which the modern cinematograph is based.

In constructing the Meccano model the following details will prove useful:—The drum consists of a $12\frac{1}{2}$ " strip bent to form a circle, with its ends overlapping one hole, and bolted to eight vertical $5\frac{1}{2}$ " strips forming the sides. Two pairs of opposite $5\frac{1}{2}$ " strips are connected by $3\frac{1}{2}$ " strips and angle brackets bolted in the third holes from their lower ends. The $3\frac{1}{2}$ " strips cross at right angles to one another and are bolted in the centre to a bush wheel, in the boss of which is secured a short rod forming the pivot of the revolving drum. This rod is journaled in a double bent strip bolted to a $2\frac{1}{2}$ " \times 1 " double angle strip 2. This, in turn, is secured to the base of the model by two 1 " \times 1 " angle brackets 3. A further bearing for the short rod consists of a crank bolted in the base of the model.

The drum is rotated from the crank handle 4, on which is mounted a $\frac{1}{2}$ " pinion engaging a 57-teeth gear wheel 5 secured to a $3\frac{1}{2}$ " rod carrying a pulley wheel 6. The latter is connected by means of a cord 7 to a similar wheel nipped to the vertical spindle of the drum. Bearings are provided for the inner ends of the crank handle and $3\frac{1}{2}$ " rod by a double angle strip bolted between the plate 8 and $5\frac{1}{2}$ " strip 9. The sighting box 10 is built up from a framework of strips and is secured by means of a crank 11 to a short vertical rod rigidly mounted in the boss of the $1\frac{1}{2}$ " pulley 12. The four sides of the framework 10 are covered with some black material; stiff black paper suitable for this purpose may be obtained from any stationers. The drum is enclosed in the same way, but the covering paper should be cut in a strip measuring $12\frac{1}{2}$ " \times $4\frac{1}{2}$ " and pierced with slots spaced $1\frac{1}{4}$ " apart (from centre to centre) so that they fall exactly between the upright $5\frac{1}{2}$ " strips. The slots should measure $1\frac{1}{4}$ " \times $\frac{1}{2}$ ".

The type of drawing suitable for use in this model is shown in Fig. 3.49A, and the dimensions indicated therein should be followed carefully. No doubt Meccano boys will be able to devise numerous amusing pictures of a similar kind for themselves. The strip of stout white paper carrying the sketches is inserted in the bottom of the drum, as indicated at 13. The model is now ready for operation. Placing the frame 10 over the eyes, the line of vision is directed through the narrow end, where the strips are held apart by means of double brackets, and through the slots in the drum. The latter should be rotated rapidly by operating the handle 4, and as it revolves, the little dog shown in Fig. 3.49A will be seen jumping over the fence with a most realistic and amusing action.

Parts required:

1 of No. 1	1 of No. 15A	12 of No. 38
17 " " 2	2 " " 16	1 " " 45
6 " " 3	1 " " 19s	1 " " 46
1 " " 4	1 " " 21	1 " " 48A
3 " " 5	2 " " 22	2 " " 52
4 " " 8	1 " " 24	3 " " 53
2 " " 11	1 " " 26	4 " " 59
12 " " 12	1 " " 27A	2 " " 62
2 " " 12A	60 " " 37	





Fig. 3.49A

Model No. 3.50 Railway Breakdown Crane



The pivotal arm 1 consists of a 5" rod, to the ends of which are secured a small and a large fork piece, the latter being pivoted to the double bracket 2 by means of a $\frac{3}{4}$ " bolt. The hoisting cord controlling the hook 3 passes under a $3\frac{1}{2}$ " rod 4 and is wound on a crank handle 5. The cord 6, which raises the jib, is operated by a second crank handle 7. It passes over the 1" loose pulley wheel 8, round the $\frac{1}{2}$ " loose pulley 9 (which is mounted on a pivot bolt), and is then led back again and tied to a flat bracket on the $1\frac{1}{2}$ " rod that carries the pulley 8. Each crank handle 5, 7 is provided with a permanent band-and-pulley brake to prevent the jib or the load on the hook 3 from falling when the handles are released. The method of rotating the crane about its pivot is as follows:


The hand wheel consisting of a bush wheel fitted with a threaded pin is fastened to a $3\frac{1}{2}$ " rod journaled in two $1" \times 1"$ angle brackets which are bolted to the $2\frac{1}{2}" \times 3\frac{1}{2}"$ flanged plate. This rod carries a worm wheel that meshes with a 57-teeth gear wheel fastened to a 2" rod. The support for this rod is formed by a double bent strip. Connection between this rod and the body of the crane is made by means of a 1" pulley wheel, a 3" pulley wheel fastened to the base of the crane, and a crossed belt joining these two wheels. On rotation of the hand wheel the jib of the crane is, therefore, slowly rotated.

Parts required:

2 of No. 1	1 of No. 19B	1 of No. 45	1 of No. 115
11 " " 2	4 " " 20B	1 " " 46	1 " " 116
2 " " 3	1 " " 21	2 " " 48B	1 " " 116A
2 " " 4	4 " " 22	3 " " 53	4 " " 125
12 " " 5	2 " " 22A	2 " " 54	2 " " 126A
6 " " 8	1 " " 23	1 " " 57	1 " " 147B
10 " " 10	1 " " 24	3 " " 59	
2 " " 11	1 " " 27A	4 " " 90A	
3 " " 12	1 " " 32	1 " " 111	
2 " " 12A	6 " " 35	6 " " 111c	
1 " " 15	84 " " 37		
3 " " 15A	2 " " 37A		
1 " " 16	6 " " 38		
2 " " 17	2 " " 38A		
2 " " 18A	3 " " 38A		
1 " " 19			
1 " " 19s			

These Models can be built with MECCANO Outfit No. 3 (or No. 2 and No. 2A) and No. 3X

Model No. 3.51 Steam Wagon




The steering column 1 is journalled in bearings consisting of a $5\frac{1}{2}$ " strip 2 and two $2\frac{1}{2}$ " strips 3 (Fig. 3.51A), and carries the bush wheel 4, which is secured rigidly to it. A $\frac{3}{4}$ " flanged wheel 5 supports the weight of the steering column 1. The stub axles of the front road wheels consist of $\frac{3}{4}$ " bolts, on which the road wheels are spaced by washers 14. These bolts serve in the place of set-screws to secure two collars to the 1" rods 8. A pair of cranks 9, 9a secured to the rods 8 are joined by two $5\frac{1}{2}$ " strips 15 overlapped eight holes. A $1\frac{1}{2}$ " strip 10, bolted to the face of the bush wheel 4, is connected pivotally by a composite $4\frac{1}{2}$ " strip 11 (a $3\frac{1}{2}$ " strip and a $2\frac{1}{2}$ " strip overlapped three holes) to the end of the crank 9. When the steering wheel is turned, the strip 11 moves the cranks 9, 9a, thereby deflecting the front road wheels.

The electric motor 6 is controlled by raising and depressing the handle 7. Duplicate drive transmission belts 12 and 13 are used in order to secure a more dependable drive to the rear axle.

Parts required:

14 of No. 2	4 of No. 19B	2 of No. 54
6 " " 3	3 " " 20B	4 " " 59
6 " " 5	1 " " 21	2 " " 62
2 " " 6A	4 " " 22	1 " " 63
6 " " 8	1 " " 23	2 " " 99
8 " " 10	1 " " 24	2 " " 100
3 " " 11	1 " " 26	2 " " 111
10 " " 12	79 " " 37	1 " " 115
2 " " 12A	10 " " 38	4 " " 125
1 " " 15	2 " " 48B	1 " " 147B
3 " " 16	2 " " 52	1 " " 162
2 " " 18A	3 " " 53	1 " " 163


Electric Motor
(included in No. 3x Outfit only)




HOW TO CONTINUE

This completes our examples of models that may be made with Outfits No. 3 and No. 3x. The next models are a little more advanced, requiring a number of extra parts to construct them. The necessary parts are all contained in a No. 3A Accessory Outfit, the price of which will be found in the List at the end of this Manual.


A Selection of Choice Meccano Models




Loom




Tank Locomotive



*Travelling
Gantry Crane*




Hammerhead Crane




*Planing
Machine*

The models illustrated on this page show the wonderful possibilities of Meccano. They comprise a selection from a range of super models that have been specially built for the delight of Meccano boys.


A descriptive leaflet, giving full particulars of all the models in the series and the prices of the special Instruction Leaflets that are published in connection with them, may be obtained from your dealer or direct from Meccano Ltd., Binns Road, Liverpool.




*Vertical
Log Saw*




Hydraulic Crane




*High-Speed
Ship-Cooler*



Pontoon Crane



Aeroscope



Grandfather's Clock

A Selection of Meccano Standard Mechanisms

Here are a few simple and interesting movements showing how easily real mechanisms can be reproduced with Meccano. They are a selection from the Meccano Standard Mechanisms Manual, which is fully described on page 2 of this Manual.




FIG. A




FIG. C




FIG. B




FIG. D



FIG. E




FIG. F




FIG. G




FIG. H




FIG. J

Gears

The Meccano system includes a wide range of Gear Wheels, Bevel Gears, Pinion Wheels, Contrate Wheels and Worm Wheels in various sizes. All manner of interesting movements may be obtained by the use of these gears.

Fig. A shows how a drive may be transmitted from a vertical to a horizontal shaft or vice versa. Fig. B shows a Worm engaged with a Gear Wheel, giving a very great reduction in shaft speed. Fig. C illustrates another right angle drive, obtained by using Meccano Bevel Gears.

Belt and Chain Drives

In Figs. D, E, F and G we show examples of belt and chain drives. The movements illustrated require no explanation excepting, perhaps, Fig. G, which shows a simple method for slipping the belt from the fast to the loose pulleys or vice versa.

Cords usually take the place of belts in Meccano models but miniature belting may be made from strips of canvas, indiarubber, etc., in which case Flanged Wheels should be used instead of grooved Pulleys.

Steering Gears

The various types of steering mechanism commonly in use on vehicles of all descriptions may readily be reproduced with Meccano.

Fig. H. In this case the road wheels are moved about their central pivot by means of a crank, which is secured to the steering shaft, and a connecting strip.

Fig. J. The road wheels in this example are secured to a central rod, which forms a pivot, and is rotated from the hand-wheel by means of a worm gear.

A Selection of Meccano Standard Mechanisms

(continued)




FIG. K




FIG. L

Dog Clutch

The Meccano Dog Clutch (Fig. K) may be used in most models where a simple clutch is required. It is also useful in the construction of drive-changing and reversing mechanisms, etc. Various kinds of clutches, in addition to the Dog Clutch, may be constructed from the standard Meccano parts.

Intermittent Rotary Motion

Fig. L shows one device by means of which intermittent rotary motion may be obtained. Such an arrangement is useful in revolution counters, measuring machines, etc. In addition to mechanisms that give true intermittent motion, different types of cams, converting a regular rotary motion into a constant or intermittent reciprocating motion, are described in the S.M. Manual.




FIG. M

Grab

A typical example of the many kinds of grab that can be constructed from Meccano is shown in Fig. M. If the grab is fitted to a model crane or ship-coaler, all the movements can be controlled from an operating box built into the frame of the model. The outer sides of the jaws may be filled in with cardboard and the grab can then be used to pick up loads of sand, grain, marbles, etc.

Pawl and Ratchet Wheel

Fig. N illustrates the standard Meccano Pawl and Ratchet Wheel gear, which allows the shaft carrying the Ratchet Wheel to rotate in one direction only. The advantages of such an arrangement are obvious, especially when attached to model Cranes, hoisting-tackle, etc., where the Pawl and Ratchet gear prevents falling-back of the load as it is hoisted.




FIG. N




FIG. O

Strap and Lever Brake

This device (Fig. O) will be found very useful as a quick emergency hand-brake. Although it is the most simple of such devices, it is also one of the most valuable.




FIG. P

Strap and Screw Brake

The type of brake shown in Fig. P is used to apply a constant retarding effect to a rotating shaft. It can thus be utilized in a crane to prevent the load from falling back when the winding spindle is released. One advantage of the brake is that the speed of the shaft to which it is applied can be infinitely varied, so that in some models it will take the place of a gear-changing mechanism.

CONTENTS OF OUTFITS

No.	DESCRIPTION OF PART.	00	00A	0	0A	1	1A	2	2A	3	3A	4	4A	5	5A	6	6A	7
1	Perforated Strips, 12 1/2"					4	6	1		10	2	12	4	16	32	48	2	50
1A	" " 7 1/2"					4	6	1		10	2	12	4	16	32	48	2	10
2	" " 5 1/2"					4	6	1		10	2	12	4	16	32	48	2	12
2A	" " 4 1/2"					4	6	1		10	2	12	4	16	32	48	2	25
3	" " 3 1/2"					4	6	1		10	2	12	4	16	32	48	2	8
4	" " 2 1/2"					4	6	1		10	2	12	4	16	32	48	2	24
5	" " 2 1/4"					4	6	1		10	2	12	4	16	32	48	2	84
6	" " 1 1/2"					4	6	1		10	2	12	4	16	32	48	2	120
6A	" " 1 1/4"					4	6	1		10	2	12	4	16	32	48	2	14
7	Angle Girders, 24 1/2"					4	6	1		10	2	12	4	16	32	48	2	12
7A	" " 18 1/2"					4	6	1		10	2	12	4	16	32	48	2	6
8	" " 12 1/2"					4	6	1		10	2	12	4	16	32	48	2	26
8A	" " 9 1/2"					4	6	1		10	2	12	4	16	32	48	2	6
8B	" " 7 1/2"					4	6	1		10	2	12	4	16	32	48	2	12
9	" " 5 1/2"					4	6	1		10	2	12	4	16	32	48	2	4
9A	" " 4 1/2"					4	6	1		10	2	12	4	16	32	48	2	18
9B	" " 3 1/2"					4	6	1		10	2	12	4	16	32	48	2	6
9C	" " 3 1/4"					4	6	1		10	2	12	4	16	32	48	2	8
9D	" " 2 1/2"					4	6	1		10	2	12	4	16	32	48	2	7
9E	" " 2 1/4"					4	6	1		10	2	12	4	16	32	48	2	3
9F	" " 1 1/2"					4	6	1		10	2	12	4	16	32	48	2	3
10	Flat Brackets...					4	6	1		10	2	12	4	16	32	48	2	2
11	Double Brackets...					4	6	1		10	2	12	4	16	32	48	2	4
12	Angle Brackets, 1 1/2 x 1 1/2"					4	6	1		10	2	12	4	16	32	48	2	8
12A	" " 1 1/4 x 1 1/4"					4	6	1		10	2	12	4	16	32	48	2	4
12B	" " 1 1/8 x 1 1/8"					4	6	1		10	2	12	4	16	32	48	2	4
13	Axle Rods, 1 1/2"					4	6	1		10	2	12	4	16	32	48	2	4
13A	" " 1 1/4"					4	6	1		10	2	12	4	16	32	48	2	4
14	" " 6 1/2"					4	6	1		10	2	12	4	16	32	48	2	8
15	" " 5 1/2"					4	6	1		10	2	12	4	16	32	48	2	12
15A	" " 4 1/2"					4	6	1		10	2	12	4	16	32	48	2	4
16	" " 4 1/4"					4	6	1		10	2	12	4	16	32	48	2	4
16A	" " 2 1/2"					4	6	1		10	2	12	4	16	32	48	2	4
16B	" " 3 1/2"					4	6	1		10	2	12	4	16	32	48	2	4
17	" " 2 1/4"					4	6	1		10	2	12	4	16	32	48	2	4
18	" " 1 1/2"					4	6	1		10	2	12	4	16	32	48	2	4
18A	" " 1 1/4"					4	6	1		10	2	12	4	16	32	48	2	4
19	Crank Handles (5" shaft)					4	6	1		10	2	12	4	16	32	48	2	4
19S	" " (3 1/2" shaft)					4	6	1		10	2	12	4	16	32	48	2	4
19A	Wheels, 3"					4	6	1		10	2	12	4	16	32	48	2	4
19B	Pulley Wheels, 3"					4	6	1		10	2	12	4	16	32	48	2	4
20	Flanged Wheels, 1 1/2"					4	6	1		10	2	12	4	16	32	48	2	4
20A	Pulley Wheels, 2"					4	6	1		10	2	12	4	16	32	48	2	4
20B	Flanged Wheels, 3"					4	6	1		10	2	12	4	16	32	48	2	4
21	Pulley Wheels, 1 1/2"					4	6	1		10	2	12	4	16	32	48	2	4
22	" " 1" (fast)					4	6	1		10	2	12	4	16	32	48	2	4
22A	" " 1" (loose)					4	6	1		10	2	12	4	16	32	48	2	4
23	" " 1 1/4" (loose)					4	6	1		10	2	12	4	16	32	48	2	4
23A	" " 1 1/2" (loose)					4	6	1		10	2	12	4	16	32	48	2	4
24	Bush Wheels...					4	6	1		10	2	12	4	16	32	48	2	4
25	Pinion Wheels...					4	6	1		10	2	12	4	16	32	48	2	4
26	" " Wheels, 50-teeth					4	6	1		10	2	12	4	16	32	48	2	4
27	" " 57-teeth					4	6	1		10	2	12	4	16	32	48	2	4
27A	" " 133-teeth (3 1/2" diam.)					4	6	1		10	2	12	4	16	32	48	2	4
27B	Contrate Wheels, 1 1/2"					4	6	1		10	2	12	4	16	32	48	2	4
28	" " 1 1/4"					4	6	1		10	2	12	4	16	32	48	2	4
29	Bevel Gears, 1 1/2"					4	6	1		10	2	12	4	16	32	48	2	4
30	" " 1 1/4"					4	6	1		10	2	12	4	16	32	48	2	4
30A	Gear Wheels, 1", 38-teeth					4	6	1		10	2	12	4	16	32	48	2	4
30C	" " 1"					4	6	1		10	2	12	4	16	32	48	2	4
31	Worm Wheels					4	6	1		10	2	12	4	16	32	48	2	4
32	" " 1"					4	6	1		10	2	12	4	16	32	48	2	4
34	Spanners					4	6	1		10	2	12	4	16	32	48	2	4
35	Screw Drivers					4	6	1		10	2	12	4	16	32	48	2	4
36	" " (special)					4	6	1		10	2	12	4	16	32	48	2	4
37	Nuts and Bolts, 7/32"					4	6	1		10	2	12	4	16	32	48	2	4
38	Nuts					4	6	1		10	2	12	4	16	32	48	2	4
38A	Washers					4	6	1		10	2	12	4	16	32	48	2	4
40	Hanks of Cord					4	6	1		10	2	12	4	16	32	48	2	4
41	Propeller Blades					4	6	1		10	2	12	4	16	32	48	2	4
43	Springs					4	6	1		10	2	12	4	16	32	48	2	4
44	Cranked Bent Strips					4	6	1		10	2	12	4	16	32	48	2	4
45	Double Bent Strips					4	6	1		10	2	12	4	16	32	48	2	4
46	Double Angle Strips, 2 1/2 x 1 1/2"					4	6	1		10	2	12	4	16	32	48	2	4
47	" " 3 x 1 1/2"					4	6	1		10	2	12	4	16	32	48	2	4
47A	" " 3 1/2 x 1 1/2"					4	6	1		10	2	12	4	16	32	48	2	4
48	" " 2 1/2 x 1 1/2"					4	6	1		10	2	12	4	16	32	48	2	4
48A	" " 2 1/4 x 1 1/2"					4	6	1		10	2	12	4	16	32	48	2	4
48B	" " 3 1/4 x 1 1/2"					4	6	1		10	2	12	4	16	32	48	2	4
48C	" " 4 1/4 x 1 1/2"					4	6	1		10	2	12	4	16	32	48	2	4
48D	" " 5 1/4 x 1 1/2"					4	6	1		10	2	12	4	16	32	48	2	4
50	Eye Piece, with boss					4	6	1		10	2	12	4	16	32	48	2	4
52	Perforated Flanged Plates, 5 1/2 x 2 1/2"					4	6	1		10	2	12	4	16	32	48	2	4
52A	Flat Plates, 5 1/2 x 3 1/2"					4	6	1		10	2	12	4	16	32	48	2	4
53	Perforated Flanged Plates, 3 1/2 x 2 1/2"					4	6	1		10	2	12	4	16	32	48	2	4
53A	Flat Plates, 4 1/2 x 2 1/2"					4	6	1		10	2	12	4	16	32	48	2	4
54	Perforated Flanged Sector Plates					4	6	1		10	2	12	4	16	32	48	2	4
55A	Perforated Strip, slotted, 2"					4	6	1		10	2	12	4	16	32	48	2	4
55A	00 Instruction Folders					4	6	1		10	2	12	4	16	32	48	2	4
56B	" " Manuals					4	6	1		10	2	12	4	16	32	48	2	4
56A	00-3 " "					4	6	1		10	2	12	4	16	32	48	2	4
56	4-7 " "					4	6	1		10	2	12	4	16	32	48	2	4
56C	Mecano Standard Mechanisms Manuals					4	6	1		10	2	12	4	16	32	48	2	4
57	Hooks					4	6	1		10	2	12	4	16	32	48	2	4
57A	" " (Scientific)					4	6	1		10	2	12	4	16	32	48	2	4
57B	" " (Loaded)					4	6	1		10	2	12	4	16	32	48	2	4
58	Spring Cord, 40" length					4	6	1		10	2	12	4	16	32	48	2	4

No.	DESCRIPTION OF PART.	00	00A	0	0A	1	1A	2	2A	3	3A	4	4A	5	5A	6	6A	7
59	Collars with Set Screws	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
61	Windmill Sails	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
62	Cranks	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
62A	Threaded Cranks	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
63	Couplings	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
63B	Ship Couplings	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
64	Threaded Bosses	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
65	Centre Forks	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
66	Weights, 50 Gramme	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
67	" 25	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
70	Flat Plates, $5\frac{1}{2} \times 2\frac{1}{2}$	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
72	" $2\frac{1}{2} \times 2\frac{1}{2}$	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
76	Triangular Plates, $2\frac{1}{2}$	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
77	" 1	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
78	Screwed Rods, $1\frac{1}{2}$	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
80	" 5	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
80A	" 3	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
80B	" 4	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
81	" 2	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
82	" 1	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
89	Curved Strips, $5\frac{1}{2}$	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
90	" $2\frac{1}{2}$ large radius	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
90A	" 2 1/2 small	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
94	Sprocket Chain	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
95	Sprocket Wheels, $1\frac{1}{2}$	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
95A	" 3	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
95B	" 4	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
96	" 1	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
96A	" 3	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
97	Braced Girders, $3\frac{1}{2}$	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
98	" 12	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
99	" 19	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
99A	" 5	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
100	Heads for Loons	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
101	Single Bent Strips	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
102	Flat Girders, $5\frac{1}{2}$	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
103	" 12	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
103A	" 3	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
103B	" 3	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
103C	" 3	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
103D	" 3	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
103E	" 3	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
103F	" 3	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
103G	" 3	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
103H	" 3	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
103I	" 3	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
104	Shuttles for Loons	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
105	Reed Hooks	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
106	Wood Rollers	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
106A	Sand Rollers	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
107	Designing Tables	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
108	Architraves	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
109	Face Plates, $2\frac{1}{2}$	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
110	Rack Strips, $3\frac{1}{2}$	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
111	Bolts, $\frac{1}{2}$	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
111A	" 1	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
111B	" 1	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
111C	Grider Frames	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
114	Hinges	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
114A	Threaded Pins	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
116	Fork Pieces	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
116A	Small Fork Pieces	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
118	Hub Discs ($5\frac{1}{2}$ diam.)	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
119	Channel Segments (8 to circle)	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
120A	Spring Butters	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
120B	Compression Springs	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
121	Train Couplings	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
122	Miniature Loaded Sacks	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
123	Cone Pulleys	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
124	Reversed Angle Brackets, $1\frac{1}{2}$	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
125	" 1	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
126	Trunnions	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
126A	Flat Trunnions	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
128	Boss Bell Cranks	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
129	Rack Segments ($3\frac{1}{2}$ diam.)	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
130	Triple Throw Eccentrics	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
131	Dredger Buckets	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
132	Flywheels, $2\frac{1}{2}$	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
133	Cornet Brackets	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
134	Crank Shafts, $1\frac{1}{2}$ stroke	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
135	Theodolite Protractors	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
136	Handrail Supports	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
137	Wheel Flanges	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
138A	Ship's Funnel, Gunard Type	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
140	Universal Couplings	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
141	Wire Lines	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
142	Rubber Rings, $3\frac{1}{2}$ diam.	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
142b	Dunlop Tyres, $3\frac{1}{2}$ internal diam.	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
143	Circular Girders ($5\frac{1}{2}$ diam.)	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
144	Dog Clutches	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
145	Circular Strips ($7\frac{1}{2}$ diam. overall)	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
147A	Pawls	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
147B	Pivot Bolt with two nuts	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
148	Ratchet Wheels	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
149	Electric Collecting Shoes	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
155	Rubber Rings, $\frac{1$																	

No.	DESCRIPTION OF PART.	00	00A	0	0A	1	1A	2	2A	3	3A	4	4A	5	5A	6	6A	7
163	Sleeve Pieces...
164	Chimney Adaptors...
165	Swivel Bearings...
166	End Bearings...
169	Digger Buckets...
301	Bobbins
302	Bushes, Insulating
303	Washers, "
304	6 B.A. Screws
305	6 B.A. Nuts
306	Terminals
307	Contact Screw
308	Pole Pieces
309	Coil Checks
310	Lamp Holders
311	Lamps
312	27 Gauge B.I. Wire, 30" coils
313	26 " S.C.C. Wire, reel 50 yds.
314	23 " S.C.C. Wire, reel 25 yds.
315	Bare Copper Wire, 4 yds. coil
	Electric Manual of Instructions
	Clockwork Motors...
	Electric Motor No. 1 (4-volt)
	Accumulators (8 amp.)...
	Instruction Leaflets:																	
	No. 9—Bagatelle Table
	7—Platform Scales
	10—Log Saw...
	11—Horizontal Steam Engine
	12—Stone-sawing Machine
	1—Motor Chassis
	5—Dredger
	17—Planing Machine
	18—Revolving Crane
	19—Steam Shovel
	13—Meccanograph
	6—Stiff Log Derrick
	20—Aeroscope
	21—Transporter Bridge
	22—Tractor
	23—Vertical Log Saw
	14—Grandfather's Clock
	16—L—Trotting Gaitry Crane
	24—Trotting Gaitry Crane
	25—Hydraulic Crane
	2—High-speed Ship-Cocher
	26—Twin-clutch Harmono-graph
	3—Motor Cycle and Sidecar

STORAGE BOXES FOR MECCANO PARTS

The boxes illustrated and described below are specially designed for the purpose of storing Meccano parts. Almost every Meccano boy purchases additional parts from time to time, but there is sometimes difficulty in finding suitable accommodation for them. The Meccano Storage Boxes enable extra parts to be stored neatly and methodically so that they are always easily accessible.



No. 1 Storage Box

Stained and varnished in rich oak finish, and fitted with partitions, as shown in the illustration. The lid is hinged and is secured by means of lock and key.


Dimensions: Length 45½ ins. Width 8½ ins. Depth 2½ ins.

No. 1

No. 2 Storage Box

Finished as No. 1 Box and provided with lock and key. The tray with which it is fitted enables a much larger quantity of parts to be accommodated.

Dimensions: Length 14½ ins. Width 11 ins. Depth 3½ ins.



No. 3



No. 2

No. 3 Storage Box

A perfect receptacle for Meccano parts, finished similarly to the No. 1 and No. 2 boxes and provided with lock and key. In addition to accommodation in the bottom section of the box there are two partitioned trays which fit neatly in position one above the other.


Dimensions: Length 20 ins. Width 14 ins. Depth 5½ ins.

The prices of the Meccano Storage Boxes are indicated on the price list page at the end of this Manual.

MECCANO MOTORS

Electric Motor No. 1

(4-Volt)



The 4-volt Motor is specially designed to build into Meccano models. It may be run from a 4-volt Accumulator, or, by employing a suitable transformer, direct from the main. It is fitted with reversing motion, provided with stopping and starting controls, and the gearing is interchangeable.

4-Volt Accumulators

These new and excellent types of Accumulators have been adapted to drive the Electric Motor No. 1. They have been subjected to the severest tests and have proved themselves to be the most suitable accumulators for use with any type of electric motor. They are non-spillable, have remarkable recuperative powers, and will continue to supply current when nominally exhausted.

Transformer

By means of this transformer the Meccano Electric Motor No. 1 (4 volt) may be driven direct from the house supply (alternating current only). It is available for all standard supply voltages, from 100 to 250 inclusive, at all standard frequencies. The supply voltage and frequency must be specified when ordering.

Resistance Controller

By employing this variable resistance the speed of the Meccano Electric Motor No. 1 (4 volt) may be regulated as desired. The controller is connected in series with the motor and accumulator, or with the motor and transformer if a transformer is used as the source of power. It will not regulate the speed of a high-voltage motor connected to the main.

Electric Motor No. 2

(100-250 Volt AC or DC)




This reversible Electric Motor may be employed for any purpose for which a small motor is suitable, but it is specially adapted for driving Meccano models. The side plates are perforated with standard equidistant holes, thus allowing the motor to be built into any Meccano model. The motor is specially designed for connection with the electric-light main. It is suitable for 100-120 volts or 200-250 volts (alternating or direct), and is supplied with a 6 ft. length of flex, an insulated plug for connection with the motor terminals, and an adapter for connection with an ordinary lamp socket.

A suitable resistance is required when the motor is run with a 200-250-volt current, and this is supplied by connecting a 60-watt lamp in series with the motor. A board on which are mounted a suitable lamp-holder (lamp not included) and a switch is provided separately.

Clockwork Motor

The Meccano Clockwork Motor is specially made for the purpose of driving Meccano models. It is a fine piece of mechanism—simple, powerful, and reliable. The starting, stopping and reversing levers enable the operator to control the various movements of a model in exactly the same manner as an engineer does in actual practice.



MECCANO ACCESSORY OUTFITS

Meccano Accessory Outfits

Our illustration shows one of the Meccano Accessory Outfits. As has already been explained, these Outfits connect the main Outfits from No. 00 to No. 7, making it possible for a boy who commences with one of the earlier Outfits to build up his equipment by easy stages, until he is the possessor of parts that cover the entire system.

Special Inventor's Outfit

This Outfit is intended for boys who already have Meccano, and who wish to satisfy their inventive inclinations by building models from their own designs. The parts contained include four large Pulley Wheels with Dunlop Tyres, Ball Race, Ship's Funnel, Pulley Blocks, Channel Bearing, Crane Grab and many others.

For prices of above see price list at end of Manual.



HORNBY TRAINS


Hornby Trains are manufactured by Meccano Limited and they are made from the finest materials obtainable. Each train is a beautiful piece of workmanship with perfect mechanism. All Hornby Locos are carefully tested before leaving the factory and their efficiency is guaranteed.

No. M 1 Passenger Set

This set contains Loco, Tender, two Pullman Coaches and set of Rails. One of the latter is a brake rail by means of which the train may be braked from the track. Richly coloured and well finished; fitted with brake mechanism; non-reversing. Gauge 0.

No. M 2 Passenger Set

Similar in every way to the above excepting that it has three Pullman Coaches instead of two, and additional rails.




No. M1 PASSENGER SET

No. 1 Tank Goods Set

This set contains a No. 1 Hornby Tank Loco, Hornby Wagon, Petrol Tank Wagon, Brake Van and set of Rails to form either a circle 2 ft. in diameter or an oval 2 ft. in width by 2 ft. 10 in. in length. One of the rails is a brake rail by means of which the train may be braked from the track.


Gauge 0, in colours to represent the L.M.S.R., L.N.E.R., G.W.R. or S.R. Companies' rolling stock. The Loco is fitted with reversing gear and brake mechanism.



No. 1 TANK GOODS SET

No. 2 Pullman Set

This set includes Loco and Tender of a larger type, measuring 17 in. in length. The Coaches are beautiful both in colour and finish. Each set includes Loco, Tender, and two Pullman Coaches, with set of Rails making a 4 ft. diameter circle. The rails include one brake rail by means of which the train may be both braked and reversed from the track. In colours to represent the L.M.S.R., L.N.E.R., G.W.R. or S.R. Companies' rolling stock. The Loco is fitted with reversing gear and brake mechanism. Gauge 0.



No. 2 PULLMAN SET


No. 3 Train Sets

These Train Sets are the latest additions to the range of Hornby Trains. They are distinctive in design, beautifully enamelled in correct colours and are guaranteed to give the utmost satisfaction.

Each locomotive carries the name of a famous British locomotive on the front wheel guard at each side. A special feature of the Pullman Coaches is the corridor connection, which gives the

Train a most realistic appearance. All the doors of the coaches open.

The Trains in this series are "Cornish Riviera" (G.W.R.), "Flying Scotsman" (L.N.E.R.), "Royal Scot" (L.M.S.R.), and "Dover Pullman" (S.R.). In each case the Train Set is available with either Clockwork or 4-Volt Electric Motor. Gauge 0.



No. 3C L.N.E.R. "FLYING SCOTSMAN"

For prices of the above see price list at end of Manual.

ROLLING STOCK AND ACCESSORIES



SIGNAL CABIN No. 2

Dimensions: Height 6½-in., Width 3½-in., Length 6½-in. Finished in colours and lettered "Windsor." Roof and back open to allow a signal lever frame to be fitted inside cabin, if desired, and operated ... Price 10/-



LAMP STANDARD No. 2 (DOUBLE)
Four-volt bulbs may be fitted into the globes.
Price 6/-



RAILWAY STATION No. 2. Excellent model, beautifully designed and finished. Constructed in three sections which are detachable. Dimensions: Length 2-ft. 9-in., breadth 6-in., height 7-in. ... Price 17/6

THE Hornby system consists of a complete range of Rolling Stock, Train Accessories, and Rails, Points and Crossings, with which the most elaborate model railway may be constructed. Every component in the Hornby Series is well designed and carefully modelled on its prototype in real life.




JUNCTION SIGNAL
Signal arms operated by levers at base. Very realistic model standing 14-in. in height.
Price 8/6



TUNNEL
Realistic and finished in colours. Price 12/-



TURN-TABLE No. 1 Price 3/9
TURN-TABLE No. 2
(illustrated) Price 6/6



LEVEL CROSSING No. 1
Price 5/6



***CEMENT WAGON**
Finished in grey and black ... Price 4/6



***HOPPER WAGON**
Mechanically unloaded. Finished in grey and black ... Price 5/6




***MILK TRAFFIC VAN**
Fitted with sliding door, complete with milk cans. Price 5/-



***CRANE TRUCK**
Finished in grey and black ... Price 5/-



***SNOW PLOUGH**
With revolving plough driven from front axle.
Price 8/-




BUFFER STOPS No. 2 (HYDRAULIC)
Price 7/3



***TIMBER WAGON No. 2**
Beautifully enamelled in green. Suitable for 2-ft. radius rails only ... Price 5/-



LAMP STANDARD No. 1 (SINGLE)
A 4-volt bulb may be fitted into the globe. Price 4/6



ENGINE SHED No. 1
(illustrated) Price 19/-
ENGINE SHED No. 2
Price 30/-




DOUBLE ARM SIGNAL
No. 1 Price 5/9 pair
No. 2 .. 4/9 each



***TROLLEY WAGON**
Finished in grey and red. Suitable for 2-ft. radius rails only ... Price 8/-
**Lettered L.M.S., N.E., G.W. or S.R.*



BUFFER STOPS No. 1 (SPRING)
Price 1/6



LATTICE GIRDER BRIDGE
Constructional type. Strong and well proportioned.
Price 15/-



***BREAKDOWN VAN AND CRANE**
Beautifully coloured in grey and black, with opening doors. Suitable for 2-ft. radius rails only ... Price 9/-



***GAS CYLINDER WAGON**
Finished in red, lettered gold. Price 3/9



***LUMBER WAGON No. 1**
Fitted with bolsters and stanchions for log transport. Price 3/-



***BRAKE VAN**
Finished in grey, with opening doors. Price 5/-

MECCANO PRICE LIST

MECCANO OUTFITS

No. 00 Meccano Outfit	5/-
" 0 " " " " " " " " " " " "	7/-
" 1 " " " " " " " " " " " "	14/-
" 2 " " " " " " " " " " " "	23/-
" 3 " " " " " " " " " " " "	37/6
" 4 " " " " " " " " " " " "	67/6
" 5* " " (Carton) " " " " " " " "	92/6
" 5* " " Presentation Outfit " " " " " " " "	130/-
" 6* " " Outfit (Carton) " " " " " " " "	165/-
" 6* " " Presentation Outfit " " " " " " " "	210/-
" 7 " " " " " " " " " " " "	550/-

* Outfits Nos. 5, 5A and 6 are supplied in neat and well-made cardboard boxes (cartons) or in superior oak cabinets, with lock and key.

ACCESSORY OUTFITS

No. 00A Meccano Accessory Outfit	2/-
" 0A " " " " " " " " " " " "	7/6
" 1A " " " " " " " " " " " "	10/-
" 2A " " " " " " " " " " " "	15/6
" 3A " " " " " " " " " " " "	32/-
" 4A " " " " " " " " " " " "	25/-
" 5A* " " " (Carton) " " " " " " " "	72/6
" 5A* " " " (Wood) " " " " " " " "	110/-
" 6A " " " " " " " " " " " "	310/-
Special Inventor's Outfit " " " " " " " " " "	25/-

MECCANO MOTORS, Etc.

Meccano Clockwork Motor	10/6
" " Electric Motor No. 1 (4 Volt)	20/-
" " " " " 2 (100-120 or 200-250 Volt)	50/-
Transformer " " " " " " " " " " " "	40/-
Meccano Accumulator (4 Volt, 8 Amps.)	30/-
" " " " " 20 " " " " " " " "	42/-

Lamp Board (with lamp holder and switch)	7/6
Resistance Controller (for low voltage motors)	5/-
Rheostat (for high voltage motors)	22/6
No. 1 Meccano Storage Box	16/-
" 2 " " " " " " " " " " " "	31/6
" 3 " " " " " " " " " " " "	50/-

Hornby Train Price List

No. M1 Passenger Set	12/-
" M2 Passenger Set	15/-
" M3 Goods Set	22/6
Hornby No. 0 Goods Set	26/6
" " 0 Passenger Set	30/-
" " 1 Goods Set	30/-
* " " 1 " " fitted for Hornby Control	33/6
" " 1 Passenger Set	36/6
* " " 1 " " fitted for Hornby Control	40/-
" " 2 Goods Set	47/6
* " " 2 " " fitted for Hornby Control	52/6
" " 2 Pullman Set	72/6
* " " 2 " " fitted for Hornby Control	77/6
" " 1 Tank Goods Set	35/-
* " " 1 " " fitted for Hornby Control	38/6
" " 2 " " " " " " " " " " " "	55/-

*Hornby No. 2 Tank Goods Set fitted for Hornby Control	60/-
" " 2 Tank Passenger Set	55/-
* " " 2 " " fitted for Hornby Control	60/-
Metropolitan Train Set, H.V. (100-250 Volt, A. or D.C.)	160/-
" " " " L.V. (4-Volt Electric)	130/-
" " " " C (Clockwork)	80/-
Riviera "Blue Train" Set No. 3E (4-Volt Electric)	112/6
* " " " " 3C (Clockwork)	92/6
*Hornby No. 3C "Cornish Riviera" (Clockwork)	90/-
" " " 3E (Electric)	110/-
* " " 3C "Flying Scotsman" (Clockwork)	90/-
" " " 3E (Electric)	110/-
* " " 3C "Royal Scot" (Clockwork)	90/-
" " " 3E (Electric)	110/-
* " " 3C "Dover Pullman" (Clockwork)	90/-
" " " 3E (Electric)	110/-

*The Hornby Control System enables you to manipulate the Signals and Points, and to control the Trains entirely from the Signal Cabin. A folder is available entitled "The Hornby Control System" which gives full details. Ask your dealer for a copy.

INDEX TO MODELS

Description.	Model No.
A Sudden Appearance ...	1.119
Acrobat ...	2.34
Acrobat on See-Saw ...	1.128
Acrobats, The ...	1.129
Actuated See-Saw ...	3.16
Aerial Flight ...	1.62
" Railway ...	0.38
Aeroplane ...	0.30-1.2-1.13
" ...	1.99-2.43
Anchor ...	00.48-0.29
Anti-Aircraft Gun ...	1.42-2.44
Arc Lamp ...	1.86
Arch ...	0.7
Arm Chair ...	0.40
Automatic Dial Press ...	3.23
" Signal ...	1.153
" Swing Boat ...	3.33
Axe ...	00.65
" Fire ...	00.10
Baby Chair ...	2.28
Baggage Cart ...	00.32
" Truck ...	00.79
Balance, Letter ...	1.29-3.42
" Roman ...	00.68
Ballista ...	1.49
Band Brake ...	1.134
" Saw ...	00.92-1.95
Barrier, Level-Crossing ...	00.95
Barrow ...	00.18
" Coster's ...	1.15
Basket, Cutlery ...	00.89
Bath Chair ...	00.97-0.31-1.121
Battle-Axe ...	00.107
Battleship ...	0.61
Beam Engine ...	1.78
Bed ...	00.53
" Table ...	00.99-1.81
Bellows ...	1.16-1.80
" Forge ...	1.83
Bench ...	00.3-0.60
" Lathe ...	0.32
" Planing ...	00.78
Bicycle ...	1.132
Billiard Player ...	0.67
Birdcage and Stand ...	00.63
Blacksmith ...	00.102-1.113
Boat, Ice ...	3.19
" Motor ...	00.26
" Paddle ...	3.22
" Rowing ...	1.74
" Sailing ...	1.160
" Swing ...	3.30
" Steering Gear ...	1.143
Bogie Truck ...	00.76
Book End ...	00.43
Boring Machine ...	3.3
Bow and Arrow ...	1.97
" Girder ...	1.84
Boy on Swing ...	1.136
Brake, Band ...	1.134
Bridge ...	0.68
" High-Level ...	2.14
" Railway with Signals ...	2.48
Buffers ...	00.46
Buffing Spindle ...	00.87
Butter Churn ...	1.63
Cable Railway ...	1.64
Candle Shade ...	0.64

Description.	Model No.
Candle Stick ...	1.67
Candy Puller ...	2.22
Car, Tandem ...	1.3
Carpenter's Square ...	00.5
Carrier Tricycle ...	2.35
Cart ...	1.103
" Push ...	0.44
" Tipping ...	0.46
Ceiling Fan ...	00.35
Cement Marker ...	00.23
Centrifugal Governor ...	1.17
Chaff Cutter ...	0.50
Chair ...	1.118
" Revolving Office ...	0.65
Cheese Cutter ...	00.58
Chinese Windlass ...	1.79
Chute ...	00.28
Clothes Drying Frame ...	00.82
" Hanger ...	00.4
" Horse ...	00.49
Coal Sifter ...	2.7
Coaster ...	1.87-1.150-2.17
Coat Hanger ...	00.67-1.61
Coffee Grinder ...	3.6
Collapsible Table ...	00.20
Coster's Barrow ...	1.15
Cot ...	0.20
" on Wheels ...	1.117
" Swinging ...	3.29
Couch ...	0.23
Crane, Derricking ...	1.15
" Elevated ...	1.127
" Jib ...	1.107
" Jib ...	0.49-1.138
" Lorry ...	1.72
" Patent Luffing ...	1.155
" Railway Breakdown ...	3.50
" Wagon Swivel ...	3.40
" Revolving Hammerhead ...	1.41
" Rotating ...	1.158
" Swivelling ...	0.58-1.9-1.151
" Jib ...	1.92-1.93
" Travelling Jib ...	1.51-2.45-2.46
Crib ...	00.41
Crossbow ...	3.5
Crosshead Demonstration Model ...	1.140
Cum-Bak ...	1.98
Cutlery Basket ...	00.89
" Rest ...	00.62
Dancer, The Meccano ...	1.110
Dancers, Eccentric ...	1.142
Deck Chair ...	1.32
Demonstration Scales ...	3.11
Derrick ...	2.39
Derricking Crane ...	1.15
Desk ...	00.6
Devil Wall ...	00.91
Dial Press, Automatic ...	3.23
Dignity and Impudence ...	1.126
Dinner Wagon ...	1.1
Disappearing Meccanition ...	1.124
Dividers ...	00.2-00.39
Dog Kennel ...	0.45
Double Action Pump ...	1.108
" Cable Key ...	1.40
" Drop Hammer ...	2.38

Description.	Model No.
Drafting Machine ...	3.12
" Table ...	0.12
Drill ...	1.156
" Rock ...	0.17
Driller, Well ...	00.98
Drilling Machine ...	0.18-3.1
Drop Stamp ...	1.141
" the Nigger ...	3.48
Dump Car ...	0.33
Easel ...	2.20
Eccentric Dancers ...	1.142
Electric Elevator ...	1.144
" Tramcar ...	3.26
" Truck ...	2.6
Elevated Crane ...	1.127
" Jib Crane ...	1.107
Elevator ...	1.36-1.125-2.41
" Car ...	00.112
" Electric ...	1.144
Embossing Machine ...	2.47
Engine, Beam ...	1.78
" Horizontal ...	0.8-3.37-3.44
" Two-Cylinder ...	3.28
" Vertical ...	3.36
Fan, Ceiling ...	00.35
Farm Sight ...	00.14
Fencers, The ...	0.35
Field Roller ...	1.123
Fire Alarm ...	1.8-1.133
" Axe ...	00.10
" Engine, Manual ...	1.122
" Escape ...	2.42-3.4
Flat Truck ...	00.19
Flax Cleaner ...	3.46
Forge Bellows ...	1.83
Fork ...	00.69
French Railway Signal ...	00.84
Friction Grip Tongs ...	00.33-1.100
Furrow Roller ...	00.73
Gangway ...	1.101
Garden Hose Reel ...	00.94
" Seat ...	00.111
Gate ...	1.112
Gauge, Railway ...	3.32
" Track ...	00.54
Giant Foundry Ladle ...	1.106
Girder, Bow ...	1.84
Glider ...	00.40
Go Chair ...	0.56
Gondola ...	2.37
Gong ...	1.55-2.10
Governor, Centrifugal ...	1.17
" Inverted Centrifugal ...	1.66
Gramophone ...	1.69
Gravel Sifter ...	00.59
Grill ...	00.74
Grinder, Coffee ...	3.6
Gun, Anti-Aircraft ...	1.42-2.44
" Lewis ...	00.24
" Machine ...	0.57
" Old Siege ...	0.28
" Quick-Firing ...	1.11
Gymnast ...	1.53
" Revolving ...	1.162

Description.	Model No.
Gyroscope ...	1.131
Hack Saw, Power ...	0.25
Hammer, Double Drop ...	2.38
" Helve ...	1.22
" Mechanical ...	1.7-2.2
" Trip ...	00.90
Hammock ...	0.55
Hand Car ...	00.64
" Cart ...	00.9
Hand Loom ...	1.54
" Trolley ...	3.14
" Truck ...	00.105
Hatchet ...	1.30
Hat Rack ...	0.4
Hay Tedder ...	2.40
Helve Hammer ...	1.22
High-Level Bridge ...	2.14
Hoe ...	00.75
Hooke's Coupling ...	1.85
Horizontal Engine ...	0.8-3.37-3.44
Horse ...	00.70
" and Cart ...	1.154
" Clothes ...	00.49
" Prancing ...	0.59
" Rake ...	0.47
" Sleigh ...	3.10
" Toy ...	00.85
Horseman ...	1.21
Howitzer ...	1.146
Ice Boat ...	3.19
Inclined Plane ...	1.50
Invalid, The ...	1.105
" Chair ...	1.26
Inverted Centrifugal Governor ...	1.66
" Truss ...	1.60
Jennier, Lace ...	3.31
Jib Crane ...	0.49-1.138
Junction Signal ...	0.26
Kinetograph ...	3.49
King Meccano ...	1.24
Lace Jennier ...	3.31
Ladder ...	00.12
" on Wheels ...	00.96-1.46-2.25
" Step ...	00.55
Ladle, Giant Foundry ...	1.106
Lancer ...	1.70
Large Rake ...	1.111
Lathe ...	0.5-3.35
" Bench ...	0.32
" Treadle ...	2.8
Lawn Marker ...	3.45
" Mower ...	1.6-3.9
Lazy Tongs ...	1.73
Letter Balance ...	1.29-3.42
Level Crossing Barrier ...	00.95
Lever of the first Order ...	00.109
Lewis Gun ...	00.24
Loom, Hand ...	1.54
Lorry Crane ...	1.72
" Motor ...	1.89-1.159
" Steam ...	2.1
" Tank ...	3.43
Luggage Cart ...	1.33-1.135
" Truck ...	0.2-0.48
Machine for tracing a locus ...	1.68
" Gun ...	0.57
Mail Bag Hanger ...	00.56-00.86
Man and Boy ...	1.65

Description.	Model No.
Man climbing Pole ...	1.14
Manual Fire Engine ...	1.122
Marker, Cement ...	00.23
" Lawn ...	3.45
Mason's Trowel ...	00.30
Master and Student ...	1.148
Mat Frame ...	2.11
Meat Saw ...	00.8
Meccangaroo ...	3.18
Meccano Dancer, The ...	1.110
" Man ...	00.106
Meccanograph ...	1.45
Mechanical Hammer ...	1.7-2.2
" Saw ...	1.28
" Shovel ...	1.137
" Stamp ...	1.34
Motor Boat ...	00.26
" Car, Racing ...	1.12-1.152
" Cyclist and Pillion Rider ...	1.52
" Lorry ...	1.89-1.159
" Tractor ...	1.53
" Truck ...	2.29
" Van ...	2.19
" Wagon, Tipping ...	2.5
Mountain Transport ...	1.19
Mounted Cowboy ...	1.145
Mower ...	1.6-3.9
Music Stand ...	0.41
Newton's Disc ...	3.8
Notice Board ...	0.9
Oil Cake Chopper ...	3.39
Old Siege Gun ...	0.28
Ore Crusher ...	00.100
Overhead Crane ...	1.94
Paddle Boat ...	3.22
" Steamer ...	1.43
Pantograph ...	1.163
Parallel Bars ...	0.63
Pastry Designer ...	3.20
Patent Luffing Crane ...	1.155
Pen Rack ...	00.38-00.115
Piano Stool ...	00.47
Pile Driver ...	3.13
Piston Connection, Double ...	
Action ...	1.164
Pit Head Gear ...	3.25
Planing Bench ...	00.78
Plasterer's Hawk ...	00.27
Plough ...	00.16-0.6
Polishing Spindle ...	2.15
Portal ...	0.52
Porter's Trolley ...	00.103
Potato Chopper ...	00.25
Potter's Wheel ...	1.35
Power Hack Saw ...	0.25
Prancing Horse ...	0.59
Prehistoric Animal ...	0.66
Press, Automatic Dial ...	3.23
Print Hammer ...	00.108
Pulley Block ...	0.14
" Single Sheave ...	0.22-0.37
" Shafting ...	00.72-00.83
Pump ...	0.53
" Double Action ...	1.108
" Windmill ...	1.149

INDEX TO MODELS (continued)

Description.	Model No.
Punching Bag Stand ...	0.24
Machine ...	0.34-1.56
Push Cart ...	0.44
Quick-Firing Gun ...	1.11
Return Device ...	1.88
Racing Motor Car ...	1.12-1.152
Railway, Aerial ...	0.38
" Breakdown Crane ...	3.50
" Bridge with Signals ...	2.48
" Cable ...	1.64
" Gauge ...	3.32
" Signal, French ...	00.84
" Wagon Swivel Crane ...	3.40
Rake ...	00.50-00.52-1.59
" Horse ...	0.47
" Large ...	1.111
Rat Trap ...	1.120
Rattle ...	0.36-3.38
Refreshment Wagon ...	00.45
Revolving Gymnasts ...	1.162
Hammerhead Crane ...	1.41
" Office Chair ...	0.65
" See-Saw ...	1.23
" Tricyclist ...	1.114
" Truck ...	2.23
Rifle with Bayonet ...	00.15
Rock Drill ...	0.17
Roller, Field ...	1.123
" Furrow ...	00.73
" Steam Road ...	3.21
Roman Balance ...	00.68
Rotating Crane ...	1.158
Roulette Wheel ...	00.66
Roundabout ...	1.57-2.30-3.47
Roundabout See-Saw ...	2.36
Rowing Boat ...	1.74
Safety Catch for Winding Gear ...	1.147
Sailing Boat ...	1.160
Sand Yacht ...	1.82-2.13
Saw, Band ...	00.92-1.95
" Meat ...	00.8
" Mechanical ...	1.28
" Two-Hand ...	00.77
Sawing Horse ...	00.114
Machine ...	1.157
Scales ...	0.19-0.21-1.90-2.31-3.34
Demonstration ...	3.11
Scarifier ...	3.24
Scoter ...	0.43-1.47
Scrap Reel ...	00.51
Seat, Garden ...	00.111
" Umpire's ...	1.130
See-Saw ...	0.16-1.37
" Acrobat on ...	1.128
" Actuated ...	3.16
" Revolving ...	1.23
" Roundabout ...	2.36
Shade, Candle ...	0.64
Shearing Machine ...	0.42
Shepherd's Crook ...	1.109
Ship's Lamp ...	1.25
Shipyard Bogie ...	00.7
Shovel, Mechanical ...	1.137
" Steam ...	1.115
Sifter ...	2.24

Description.	Model No.
Sifter, Coal ...	2.7
" Gravel ...	00.59
Signal ...	1.44
" Automatic ...	1.153
" French Railway ...	00.84
" Junction ...	0.26
Single Sheave Pulley Block ...	0.22-0.37
Ski-Runner ...	00.88
Sled ...	00.17-00.93-0.27
Sleigh, Horse ...	3.10
Smoothing Iron ...	2.9
Spade ...	00.22
Spindle, Buffing ...	00.87
Spinning Buttons ...	1.91
Spinning Top ...	00.29-2.12
Stamp, Drop ...	1.141
" Mechanical ...	1.34
Stamping Machine ...	1.71
" Mill ...	2.21
Stand, Music ...	0.41
" Umbrella ...	00.61
" Watch ...	00.104
Steam Engine, Vertical ...	3.36
" Lorry ...	2.1
" Road Roller ...	3.21
" Shovel ...	1.115
" Wagon ...	3.51
Steamer, Paddle ...	1.43
Steering Gear, Boat ...	1.143
Step Ladder ...	00.55
Stick, Candle ...	1.67
Stool, Piano ...	00.47
Strip Bending Machine ...	3.2
Submarine ...	1.10
Sulkey ...	0.11
Swing ...	0.3-3.7
Swing Boat ...	3.30
" Automatic ...	3.33
Swinging Cot ...	3.29
Swivelling Crane ...	0.58-1.9-1.151
" Jib Crane (Electric) ...	1.92
" Jib Crane (Hand ...	
Operated) ...	1.93
Switch ...	00.31
Sword ...	[00.44
Table ...	00.1-00.80
Table, Bed ...	00.99-1.81
" Collapsible ...	00.20
" Drafting ...	0.12
Tandem Car ...	1.3
Tank Lorry ...	3.43
" Wagon ...	3.15
Tea Wagon ...	00.101-0.10
Telegraph Key ...	00.42
" Pole ...	00.36
Telpher Span ...	1.20
The Fencers ...	0.35
Ticca Gharry ...	1.27
Tight Rope Walker ...	1.48
Timber Drag ...	1.96-1.5
" Truck ...	00.71-00.81
" Wagon ...	00.57
Tin Opener ...	00.37
Tip Wagon ...	1.4
Tipping Cart ...	0.46

Description.	Model No.
Tipping Motor Wagon ...	2.5
Toast Rack ...	1.139
Toboggan ...	3.17
Top ...	1.104
Top, Spinning ...	00.29-2.12
Towel Horse ...	00.110-2.18
Tower Wagon ...	1.18-1.77-3.27
Toy Horse ...	00.85
Track Gauge ...	00.54
Tractor, Motor ...	1.53
Tramcar, Electric ...	3.26
Travelling Crane ...	1.51
" Jib Crane ...	2.45-2.46
Treadle Lathe ...	2.8
Tricycle ...	2.26
" Carrier ...	2.35
Tricyclist, Revolving ...	1.114
Trip Hammer ...	00.90
Trolley ...	00.21-00.60-0.1
" Hand ...	3.14
" Porter's ...	00.103
Trowel ...	00.13
Trowel, Mason's ...	00.30
Truck ...	1.116
" Baggage ...	00.79
" Bogie ...	00.76
" Electric ...	2.6
" Flat ...	00.19
" Hand ...	00.105
" Luggage ...	0.2-0.48
" Motor ...	2.29
" Revolving ...	2.23
" Timber ...	00.71-00.81
" with Sides ...	1.31
Try-your-strength Machine ...	1.38-2.4
Turnstile ...	00.113-2.3
Turntable ...	2.27
Tweezers ...	00.34
Two Cylinder Vertical Engine ...	3.28
Two-Hand Saw ...	00.77
Umbrella Stand ...	00.61
Umpire's Seat ...	1.130
Van, Motor ...	1.39-2.19
Velocipede ...	00.11
Vertical Engine, Two-cylinder ...	3.28
" Steam Engine ...	3.36
Viaduct ...	0.62
Violin and Bow ...	1.76
Wagon, Dinner ...	1.1
" Steam ...	3.51
" Tank ...	3.15
" Tea ...	00.101-1.10
" Timber ...	00.57
" Tip ...	1.4
" Tower ...	1.18-1.77-3.27
Walking Man ...	0.54
Watch Stand ...	00.104
Weather Vane ...	0.51-1.75
Well Driller ...	00.98
" Windlass ...	0.13
Windlass ...	1.102
" Chinese ...	1.79
" Well ...	0.13
Windmill ...	00.116-2.16
" Pump ...	1.149
Wire Rope Maker ...	3.41

**Patents and Designs
Great Britain**

20,535/13	139,125
22,962/13	177,430
3,869/14	250,378
4,183/14	253,236
4,564/15	648,958
671,484	



Meccano Ltd.,
5/6, Marshall Street,
London, W.1.

London Office & Warehouse :
Meccano Ltd.,
Walnut Tree Walk,
Kennington Road, London, S.E.11


Meccano Agencies :

Algiers,	Bogota,
Amsterdam,	Bombay,
Auckland,	Brussels,
Barcelona,	Buenos Aires,
Basle,	Cape Town.


MECCANO

THE TOY THAT MADE ENGINEERING FAMOUS

Millions of boys in every country throughout the world play with Meccano. These are the Meccano Factories and distributing centres.



Head Office & Factory :
BINNS ROAD, LIVERPOOL



Meccano Company Inc.,
Elizabeth, New Jersey, U.S.A.

**Patents and Designs
Great Britain**

671,485	682,934
671,534	683,011
671,790	686,112
680,416	698,054
682,208	718,404
682,209	718,731



Meccano (France) Ltd.,
78-80 Rue Rebeval,
Paris XIXeme.

Canadian Office and Warehouse :
Meccano Ltd.,
45, Colborne Street, Toronto.

Meccano Agencies :

Constantinople,	Malta,
Durban,	Monte Video,
Genoa,	Oslo,
Iquitos,	Stockholm,
Johannesburg,	Sydney.